



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21012471/Uvf3e2	
			Date: 07/01/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBH 356H	Veh. Inspected	SLK 2380P
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2103639/SYH	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	09/12/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA CIVIC 1.6 (A)	c.c	1597
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	MRHFC5650GT000819	Colour	BLUE
	Odometer	70997 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 R16	YOKOHAMA	6 mm
	L/H Front Tyre	215/55 R16	YOKOHAMA	6 mm
	R/H Rear Tyre	215/55 R16	YOKOHAMA	6 mm
	L/H Rear Tyre	215/55 R16	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND O/S UNDERCARRIAGE. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/12/2021	Inspection Date	09/12/2021
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	