

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : China Taiping Insurance
(Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Claim Details

Case Ref. No. : TP/122021/5112
Date : 09-12-2021
Accident Date : 12-07-2021

Vehicle Details

Make & Model : Mitsubishi LANCER 1.5 MIVEC
SPORTS AT ABS D
Chassis No : JMYSRCY2AAU000738
Registration No : SJX7060K

Third Party Vehicle Details

Registration No : SLC8380S

S/N	Description	Qty	Amount (S\$)
1	FRONT RH HEADLAMP <i>cut</i>	1.00	\$671.00
2	FRONT LH HEADLAMP <i>cut</i>	1.00	\$671.00
3	FRONT RH HEADLAMP LOWER BRACKET <i>X 11</i>	1.00	\$9.00 <i>X</i>
4	FRONT LH HEADLAMP LOWER BRACKET <i>X 11</i>	1.00	\$9.00 <i>X</i>
5	FRONT GRILLE <i>cut</i>	1.00	\$251.00
6	FRONT GRILLE EMBLEM <i>cut</i>	1.00	\$51.00
7	FRONT BUMPER <i>cut</i>	1.00	\$810.00
8	FRONT BUMPER CENTRE LOWER GRILLE <i>cut</i>	1.00	\$73.00
9	FRONT BUMPER RH SIDE RETAINER <i>X 11</i>	1.00	\$13.00 <i>X</i>
10	FRONT BUMPER LH SIDE RETAINER <i>X 11</i>	1.00	\$13.00 <i>X</i>
11	FRONT BUMPER CLIPS @ \$3.00 <i>cut</i>	10.00	\$30.00

Discount: -10%

\$2,601.00
(\$260.10)

- 12 FRONT NO. PLATE *cut*
13 TO REPAIR DAMAGES
14 TO SPRAY PAINTING

Subtotal w/o GST:

\$2,340.90

\$40.00

\$380.00

\$380.00

\$3,140.90

3703

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: Issued by Raymond Teo

This is a computer-generated document. No signature is required.

email: rasul@lkkauto.com

Resurvey after repair

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair (Supplementary)

Attention To : China Taiping Insurance
(Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Claim Details

Case Ref. No. : TP/122021/5112
Date : 09-12-2021
Accident Date : 12-07-2021

Vehicle Details

Make & Model : Mitsubishi LANCER 1.5 MIVEC
SPORTS AT ABS D
Chassis No : JMYSRCY2AAU000738
Registration No : SJX7060K

Third Party Vehicle Details

Registration No : SLC8380S

S/N	Description	Qty	Amount (\$\$)
1	FRONT BUMPER TOP BEAM <i>bt ✓</i>	1.00	\$69.00
			\$69.00
	Discount: -10%		(\$6.90)
			\$62.10 <i>62.10</i>
2	FRONT BUMPER RH LOWER SPOILER <i>com ✓</i>	1.00	\$150.00
3	FRONT BUMPER LH LOWER SPOILER <i>com ✓</i>	1.00	\$150.00
4	FRONT CAMERA <i>cut ✓</i>	1.00	\$200.00
			\$500 <i>500</i>
			\$200.00 <i>SN</i>
	Subtotal w/o GST:		\$562.10

230130

635.00

62.10

500.00

3498.40

20%

2798.72

45,821.800

Issued by Raymond Teo

This is a computer-generated document. No signature is required.