



Estimated Cost of Repair (Supplementary)

Attention To : **China Taiping Insurance
(Singapore) Pte Ltd**
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Claim Details

Case Ref. No. : TP/122021/5112
Date : 09-12-2021
Accident Date : 12-07-2021

Vehicle Details

Make & Model : Mitsubishi LANCER 1.5 MIVEC
SPORTS AT ABS D
Chassis No : JMYSRCY2AAU000738
Registration No : SJX7060K

Third Party Vehicle Details

Registration No : SLC8380S

S/N	Description	Qty	Amount (\$\$)
1	FRONT BUMPER TOP BEAM	1.00	\$69.00
			\$69.00
Discount: -10%			(\$6.90)
			\$62.10
2	FRONT BUMPER RH LOWER SPOILER	1.00	\$150.00
3	FRONT BUMPER LH LOWER SPOILER	1.00	\$150.00
4	FRONT CAMERA	1.00	\$200.00
Subtotal w/o GST:			\$562.10

Issued by Raymond Teo

This is a computer-generated document. No signature is required.