

ASS. REG. BY

Steve

12/21

CS/CT 12/01 2486/6v93

ASSIGNMENT

From:

Delo

Estimated Cost:

OR / INS / REPAIR / CO / RES / NVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

Insured: SMZ 7235C

Policy No. DMPCSNW00168822100

Claims No. SNM21D207138/C02/IRENE

Sum Insured:

Excuse:

(Client's Record)

Make of Velt

(Policy Condition)

1. The vehicle has commenced its repair at the time of inspection.



Net. or Market Value:

IDAC Accident Report

Consistent? Yes or No

RIA / PR. Scene

Consistent? Yes or No

Est. Repair:

days

Res. Yes or No

Sum Sum:

%

3 Vol. Yes or No

GA / REV / REP. / 24 HRS

Vehicle IN/OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

13/12/21

Steve confirmed \$1400 (Red 200.13%)

Time / Date, File, Report No.

☐ Prel. Report
☐ Final Report

Time / Date, File, Report No.

14/12/21-typist

Merimen

\$1400

Veh No:

SBS 3981A

Yr Regn: 12/6/15

Type: M. Car / M. Cycle / Bus / Van / Lorry / Truck / Trailer / Motor

Make: Volvo B9TL

C.B. 9364

Colour: Mar - Colour

A/O: Insured / Stg / NI / N

Sp. Reading: 412123

T/Ratio: Insured / Stg / NI / N

Eng/No:

YV384P936:PA171446

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Locked / Jammed / Locked / Burnt or

Brakes: Locked / Jammed / Locked / Burnt or

Mod: All / 3/4 / 1/2 / 1/4

Tyre Size:

215/70R17.5

RY: 11

BY: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIA / SUMI /

TOYO / YOKO or

Front

4

mm

Rear

4

mm

Wheel

4

mm

Wheel

4

mm

D.O.A.

21/11/21

Boxfresh

Survey held at

Det. of Damages: Frt / Rear / O/S

1/3

UIC / Roof / or

The V/O / Chassis frame / Body structure affected due to collision

Days of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation

Survey Fee

Survey Fee

Survey Fee

Survey Fee

Survey Fee

Survey Fee

Add Fee:

Site Insp

(\$)

Interview

(\$)

Tech. Invo

(\$)

Workshop

(\$)



Steve (LKK)
10/12/21, 12:00pm
8322 8813

sterecho@lkkauto.com

Wk PL
2 days
PIP, My AL My
Boxfresh Pte Ltd

7030 Ang Mo Kio Ave 5 #06-49
Northstar @AMK Singapore 569880
Tel : 64585441 Fax : 64553470

Vehicle No : SBS3981A

Accident date : 27 Nov 2021

Model No : Volvo

Registered owner : Go Ahead Singapore Pte Ltd

B9tl

Date of Estimate : 10/12/21

My Ref : BF-IC-1048

Total Charge

Parts Repair (2 days)

- a) Repair panel no 2 - 6
- b) Repair NSR Engine panel
- c) Sand, putty and make good surface of affected parts
- d) Spray paint of all affected parts.
- e) Replace stickers of all affected parts.

Repair cost for above items

Subtotal S\$ 1600 **1400**

Total Charge S\$ 1600

GST S\$ 112

Total Bill S\$ 1712

BOXFRESH PTE LTD

WORKSHOP: 154 GUL CIRCLE SINGAPORE 629611

OFFICE: 7030 ANG MO KIO AVE 5 #06-49 NORTHSTAR SINGAPORE 569880

T: +65 64585441 • F: +65 64553470 • E: business@boxfresh.com.sg • W: www.boxfresh.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: