

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	CHINA TAIPING IN		Ref:	CS/CTI21012486/Gvy3	
	3 ANSON ROAD #* SPRINGLEAF TOV		Date:	09/12/2021	
				Code:	СТІ
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMZ 7235C	Veh. Inspected		SBS 3981A
	Policy No.		Coverage (\$)		0.00
	Claim No.	SNM21D207138/C02/SMZ7235 C/TAYHP	Excess (\$)		0.00
	Assign From	TAN KIAN WEI BILLY	Assign Date		09/12/2021
2. Vehicle Particulars & Condition					
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	-	Steering		
	Brakes	Modification			
	General				
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.	Description of Damages				
5.	General Information				
	Accident Date	27/11/2021	Inspection Date	<del>)</del>	10/12/2021
	Survey held at	154 GUL CIRCLE			
	Repairer	BOXFRESH PTE LTD			
5a. Remarks					
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					