

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
 WORKSHOP : UBI ROAD 1
 CONTACT NO : 6366 2323
 FAX NO : 6841 1183
 REFERENCE : PA/OD/0979/2021/JT
 DATE : 2-Dec-21
 WIP : 56693

Veron

\$21326.40

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TAN CHIN HWEE
 ADDRESS : 9 DAIRY FARM HEIGHTS
 #12-23
 SINGAPORE 677670
 TELEPHONE : HP +65 90182089
 TYPE OF CLAIM : OWN DAMAGE CLAIM
 POLICY NO : 1900079342-01
 VEHICLE NO : SJZ 2868 U
 MODEL CODE : AUDI A5 SB 20 TFSI
 MODEL YEAR : 21/3/2019
 ENGINE NO : CVK 074438
 CHASSIS NO : WAUZZZF54KA01S101
 MILEAGE : -
 DATE IN : -
 ESTIMATED BY : JOHNNY BOO / ALLAN WU
 ACCIDENT DATE : 1-Dec-21
 PLACE OF ACCIDENT : BEDOK NORTH AVENUE 1

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408599


TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJZ 2868 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEALIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, S/N \$ HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	✓ ✓
2	TO REMOVE AND TRANSFER BOTH HEALIGHT'S CONTROL UNIT AND POWER MODULE. S/N \$	800.00	? 250
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACCUM AND REGAS. S/N \$	1,700.00	? 780 ✓
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR. S/N \$	560.00	✓ ✓
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. \$	5,600.00	1020 (With Lock Carries) 2250 (With Lock Corner) 2500
SUB TOTAL LABOUR CHARGES		\$ 9,140.00	




55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJZ 2868 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH UPPER A-PILLAR AND BOTH FRONT DOORS.	\$ 5,000.00	2200 ✓
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	192 ✓
TOTAL LABOUR CHARGES		: \$ 15,524.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJZ 2868 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>dent</i>	1	\$ 2,251.00	✓ 1800.80
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 407.00	X
3	FRONT BUMPER SECURING STRIP <i>Not new</i>	2	\$ 71.00	? X
4	FRONT BUMPER GRILLE - CENTER <i>cracked</i>	1	\$ 196.00	✓ 156.40
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i>	1	\$ 228.00	X
6	FRONT AIR GUIDE - LH / RH <i>new</i>	2	\$ 126.00	X
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>Not new</i>	2	\$ 948.00	? X
8	RADIATOR GRILLE <i>Smashed</i>	1	TBC	✓ 1040
9	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>cracked</i>	2	\$ 102.00	✓ 81.60
* 10	RADIATOR GRILLE COVER - UPPER <i>new</i>	1	\$ 189.00	? 150.80
11	FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>	1	\$ 124.00	✓ 99.20
12	FRONT BUMPER REINFORCEMENT BEAM <i>Dented</i>	1	\$ 845.00	? 675.60
13	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 72.00	X
14	FRONT BUMPER BRACKET - LH / RH <i>Not new</i>	2	\$ 428.00	? X
15	FRONT BUMPER TOP COVER <i>cracked</i>	1	\$ 127.00	? 101.60
16	CAUTION STICKER <i>new</i>	1	\$ 14.00	? 10.88
17	AIRCON STICKER	1	\$ 8.00	? 5.68
18	FRONT BUMPER LOCK CARRIER BRACKET <i>Dented</i>	1	\$ 137.00	? 109.60
19	FRONT BUMPER SUPPORT - LH / RH <i>Dented</i>	2	\$ 58.00	? 44.96
20	FRONT PARKING AID SENSOR - INNER <i>new</i>	2	TBC	X
SUB TOTAL SPARE PARTS		:	\$ 6,331.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1163

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJZ 2868 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER WIRING SET <i>Not m</i>	1	\$ 510.00	X
22	HORN - LH / RH <i>Not m</i>	2	\$ 252.00	+
23	HORN SUPPORT - LH / RH <i>Not m</i>	2	\$ 58.00	+
24	BONNET <i>Buckled</i>	1	\$ 3,312.00	2649.60
25	BONNET ATTACHMENT PARTS <i>Not m</i>	1	\$ 123.00	+
26	BONNET HINGE - LH / RH <i>Not m</i>	2	\$ 838.00	+
27	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>Not m</i>	3	\$ 84.00	65.68
28	BONNET SOUND ABSORBER <i>Not m</i>	1	\$ 343.00	+
29	BONNET STRIKER - LH / RH <i>Best</i>	2	\$ 100.00	79.84
30	BONNET LOCK <i>Not m</i>	2	\$ 427.00	X
31	BONNET MICRO-SWITCH <i>Not m</i>	1	\$ 13.00	X
32	BONNET BOWDEN CABLE INNER - CENTER <i>Not m</i>	1	\$ 58.00	X
33	BONNET BOWDEN CABLE OUTER - CENTER <i>Not m</i>	1	\$ 58.00	46
34	BONNET RELEASE LEVER <i>Not m</i>	1	\$ 14.00	X
35	BONNET LOCK CABLE <i>Not m</i>	1	\$ 74.00	X
36	PLENUM CHAMBER <i>Not m</i>	1	\$ 97.00	X
37	FRONT WHEEL HOUSING LINER - LH / RH <i>Not m</i>	2	\$ 550.00	X
38	FRONT WHEEL SPOILER - LH / RH <i>Not m</i>	2	\$ 146.00	X
39	FRONT SPOILER - LH / RH <i>Not m</i>	2	\$ 71.00	X
* 40	HEADLIGHT - LH / RH <i>Not m</i> <i>HT crushed</i>	2	\$ 15,804.00	X 6321.60
SUB TOTAL SPARE PARTS		:	\$ 22,932.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183


EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJZ 2868 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	LIFT CYLINDER - LH / RH <i>2 new</i>	2	\$ 396.00	+
42	LIFT CYLINDER BRACKET - LH / RH	2	\$ 30.00	+
43	LIFT CYLINDER CORRUGATED PIPE	1	\$ 86.00	+
44	RADIATOR COOLANT LOCK CARRIER <i>3 new</i>	1	\$ 1,016.00	? X
45	RADIATOR COOLANT SUPPORT - LH & RH	2	\$ 76.00	? X
46	A/C CONDENSER FLUID RESERVOIR <i>Revised</i>	1	\$ 622.00	? 497.60
47	REFRIGERANT LINE <i>2 new</i>	1	\$ 167.00	+
48	REFRIGERANT DISCHARGE HOSE	1	\$ 340.00	+
49	REFRIGERANT COOLANT PIPE	1	\$ 248.00	+
50	OUTSIDE TEMPERATURE SENSOR BRACKET <i>new</i>	1	\$ 19.00	? 14.56
51	AIR COOLER CHARGED <i>new</i>	1	\$ 587.00	? X
52	RADIATOR COOLANT COOLER <i>3 new</i>	1	\$ 904.00	? X
53	RADIATOR COOLANT	6	\$ 266.00	? X
54	RADIATOR AIR GUIDE INNER- LH / RH <i>new</i>	2	\$ 63.00	? X
55	RADIATOR AIR GUIDE OUTER- LH / RH <i>checked</i>	2	\$ 32.00	? 25.60
56	RADIATOR AIR GUIDE - UPPER / LOWER <i>2 new</i>	2	\$ 38.00	? X
57	RADIATOR INTAKE AIR DUCT LOWER - RH	1	\$ 22.00	? X
58	RADIATOR INTAKE AIR DUCT UPPER - RH	1	\$ 53.00	? X
59	RADIATOR INTAKE HOSE <i>new</i>	1	\$ 95.00	? X
60	FRONT WINDOW SLOT SEAL TRIM STRIP - LH / RH <i>new</i>	2	\$ 798.00	? X
SUB TOTAL SPARE PARTS		:	\$ 5,858.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJZ 2868 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
61	FRONT DOOR TRIM - LH / RH <i>New</i>	2 S	328.00	✓ 261.60
62	RADIATOR FAN RING <i>nn</i>	1 S	267.00	> X
63	RADIATOR FAN CONTROL UNIT <i>nn</i>	1 S	2,318.00	? X
64	FRONT NO PLATE <i>Dented</i>	S/N S	80.00	✓ 80
65	SUNDRIES <i>nec</i>	S	350.00	? 45.20
TOTAL SPARE PARTS		:	\$	40,790.00
TOTAL LABOUR CHARGES		:	\$	15,524.00
GRAND TOTAL		:	\$	<u>56,314.00</u>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adrian Lim
08/10/21

: are Authorized. 06 Days (Without Lock Carrier)
09 Days (With Lock Carrier)

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT