

Car-in 21/12/21-

wip: 56693

PREMIUM AUTOMOBILES

Kiam



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Veron

AIG - Adrian

- 6 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 51Z 2868 U

| | | | | | DAMAGED PARTS & PRICES | |
|------------------------------|--|-----|--------|--------------------|------------------------|--|
| S/N | PARTS DESCRIPTION | QTY | S/NETT | S/NETT | REMARKS | |
| 1 | FRONT BUMPER <i>rehd</i> | 1 | \$ | 2,251.00 | ✓ | |
| 2 | FRONT BUMPER FIXING PARTS <i>new</i> | 1 | \$ | 407.00 | x | |
| 3 | FRONT BUMPER SECURING STRIP ? | 2 | \$ | 71.00 | ? | |
| 4 | FRONT BUMPER GRILLE - CENTER <i>crackd</i> | 1 | \$ | 196.00 | ✓ | |
| 5 | FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i> | 1 | \$ | 228.00 | x | |
| 6 | FRONT AIR GUIDE - LH / RH <i>new</i> | 2 | \$ | 126.00 | x | |
| 7 | FRONT BUMPER AIR GUIDE GRILLE - LH / RH ? | 2 | \$ | 948.00 | ? | |
| 8 | RADIATOR GRILLE <i>Smashed</i> | 1 | | TBC | ✓ | |
| 9 | FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>crackd</i> | 2 | \$ | 102.00 | ✓ | |
| 10 | RADIATOR GRILLE COVER - UPPER ? | 1 | \$ | 189.00 | ? | |
| 11 | FRONT BUMPER FOAM FILLER PIECE <i>crackd</i> | 1 | \$ | 124.00 | ✓ | |
| 12 | FRONT BUMPER REINFORCEMENT BEAM ? | 1 | \$ | 845.00 | ? | |
| 13 | FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i> | 2 | \$ | 72.00 | x | |
| 14 | FRONT BUMPER BRACKET - LH / RH ? | 2 | \$ | 428.00 | ? | |
| 15 | FRONT BUMPER TOP COVER <i>crackd</i> | 1 | \$ | 127.00 | ✓ | |
| 16 | CAUTION STICKER <i>new</i> | 1 | \$ | 14.00 | ✓ | |
| 17 | AIRCON STICKER <i>new</i> | 1 | \$ | 8.00 | ✓ | |
| 18 | FRONT BUMPER LOCK CARRIER BRACKET ? | 1 | \$ | 137.00 | ? | |
| 19 | FRONT BUMPER SUPPORT - LH / RH ? | 2 | \$ | 58.00 | ? | |
| 20 | FRONT PARKING AID SENSOR - INNER <i>new</i> | 2 | | TBC | x | |
| SUB TOTAL SPARE PARTS | | | : | \$ 6,331.00 | | |

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Adrian
Removed.
H.S.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 684J 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. S1Z 2868 U

| | | | DAMAGED PARTS & PRICES | |
|------------------------------|--|-----|------------------------|---------|
| S/N | PARTS DESCRIPTION | QTY | S/NETT | REMARKS |
| 21 | FRONT BUMPER WIRING SET <i>Not m</i> | 1 | \$ 510.00 | X |
| 22 | HORN - LH / RH <i>Not m</i> | 2 | \$ 252.00 | + |
| 23 | HORN SUPPORT - LH / RH <i>Not m</i> | 2 | \$ 58.00 | + |
| 24 | BONNET <i>Bricled</i> | 1 | \$ 3,312.00 | ✓ |
| 25 | BONNET ATTACHEMENT PARTS <i>Not m</i> | 1 | \$ 123.00 | + |
| 26 | BONNET HINGE - LH / RH <i>Not m</i> | 2 | \$ 838.00 | + |
| 27 | BONNET IMPACT PROTECTION - CENTER / LH / RH <i>Not m</i> | 3 | \$ 84.00 | ✓ |
| 28 | BONNET SOUND ABSORBER <i>Not m</i> | 1 | \$ 343.00 | + |
| 29 | BONNET STRIKER (LH/RH) <i>Best.</i> | 2 | \$ 100.00 | ✓ |
| 30 | BONNET LOCK | 2 | \$ 427.00 | ? |
| 31 | BONNET MICRO-SWITCH | 1 | \$ 13.00 | ? |
| 32 | BONNET BOWDEN CABLE INNER - CENTER <i>Damaged</i> | 1 | \$ 58.00 | ✓ |
| 33 | BONNET BOWDEN CABLE OUTER - CENTER <i>Damaged</i> | 1 | \$ 58.00 | ✓ |
| 34 | BONNET RELEASE LEVER | 1 | \$ 14.00 | ? |
| 35 | BONNET LOCK CABLE | 1 | \$ 74.00 | ? |
| 36 | PLENUM CHAMBER <i>Not m</i> | 1 | \$ 97.00 | X |
| 37 | FRONT WHEEL HOUSING LINER - LH / RH <i>Not m</i> | 2 | \$ 550.00 | X |
| 38 | FRONT WHEEL SPOILER - LH / RH <i>Not m</i> | 2 | \$ 146.00 | X |
| 39 | FRONT SPOILER - LH / RH <i>Not m</i> | 2 | \$ 71.00 | X |
| 40 | HEADLIGHT - LH / RH | 2 | \$ 15,804.00 | ? |
| SUB TOTAL SPARE PARTS | | | \$ 22,932.00 | |

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJZ 2868 U

| | | | DAMAGED PARTS & PRICES | | |
|------------------------------|---|-----|------------------------|---------|--|
| S/N | PARTS DESCRIPTION | QTY | S/NETT | REMARKS | |
| 41 | LIFT CYLINDER - LH / RH | 2 | \$ 396.00 | + | |
| 42 | LIFT CYLINDER BRACKET - LH / RH | 2 | \$ 30.00 | + | |
| 43 | LIFT CYLINDER CORRUGATED PIPE | 1 | \$ 86.00 | + | |
| 44 | RADIATOR COOLANT LOCK CARRIER | 1 | \$ 1,016.00 | ? | |
| 45 | RADIATOR COOLANT SUPPORT - LH & RH | 2 | \$ 76.00 | ? | |
| 46 | A/C CONDENSER FLUID RESERVOIR | 1 | \$ 622.00 | ✓ | |
| 47 | REFRIGERANT LINE | 1 | \$ 167.00 | + | |
| 48 | REFRIGERANT DISCHARGE HOSE | 1 | \$ 340.00 | + | |
| 49 | REFRIGERANT COOLANT PIPE | 1 | \$ 248.00 | + | |
| 50 | OUTSIDE TEMPERATURE SENSOR BRACKET | 1 | \$ 19.00 | ✓ | |
| 51 | AIR COOLER CHARGED | 1 | \$ 587.00 | ? | |
| 52 | RADIATOR COOLANT COOLER | 1 | \$ 904.00 | ? | |
| 53 | RADIATOR COOLANT | 6 | \$ 266.00 | ? | |
| 54 | RADIATOR AIR GUIDE INNER- LH / RH | 2 | \$ 63.00 | ? | |
| 55 | RADIATOR AIR GUIDE OUTER- LH / RH | 2 | \$ 32.00 | ✓ | |
| 56 | RADIATOR AIR GUIDE - UPPER / LOWER | 2 | \$ 38.00 | ? | |
| 57 | RADIATOR INTAKE AIR DUCT LOWER - RH | 1 | \$ 22.00 | ? | |
| 58 | RADIATOR INTAKE AIR DUCT UPPER - RH | 1 | \$ 53.00 | ? | |
| 59 | RADIATOR INTAKE HOSE | 1 | \$ 95.00 | ? | |
| 60 | FRONT WINDOW SLOT SEAL TRIM STRIP - LH / RH | 2 | \$ 798.00 | ? | |
| SUB TOTAL SPARE PARTS | | | \$ 5,858.00 | | |

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.