

Car-in

21/12/21

Wip: 56693

PREMIUM AUTOMOBILES

Kiam

C.O.O

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 7323 FAX: 6841 1183

EMAIL: NORA.KIAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Veron

AIG - Adnan

- 6 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 5JZ 2868 U

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>cracked</i>	1 S	2,251.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1 S	407.00	x
3	FRONT BUMPER SECURING STRIP	2 S	71.00	✓
4	FRONT BUMPER GRILLE - CENTER <i>cracked</i>	1 S	196.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i>	1 S	228.00	x
6	FRONT AIR GUIDE - LH / RH <i>new</i>	2 S	126.00	x
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 S	948.00	✓
8	RADIATOR GRILLE <i>smashed</i>	1	TBC	✓
9	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>cracked</i>	2 S	102.00	✓
10	RADIATOR GRILLE COVER - UPPER	1 S	189.00	✓
11	FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>	1 S	124.00	✓
* 12	FRONT BUMPER REINFORCEMENT BEAM <i>Dented.</i>	1 S	845.00	✓
13	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 S	72.00	x
14	FRONT BUMPER BRACKET - LH / RH	2 S	428.00	✓
15	FRONT BUMPER TOP COVER <i>cracked</i>	1 S	127.00	✓
16	CAUTION STICKER <i>free</i>	1 S	14.00	✓
17	AIRCON STICKER	1 S	8.00	✓
18	FRONT BUMPER LOCK CARRIER BRACKET	1 S	137.00	✓
19	FRONT BUMPER SUPPORT - LH / RH	2 S	58.00	✓
20	FRONT PARKING AID SENSOR - INNER <i>new</i>	2	TBC	x
SUB TOTAL SPARE PARTS			S 6,331.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST


LEGEND: REMARKS (OK) = APPROVED, REMARKS (OO) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Adnan

Remarked

H.S.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6566 2323 FAX: 6541 1183

EMAIL: NOVA ENA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJZ 2868 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT BUMPER WIRING SET <i>Not in</i>	1	S 510.00	✓	
22	HORN - LH / RH <i>Not in</i>	2	S 252.00	✓	
23	HORN SUPPORT - LH / RH <i>Not in</i>	2	S 58.00	✓	
24	BONNET <i>Cracked</i>	1	S 3,312.00	✓	
25	BONNET ATTACHMENT PARTS <i>Not in</i>	1	S 123.00	✓	
26	BONNET HINGE - LH / RH <i>Not in</i>	2	S 838.00	✓	
27	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>Not in</i>	3	S 84.00	✓	
28	BONNET SOUND ABSORBER <i>Not in</i>	1	S 343.00	✓	
29	BONNET STRIKER (LH / RH) <i>Best</i>	2	S 100.00	✓	
30	BONNET LOCK	2	S 427.00	✓	
31	BONNET MICRO-SWITCH	1	S 13.00	✓	
32	BONNET BOWDEN CABLE INNER - CENTER	1	S 58.00	✓	} Damaged
33	BONNET BOWDEN CABLE OUTER - CENTER	1	S 58.00	✓	
34	BONNET RELEASE LEVER	1	S 14.00	✓	
35	BONNET LOCK CABLE	1	S 74.00	✓	
36	PLENUM CHAMBER <i>Not in</i>	1	S 97.00	✓	
37	FRONT WHEEL HOUSING LINER - LH / RH <i>Not in</i>	2	S 550.00	✓	
38	FRONT WHEEL SPOILER - LH / RH <i>Not in</i>	2	S 146.00	✓	
39	FRONT SPOILER - LH / RH <i>Not in</i>	2	S 71.00	✓	
* 40	HEADLIGHT (LH / RH) <i>RH cracked</i>	2	S 15,804.00	✓	
SUB TOTAL SPARE PARTS		:	S 22,932.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (O) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.