

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Veron.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJZ 2868 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEALIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, S/N S HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEALIGHT'S CONTROL UNIT AND POWER MODULE. S/N S	800.00	? - 250 <i>sls</i>
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACCUM AND REGAS. S/N S	1,700.00	? - 780 <i>sls</i>
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR. S/N S	560.00	✓
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. S	5,600.00	1000 (With 1/2 carrier) 325 (With full carrier)
SUB TOTAL LABOUR CHARGES		: \$ 9,140.00	

Resurveyed
Adrian
sls

Car-in

21/12/21.

Wipi 56693

PREMIUM AUTOMOBILES

Kiam

45 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 7323 FAX: 6843 1183

EMAIL: NORA.KIAT@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Veron

ATC - 1/1/21

- 6/1/21

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 51Z 2868 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PARTS	
			S/NETT	RE MARKS
1	FRONT BUMPER <i>crushed</i>	1 S	2,251.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1 S	407.00	✓
3	FRONT BUMPER SECURING STRIP	2 S	71.00	✓
4	FRONT BUMPER GRILLE - CENTER <i>crushed</i>	1 S	196.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i>	1 S	218.00	✓
6	FRONT AIR GUIDE - LH / RH <i>new</i>	2 S	126.00	✓
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 S	948.00	✓
8	RADIATOR GRILLE <i>crushed</i>	1	TBC	✓
9	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>crushed</i>	2 S	102.00	✓
10	RADIATOR GRILLE COVER - UPPER	1 S	189.00	✓
11	FRONT BUMPER FOAM FILLER PIECE <i>crushed</i>	1 S	124.00	✓
* 12	FRONT BUMPER REINFORCEMENT BEAM <i>crushed</i>	1 S	845.00	✓ <i>SSS</i>
13	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 S	72.00	✓
14	FRONT BUMPER BRACKET - LH / RH	2 S	428.00	✓
15	FRONT BUMPER TOP COVER <i>crushed</i>	1 S	127.00	✓
16	CAUTION STICKER <i>new</i>	1 S	14.00	✓
17	AIRCON STICKER	1 S	8.00	✓
* 18	FRONT BUMPER LOCK CARRIER BRACKET <i>new</i>	1 S	137.00	✓ <i>SSS</i>
* 19	FRONT BUMPER SUPPORT <i>new</i>	2 S	58.00	✓ <i>SSS</i>
20	FRONT PARKING AID SENSOR - INNER	2	TBC	✓
SUB TOTAL SPARE PARTS			S 6,331.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: (X) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

Adrian Lim

Responsible

SSS