

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0965/2021/ZK
DATE : 29-Nov-21
WIP : 55962

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 07/12/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

5 days - ok - Jy - 01 Mar 22

OWNER'S NAME : MR ZHANG WEI
ADDRESS : BLK 139A LORONG 1A TOA PAYOH
#34-44
SINGAPORE 311139
TELEPHONE : HP +65 8686 0169
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070144500
VEHICLE NO : **SMV 5772 C**
MODEL CODE : AUDI A3 SPORTBACK 1.4 TFSI
MODEL YEAR : 08/10/2020
ENGINE NO : CZE 866427
CHASSIS NO : WAUZZZ8V5LA088122
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Nov-21
PLACE OF ACCIDENT : MOUNT FABER LOOP

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 5772 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY	S/N \$	360.00	\$ 360.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	S/N \$	2,100.00	\$ 1,000.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,000.00	\$ 1,100.00
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	\$	280.00	\$ 280.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 5,282.00	\$ 2,932.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 5772 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,016.00	\$ 1,612.80
2	FRONT BUMPER FIXING SET	1	\$ 187.00	
3	FRONT BUMPER GUIDE SECTION - LH	1	\$ 39.00	
4	FRONT BUMPER CLOSING ELEMENT - LH / CENTER	2	\$ 594.00	
5	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 188.00	
6	FRONT FENDER	1	\$ 851.00	\$ 680.40
7	FRONT FENDER ATTACHMENT PART	1	\$ 72.00	
8	FRONT FENDER BRACKET - LH	1	\$ 48.00	
9	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 62.00	\$ 48.88
10	FRONT FENDER BRACE	1	\$ 96.00	\$ 76.48
11	FRONT WHEEL HOUSING LINER - LH	1	\$ 169.00	
12	FRONT WHEEL HOUSING LINER ATTACHMENT PART	1	\$ 57.00	
13	HEADLIGHT - LH	1	\$ 5,455.00	
14	HEADLIGHT LIFT CYLINDER - LH	1	\$ 142.00	
15	HEADLIGHT HOSE	1	\$ 68.00	
16	FRONT ALUMINIUM RIM - LH	1	\$ 1,245.00	\$ 996.00
17	SUNDRIES		\$ 300.00	\$ 59.44
18	TOTAL SPARE PARTS	:	\$ 11,589.00	\$ 3,474.00
19	TOTAL LABOUR CHARGES	:	\$ 5,282.00	\$ 2,932.00
20	GRAND TOTAL	:	\$ 16,871.00	\$ 6,406.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-17/01/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT