

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFM21216at Workshop m/s Kim Chue

of _____

Insured: _____

Policy No. _____

Claims No. CLMOMVP000001171Sum Insured: _____ Excess: 600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: \$92k.

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: Rep B/c.Veh No: SFM21216 Yr Regn: 28/9/17Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA/Make: Jaguar XE c.c. 1998Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 62650 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SAJAB 4AX8JC P23360Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45 R19R: 245/40 ZR19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 9/12/14 D.O.I. 10/12/14

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 6/135keep use 1st price for 4/5?front bumper under cover torn, horn cracked, front air guide gornish 2 in
front bumper reformed. 10.12.1123/12/11 2/5 @ 11,000 confirmed with Alan.**RED:24324.00;68%**

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: **5**

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS. \$ SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I.: (\$)

TOTAL

1 Kaki Bukit Ave 6 #01-48 Autobay

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 199802379R

not allocated
2 KLE
10/14/21
2/5 \$11,000 S. Long
Edaphic Attr. 21-

Date : 09.12.2021
Vehicle Num : SFM 2121G
Make/Model : JAGUAR XE 2.0
Assis/Engine no :
Accident Date : 09.12.2021
Claim No : 1221-22714
Reference :
Policy No :

Vehicle Num : SFM 2121G

Chassis/Engine no :

Claim No : 1221-22714

Reference :

Policy No :

List Item:			
1 pc Front bonnet			1,523.50
2 pc Front bonnet lower lock @ 425.20			850.40
2 pc Front bonnet lock catch @ 75.20			150.40
1 pc Front bonnet insulator			669.50
1 pc Front bumper air grille			137.00
1 pc Front bumper			2,860.00
1 pc Front bumper inner corner sponge LH			78.00
1 pc Front bumper inner centre sponge			185.00
2 pc Front bumper head lamp nuggle motor @ 245.00			490.00
4 pc Front bumper parking sensor @ 335.00			1,340.00
1 pc Front bumper parking sensor hardness wire			295.00
1 pc Front bumper top beam			275.00
2 pc Front bumper side retainer @ 195.20			390.40
1 pc Front bumper fog lamp cover top LH			49.60
1 pc Front bumper fog lamp cover lower			62.70
2 pc Head lamp @ 4985.00			9,970.00
2 pc Head lamp warning decals @ 48.20			96.40
2 pc Head lamp hid sensor @ 1295.00			2,590.00
2 pc Head lamp panel @ 298.70			597.40
1 pc Front support panel			1,860.00
1 pc Air cleaner box			672.10
1 pc Aircond condenser			1,550.00
1 pc Radiator assy			1,875.00
1 pc Front fender LH			1,765.80
1 pc Front fender chrome garnish			455.60
1 pc Front fender inner shield LH			315.20
1 pc Front grille assy			1,680.00
1 pc Front logo			475.00
List Item Total:			33,259.00
Discount 10%:			3,325.90
			29,933.10

12028.01

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 199802379R

PAGE 2 OF 2

Estimate : 22714

Date : 09.12.2021

Vehicle Num: SFM 2121G

Make/Model : JAGUAR XE 2.0

Chassis/Engine no :

Accident Date : 09.12.2021

Claim No : 1221-22714

Reference :

Policy No :

Qty	Particular	Amount \$
-----	------------	-----------

Special Nett Item :

1 pc Front number plate

SCA

\$	45.00
\$	45.00

40

Labour Charge :

To check wiring & diagnostic fault code

Remove & refix aircond condenser & refill gas

Remove and refix radiator

Knock dents on left front fender inner panel remove & refix and renew parts

Respray painting

\$	280.00
\$	150.00
\$	150.00
\$	1,500.00
\$	1,500.00
\$	3,580.00

50

100

100

X 800

100

E & O . E

Total Amount : \$ 33,558.10

KIM CHWEE AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-13890-12
10%
12891.10
14281.10
217
11424.

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-46 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

Supplementary : 22714

Date : 14.12.2021

Vehicle Num : SFM 2121G

Make/Model : JAGUAR XE 2.0

Chassis/Engine no :

Accident Date : 09.12.2021

Claim No : 1221-22714

Reference :

Policy No :

Qty	Particular	Supp	Amount S\$
-----	------------	------	------------

List Item :

Front bumper under cover	Torn	\$	185.00 ✓
Horn	one	\$	80.00 ✓
Front air guide garnish	Torn	\$	245.00 ✓
Front bumper reinforcement	DS	\$	1,012.11 ✓
Front bumper reinforcement bracket LH	Buf	\$	350.00 ✓
Front bumper reinforcement side bracket LH	one	\$	90.00 ✓
List Item Total :		\$	1,962.11
Discount 10 % :		\$	196.21
		\$	1,765.90

35324

E & O . E

Total Amount : \$ 1,765.90