

SIN YU SIN WORKSHOP

Reg No: 53253863C,

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103 / 97825292 Fax: (65) 681166

Email : Sinyusin@hotmail.com

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

09 December 2021

QUOTATION FOR ACCIDENT REPAIR OF SLE3729T HYUNDAI ELANTRA

THIRD PARTY INSURER: AIG

S/No.	Parts List	Qty	Amount (\$)
1.	Front headlamp RH	1	\$ 1198.00 <i>cut</i>
2.	Front headlamp lower bracket RH	1	98.60 \$ 128.00 <i>de</i>
3.	Front bumper	1	498.20 \$ 698.00 <i>de</i>
4.	Front bumper sider retainer L/R	2	55.00 <i>LH X m</i> \$ 110.00 <i>RH X nn</i>
5.	Front bumper fog lamp RH	1	\$ 245.00 <i>cut</i>
6.	Front bumper fog lamp cover RH	1	110 \$ 158.50 <i>de</i>
7.	Front bumper inner sponge	1	\$ 180.40 <i>X</i>
8.	Front support panel	1	\$ 996.00 <i>X</i>
9.	Front fender inner shield RH	1	\$ 128.70 <i>X</i>
Subtotal before discount			\$ 3842.60 <i>2149.80</i>
Discount 20%			\$ 768.52
Subtotal 1			\$ 3074.08 <i>1719.84</i>

S/NETT	Parts List	Qty	Amount (\$)
1.	Front bumper clip	1	\$ 30.00 <i>cut</i>
2.	Front fender inner shield clip	1	\$ 30.00 <i>X nn.</i>
S/Nett Total			\$ 60.00 <i>30</i>

Front Labour

To check wiring and rectify electrical faults where necessary	\$ 60.00 <i>30</i>
To straighten, repair, realign on front affected area and replace damaged parts	\$ 600.00 <i>200</i>
To spray painting on affected area	\$ 600.00 <i>200</i>
Total Labour Cost	\$ 1260.00 <i>430</i>

Total Cost Of Repairs (Total cost of parts + Total labour cost) **\$ 4,394.08**

Taufik 97495747
WP 13/12/21 @ 1145
Resurvey after repair
2 days
Taufik @ luhants-wm
2 days #