

ESTIMATE TO REPAIR

VEHICLE NO. : SNA 7631 L
MAKE : MERCEDES BENZ
MODEL : A200 AMG LINE AUTO
YEAR : 2020
CHASSIS NO : W1K1771872J294844

SURVEYOR NAME : *LKK*
DATE OF SURVEY : 28 DEC 2021
TIME OF SURVEY :

DATE : 09-Dec-21
DATE OF ACCIDENT : 02-Dec-21
THIRD PARTY REF : GBJ 2745 U
THIRD PARTY REF : AIG ASIA PACIFIC INSURANCE PTE LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	front bumper			\$M 1,341.00	✓
1 pc	rear bumper inner part			\$ J 540.00	X
1 pc	n/s head lamp			\$P 2,616.00	X
1 pc	front radar sensor			\$ SVC 1,028.00	X
	Less 10%			\$	5,525.00
				\$	552.50
				\$	4,972.50
	To putting spray paint			\$	300.00
	To replace radar sensor & reprogram			\$	500.00
	labour charges			\$	300.00
TG/VL	TOTAL			\$	6,072.50
<i>NOT Authorized</i> <i>Running Bypassing</i> <i>2 days</i> LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					

2501
X
2001

Lim Tan Motor Pte Ltd
Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64569127 Email: edmund@ltm.sg
Co. Reg No. 199307277D GST Reg No. M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without prior written consent of Lim Tan Motor Pte Ltd