Automotive Repair Centre Pte Ltd **Estimate** CO. Reg. No. : 201312913C Steve (LKK) 48 Toh Guan Road East (Enterprise Hub) ESTIMATE NO.: EST2112-304-TG #02-146, Singapore 608586 DATE: 9-Dec-2021 Tel: 64688834 Fax: 64622278 POLICY NO.: P10526296R00 E-mail: info@automotiverepaircentre.com.sg VEHICLE REG. NO. : SGE7817E VEHICLE MAKE: TOYOTA NOAH HYBRID 1.8X 2018 то FOR SURVEYOR Motor Claim Department **SMRT TAXIS PTE LTD** 60 Woodlands Industrial Park E4

ESTIMATE REPAIR COST

Singapore 757705

Tel: (65) 63690111, Fax: (65) 63693639

	ESTIMATE REPAIR COS	ST					_
NO.	DESCRIPTION	QUANTITY	רואט	COST	T	OTAL COST	
	SPARE PARTS						1
1	Front Bumper _ BR	1	\$	980.00	\$	980.00	1
2	Bumper Clips / hec	10	\$	5.50	\$	55.00	1
3	Front Bumper Retainer RH / BR	1	\$	140.00	\$	140.00	1
4	Front Bumper Retainer LH 😾 🎧	1	\$	140.00	\$	140.00	1
5	Front Bumper Foglamp Cover RH / CVT	1	\$	150.00	\$	150.00	1
7	Front Grille Assy 💢 📉	1	\$	1,300.00	\$	1,300.00	
8	Front Emblem 😾 ₥	1	\$	260.00	\$	260.00	1
9	Head Lamp RH / BR	1	\$	3,580.00	\$	3,580.00	
11	Front Fender RH $\longrightarrow \mathcal{V}$	1	\$	1,250.00	\$	1,250.00	1
12	Front Fender Hybrid Emblem / hec	1	\$	100.00	\$	100.00	
13	Front Fender Shield RH / Th	1	\$	280.00	\$	280.00	
14	Front Fender Clips / T	10	\$	5.50	\$	55.00	
15	Washer Spare Tank / CRU	1	\$	320.00	\$	320.00	
16	Front Fender Liner Bracket RH 🖊 D	1	\$	130.00	\$	130.00	
	Total Spare Parts				\$	8,740.00	
	SPECIAL NETT						
			Total S _I	pecial Nett	\$	-	
	<u>LABOUR</u>						
17	Spray Painting Front Bumper, Fender RH & Door RH	1	\$	800.00	\$	800.00	6¢
18	Remove, refit and repair affected accident parts	1	\$	600.00	\$	600.00	41
19	Repair & Respray Front Rim RH	1	\$	100.00	\$	100.00	
20	Wheel Alignment	1	\$	80.00	\$	80.00	6
21	Apply Rust Proofing on Replaced/Repaired Panel	1	\$	100.00	\$	100.00	30
22	Check and Rectify Electrical Wiring	1	\$	30.00	\$	30.00	
The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Amount Before Excess					\$	1,710.00	
					\$	10,450.00	1
Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Add GST @ 7%						731.50	
Quotation on parts and labour are current and subject to change. Total Amount Payable					\$	11,181.50	1