

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2112-304-TG

DATE : 9-Dec-2021

POLICY NO. : P10526296R00

VEHICLE REG. NO. : SGE7817E

VEHICLE MAKE : TOYOTA NOAH HYBRID 1.8X 2018

TO Motor Claim Department

SMRT TAXIS PTE LTD

60 Woodlands Industrial Park E4

Singapore 757705

Tel: (65) 63690111, Fax: (65) 63693639

FOR SURVEYOR

Steve (LKK)

10/12/21

w/P

L/S

Respry After Spray
5 days**ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Front Bumper — BR	1	\$ 980.00	\$ 980.00 —
2	Bumper Clips — nec	10	\$ 5.50	\$ 55.00 30 —
3	Front Bumper Retainer RH — BR	1	\$ 140.00	\$ 140.00 110 —
4	Front Bumper Retainer LH x nn	1	\$ 140.00	\$ 140.00
5	Front Bumper Foglamp Cover RH — CVT	1	\$ 150.00	\$ 150.00 —
7	Front Grille Assy x nn	1	\$ 1,300.00	\$ 1,300.00
8	Front Emblem x m	1	\$ 260.00	\$ 260.00
9	Head Lamp RH — BR	1	\$ 3,580.00	\$ 3,580.00 3001 —
11	Front Fender RH — DD	1	\$ 1,250.00	\$ 1,250.00 788 —
12	Front Fender Hybrid Emblem — nec	1	\$ 100.00	\$ 100.00 —
13	Front Fender Shield RH — Th	1	\$ 280.00	\$ 280.00 171 —
14	Front Fender Clips — Th	10	\$ 5.50	\$ 55.00 20 —
15	Washer Spare Tank — CRV	1	\$ 320.00	\$ 320.00 167 —
16	Front Fender Liner Bracket RH — DD	1	\$ 130.00	\$ 130.00 —
Total Spare Parts				\$ 8,740.00 5747
SPECIAL NETT				
Total Special Nett				\$ - 25% 430.25
LABOUR				
17	Spray Painting Front Bumper, Fender RH & Door RH	1	\$ 800.00	\$ 800.00 600
18	Remove, refit and repair affected accident parts	1	\$ 600.00	\$ 600.00 400
19	Repair & Respray Front Rim RH	1	\$ 100.00	\$ 100.00 —
20	Wheel Alignment	1	\$ 80.00	\$ 80.00 60
21	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00 30
22	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00 —
Total Labour				\$ 1,710.00 1220
Amount Before Excess				\$ 10,450.00
Add GST @ 7%				731.50
Total Amount Payable				\$ 11,181.50

Estimate prepared by: RAZALI

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

= 5530.25