

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0875/2021/JT
DATE : 25-Oct-21
WIP : 50589

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 09/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR GAN CHEONG TECK
ADDRESS : 64 CHAO CHU KANG AVE 5
#08-10
SINGAPORE 688193
TELEPHONE : HP +65 96657552
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070032301
VEHICLE NO : **SMS 7456 T**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 12/3/2020
ENGINE NO : CVK 087991
CHASSIS NO : WAUZZZF47KA117936
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Oct-21
PLACE OF ACCIDENT : CHOA CHU KANG

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 7456 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$ 360.00	/ ✓
2	TO DISMANTLE AND RENW REAR BUMPER. TO REPAIR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PAERTS REMOVED.	\$ 1,400.00	500 ✓
3	TO RESPRAY REAR BUMPER AND REAR END PANELLING.	\$ 2,000.00	550 ✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	/ ✓
TOTAL LABOUR CHARGES		: \$ 3,952.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 7456 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER / <i>RL</i>	1	\$ 2,996.00	2396.8
2	REAR BUMPER FIXING SET <i>X NN</i>	1	\$ 459.00	
3	REAR BUMPER SECURING STRIP <i>ML</i>	1	\$ 223.00	178
4	REAR BUMPER SPOILER <i>RL</i>	1	\$ 249.00	198.8
5	REAR BUMPER TRIM <i>at</i>	1	\$ 292.00	233.2
6	REAR BUMPER BRACKET - LH / RH <i>X NN</i>	2	\$ 232.00	
7	REAR LIGHT REFLECTOR - LH / RH <i>X NN</i>	2	\$ 82.00	
8	REAR BUMPER CARRIER <i>X NN</i>	1	\$ 1,063.00	
9	REAR BUMPER SEAL <i>X NN</i>	2	\$ 28.00	
10	REAR BUMPER GUIDE SECTION - LH / RH <i>X Snn</i>	2	\$ 46.00	
11	REAR BUMPER HOLDING STRAP - LH / RH <i>X</i>	2	\$ 166.00	
12	REAR PARKING AID SENSOR <i>X NN</i>	2	TBC	
13	REAR PARKING AID SENSOR SEAL <i>ML</i>	4	\$ 14.00	8.64
14	REAR EXHAUST TRIM - LH / RH <i>X NN</i>	2	\$ 708.00	
15	SUNDRIES <i>✓ NEC</i>		\$ 250.00	17.68
TOTAL SPARE PARTS			: \$ 6,808.00	3033.12
TOTAL LABOUR CHARGES			: \$ 3,952.00	
GRAND TOTAL			: \$ 10,760.00	4635.12

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

Uno Q:~
07/12/21
Not Authorised
3 Days

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

before paint photos

Excess: T&A

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party claims on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplemental items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: