

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
Singapore 568047
Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MPC21B00013100	Date of Loss:	06/12/2021
Vehicle Reg. No.:	SGH8008B	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	Chai Chian Wee		
Driver:	Chai Chian Wee		
Make/Model:	LEXUS IS250, 2.5 (A)	Vehicle Reg. Date:	25/08/2006
Vehicle Colour:	Black		
Engine No:	4GR0231900	Chassis No:	JHBK262102021742
Odometer:	229949 KM		
Paint Type:		<i>NOT NOTICED</i>	
Total Loss?	NO	<i>1. B.1, 1. B.2 & B.3</i>	
Est. Duration of Repair (day)	<i>4 day</i>	<i>Repair After Rain</i>	
Present Location:	ACCORD AUTO SERVICES PTE LTD (HQ)	<i>Ex @ 750</i>	

NOT Notched
1-B.1, ~~4-P~~ 8 B4
Many After Pains
Ex 875d

8 2625-90

COST OF CLAIMS

Amount

Parts	3,972.15
Miscellaneous Items	80.00
Labour	1,860.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$)	5,912.15
+ GST 7.00% (S\$)	413.85
Nett Amount (S\$)	6,326.00

This claim is handled by: GOH JACQUELINE

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

REPAIR DETAILS

Reference

Part Source: MRM-SG
 Parts: 143
 Labour: Repairer's
 Print Code: **Accord Auto Services Pte Ltd/SGH8008B/08/12/2021 19:00**
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BONNET				
2	1		*FRONT BUMPER	0.00	0.00	R *800.00 F	X
3	1		*FRONT BUMPET SIDE RETAINER LH & RH	0.00	0.00	B *280.00 F	✓
4	1		*FRONT BUMPER TOP RUBBER	c/s cm	0.00	*80.00 F	4
5	1		*FRONT GRILLE	0.00	0.00	na *38.00 F	✓
6	1		*FRONT GRILLE EMBLEM	Pr	0.00	*130.00 F	X
7	1		*FRONT NUMBER PLATE GARNISH	na	0.00	*40.00 F	X
8	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	Pr *50.00 F	X
9	1		*FRONT RH FOGLAMP	0.00	0.00	Pr *45.00 F	X
10	1		*FRONT RH FOGLAMP SIDE COVER	my Ar	0.00	*155.00 F	✓
11	1		*FRONT RH HEADLAMP	Pr	0.00	*80.00 F	X
12	1		*FRONT RH HEADLAMP TOP BRACKET	my Br	0.00	*400.00 F	✓
13	1		*FRONT RH HEADLAMP LOWER BRACKET	cm	0.00	*90.00 F	2
14	1		*FRONT RH FENDER SHIELD	cm	0.00	*60.00 F	1
15	1		*FRONT RH FENDER	cm	0.00	*175.00 F	1
16	1		*FRONT REINFORCEMENT BAR	Br	0.00	*320.00 F	1
17	1		*FRONT RH REINFORCEMENT ARM	R	0.00	*210.00 F	X
18	1		*FRONT BUMPER SPONGE	R	0.00	*130.00 F	X
19	1		*FRONT RADIATOR TOP GARNISH	Pr	0.00	*55.00 F	X
20	1		*FRONT SUPPORT PANEL	Pr	0.00	*165.00 F	X
				R	0.00	*480.00 F	X
Sub Total (\$\$)						3,783.00	
+ Margin on L,N Items 5.00% (\$\$)						189.15	
Total Parts (\$\$)						3,972.15	

Accord Auto Services Pte Ltd/SGH8008B/08/12/2021 19:00. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

			Amount	
1	1	FRONT BUMPER & RADIATOR TOP GARNISH CLIPS	nn 50.00	X
2	1	FRONT FENDER SHIELD CLIPS	nn 30.00	✓
Sub Total (S\$)			80.00	

Estimates on Labour

No Particulars

Labour Items

Lab.Type Amount

1	SPRAY PAINTING ON ALL AFFECTED AREA			540
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	800.00	400
3	TO CHECK WIRING SYSTEM & LIGHT	New	80.00	20
4	TO REMOVE/REFIX RADIATOR & AIRCON CONDENSOR FOR REPLACE SUPPORT PANEL (TOP UP AIRCON GAS, RADIATOR & ETC..)	New	nn 180.00	X
Gross Labour Cost (S\$)			1,860.00	

Accord Auto Services Pte Ltd/SGH8008B/08/12/2021 19:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >