

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Dec 2021)
 Parts: 143 LEXUS IS250 2.5 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Accord Auto Services Pte Ltd/SGH8008B/08/12/2021 19:00
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BONNET	0.00	0.00	R *800.00 F	X
2	1		*FRONT BUMPER	0.00	0.00	R *280.00 F	✓
3	1		*FRONT BUMPERT SIDE RETAINER LH & RH	0.00	0.00	clsem *80.00 F	4
4	1		*FRONT BUMPER TOP RUBBER	0.00	0.00	an *38.00 F	✓
5	1		*FRONT GRILLE	0.00	0.00	sn *130.00 F	X
6	1		*FRONT GRILLE EMBLEM	0.00	0.00	an *40.00 F	✓
7	1		*FRONT NUMBER PLATE GARNISH	0.00	0.00	sn *50.00 F	X
8	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	sn *45.00 F	✓
9	1		*FRONT RH FOGLAMP	0.00	0.00	mtj an *155.00 F	✓
10	1		*FRONT RH FOGLAMP SIDE COVER	0.00	0.00	sn *80.00 F	X
11	1		*FRONT RH HEADLAMP	0.00	0.00	mtj an *400.00 F	✓
12	1		*FRONT RH HEADLAMP TOP BRACKET	0.00	0.00	an *90.00 F	7
13	1		*FRONT RH HEADLAMP LOWER BRACKET	0.00	0.00	cm *60.00 F	✓
14	1		*FRONT RH FENDER SHIELD	0.00	0.00	cm *175.00 F	✓
15	1		*FRONT RH FENDER	0.00	0.00	an *320.00 F	✓
16	1		*FRONT REINFORCEMENT BAR	0.00	0.00	R *210.00 F	X
17	1		*FRONT RH REINFORCEMENT ARM	0.00	0.00	R *130.00 F	X
18	1		*FRONT BUMPER SPONGE	0.00	0.00	sn *55.00 F	X
19	1		*FRONT RADIATOR TOP GARNISH	0.00	0.00	sn *165.00 F	X
20	1		*FRONT SUPPORT PANEL	0.00	0.00	*480.00 F	7

F=Franchise part.

Sub Total (S\$)	3,783.00
+ Margin on L,N Items 5.00% (S\$)	189.15
Total Parts (S\$)	3,972.15

Accord Auto Services Pte Ltd/SGH8008B/08/12/2021 19:00. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT BUMPER & RADIATOR TOP GARNISH CLIPS	nn 50.00 X
2	1	FRONT FENDER SHIELD CLIPS	nn 30.00 ✓
Sub Total (S\$)			80.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	SPRAY PAINTING ON ALL AFFECTED AREA	New	800.00 500
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	800.00 400
3	TO CHECK WIRING SYSTEM & LIGHT	New	80.00 200
4	TO REMOVE/REFIX RADIATOR & AIRCON CONDENSOR FOR REPLACE SUPPORT PANEL (TOP UP AIRCON GAS, RADIATOR & ETC..)	New	nn 180.00 X
Gross Labour Cost (S\$)			1,860.00

Accord Auto Services Pte Ltd/SGH8008B/08/12/2021 19:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >