

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4372A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	COVER REAR BUMPER	CUT	458.60	458.60
10	BUMPER PIECE	NOT NECESSARY	22.00	-
1	GUARD-REAR BUMPER CENTER	SCRATCHED	552.60	552.60
1	ORNAMENT SUB-ASSY BACK DO	NECESSARY	52.90	52.90
1	PLATE-BACK DOOR NAME (HYB)	NECESSARY	52.40	52.40
1	PLATE-BACK DOOR NAME (PRI)	NECESSARY	60.80	60.80
	LESS 25% DISCOUNT		-299.83	-294.33
			899.47	882.97
<u>NETT ITEMS</u>				
1	APP LOGO REAR BONNET CTPL (N)	NECESSARY	40.00	40.00
1	REAR BONNET COMFORTDELGRO (N)	NECESSARY	30.00	30.00
1	REAR BOOT 65521111 CTPL (N)	NECESSARY	30.00	30.00
	LESS 10% DISCOUNT		-10.00	-10.00
			90.00	90.00
<u>SPECIAL NETT ITEMS</u>				
1	BUMPER PROTECTOR MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
<u>LABOUR</u>				
	PANEL BEATING.		400.00	350.00
	SPRAYPAINT CHARGE.		600.00	500.00
	REMOVE/REFIX REVERSE SENSOR.		50.00	20.00
			1,050.00	870.00
GRAND TOTAL			2,089.47	1,892.97
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,892.97

Report Ref No. NS/INC21012513/Vtcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.