


**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No \_\_\_\_\_  
 Clnms No. **MT/1154283-002**  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs 2 days  Res.: Yes or No  
 Lum Sum \_\_\_\_\_ % J Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT



Veh No: SHA4372A ✓ Yr Regn: 27/02/19  
 Type: M. Car / M. Cycle / Bus / Van / Lorry /  Taxi / Primo Mover /  
 Truck / Trailer or  
 Make: Toyota Prius Hybrid c.c. 1798  
 Colour: blue AC: Insured / Std / Nil / NA  
 Sp. Reading: 137459 T/Radio: Insured / Std / Nil / NA  
 Eng/No: \_\_\_\_\_  
 C/No: 3TDH83Fax03090562  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  Good / Jammed / Leaked / Burnt or  
 Brake:  Good / Jammed / Leaked / Burnt or  
 Mod: Nil /  S/RIm STD A/RIm or  
 Tyre Size: F: 195/65R15  
 R: 195/65R15  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or westlake  

Front	Rear
R/Bal. <u>5</u> mm	R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm	L/Bal. <u>5</u> mm
D.O.A. <u>9/12/21</u>	D.O.I. <u>9/12/21 1630</u>

 Survey held at CDGE  
 Des. of Damages: Fnt /  Rear / O/S / N/S / UIC / Roof/Top or  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>NO CIA Given</u>
	<b>FINALISE AT 1892.97,</b>
	<b>RED: 196.5;0%</b>

Case/Time File Pass to?  : Procl. Report  
 : Final Report  
 Date/Time File Return to?

Days Of Repair: 2  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Inve (\$ \_\_\_\_\_)  
 : Wheel end (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_  
 Transportation \_\_\_\_\_  
 \$ + PG \$ \_\_\_\_\_  
 Fines \_\_\_\_\_  
 Other \_\_\_\_\_  
 Total \_\_\_\_\_

Request For: \_\_\_\_\_  
 Date: \_\_\_\_\_

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305497430  
 REGN NO : SHA4372A ✓  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID(G4A)  
 DATE OF REGN : 27.12.2019  
 DATE/TIME IN : 09.12.2021 09:15  
 ACCIDENT DATE : 09.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2282-G	COVER REAR BUMPER%	1	458.60	25.00	343.95	Xr	
0002	04-01-0302-2267-G	BUMPER PIECE	10	22.00	25.00	16.50	Dis	
0003	04-01-0302-2287-G	GUARD-REAR BUMPER CENTER	1	552.60	25.00	414.45	Xsuc	
0004	04-01-0302-2269-G	ORNAMENT SUB-ASSY BACK DO	1	52.90	25.00	39.67	Xre	
0005	04-01-0302-2270-G	PLATE-BACK DOOR NAME (HYB	1	52.40	25.00	39.30	Xre	
0006	04-01-0302-2271-G	PLATE-BACK DOOR NAME (PRI	1	60.80	25.00	45.60	Xre	
0007	28-01-9999-2025-A	APP LOGO REAR BONNET CTPL	1 N	40.00	10.00	36.00	Xre	
0008	28-01-0302-2015-A	REAR BONNET COMFORTDELGRO	1 N	30.00	10.00	27.00	Xre	
0009	28-01-0302-0006-A	REAR BOOT 65521111 CTPL^	1 N	30.00	10.00	27.00	Xre	
							SUB-TOTAL :	989.47

JOB NATURE

0000	PB	PANEL BEATING	400.00	350
0001	SP	SPRAYPAINT CHARGE	600.00	500 ✓

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305497430  
 REGN NO : SH1A4372A  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID  
 DATE OF REGN : 27.12.2019  
 DATE/TIME IN : 09.12.2021 09:1  
 ACCIDENT DATE : 09.12.2021

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0002 L REMOVE/REFIX REVERSE SENSOR	50.00				20
SUB-TOTAL :					1,050.00
TOTAL :					2,039.47

MVA NAME & SIGNATURE  
 DATE :

AUTHORISED : YES / NO  
 SURVEYOR NAME & SIGNATURE  
 DATE :

*Thuan@lkkauto.com*  
*87235769*  
*9/12/21 1630*  
*11p bfr paint photo*  
*2 days w P ✓*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

am: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 4150151

JC NO305497430


COMER  
S COMFORT TRANSPORTATION PTE LTD  
OMER NO 7010045  
ESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
(R) 65508755 (O)  
(P)  
DUPLICATE CARD NO.

REGN NO SHA4372A	MILEAGE
MAKE TOYOTA	FUEL E 1/2 F
MODEL PRIUS HYBRID(G4A09)	DATE/TIME IN 12.2021 09:15
YR OF MANU 27.12.2019	TARGET DATE
CHANGE CODE JTDKB3FUX03090562	COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 09.12.2021  
DURE: 3P.09.12.2021

NO LABOR CODE DESCRIPTION



VEHICLE PASSED OUT BY

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Management Slip  
Vehicle No: SHA4372A  
Signature: JU NTUC  
Signature/Date

Exit Pass  
Vehicle No: SHA4372A  
Name of Service Advisor  
Date  
To be kept by Security Guard