

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF642X

*Not Notified
Melany Bepain*

AAD2112-

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

09 DEC 2021

SHF642X

JTDKB3FU003092045

TOYOTA

PRIUS GEN 4

02/12/2021

TOKIO

12/03/2021

PART	LIST	
1 COVER, FRONT BUMPER	\$ R ₁ 521.00	✓
1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$ DIT 110.50	✓
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$ R ₁ 716.60	✓
1 REINFORCEMENT, FRONT BUMPER, NO.2	\$ R ₁ 246.10	✓
1 ABSORBER, FRONT BUMPER, LOWER	\$ CM 132.70	✓
1 ABSORBER, FRONT BUMPER ENERGY	\$ CM 80.20	✓
1 SUPPORT, FRONT BUMPER SIDE, RH	\$ DIT 80.10	✓
1 SUPPORT, FRONT BUMPER SIDE, LH	\$ DIT 82.30	✓
1 COVER, ENGINE UNDER, NO.1	\$ DIT 472.40	✓
1 COVER SUB-ASSY, ENGINE UNDER, NO.2	\$ 241.90	?
1 EXTENSION, FRONT BUMPER, RH	\$ 120.10	?
1 EXTENSION, FRONT BUMPER, LH	\$ 120.10	?
1 MOULDING, FRONT BUMPER SIDE, LH	\$ R ₁ 95.60	X
1 MOULDING, FRONT BUMPER SIDE, RH	\$ CM 95.60	✓
1 COVER, FRONT BUMPER HOLE, LH	\$ M ₁ 30.20	✓
1 COVER, FRONT BUMPER HOLE, RH	\$ M ₁ 30.20	✓
1 LAMP ASSY, FOG, LH	\$ 237.10	?
1 LAMP ASSY, FOG, RH	\$ 237.10	?
1 UNIT ASSY, HEADLAMP, LH	\$ B ₁ 2,637.60	✓
1 COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$ 3,772.50	?
1 UNIT ASSY, HEADLAMP, RH	\$ CM 2,637.60	✓
1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$ 3,772.50	?
1 GRILLE SUB-ASSY, RADIATOR	\$ CM 422.50	✓
1 GRILLE, RADIATOR, LOWER NO.1	\$ CM 178.60	✓
1 EMBLEM ASSY, RADIATOR GRILLE	\$ CM 105.80	✓
1 SUPPORT, RADIATOR, UPPER RH	\$ DIT 78.90	✓
1 SUPPORT, RADIATOR, UPPER LH	\$ DIT 78.90	✓
1 SUPPORT SUB-ASSY, RADIATOR, UPPER	\$ R ₁ 377.10	✓

Trans-cab Auto Services Pte Ltd**AAD2112-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF642X

1	SUPPORT SUB-ASSY, RADIATOR, LOWER	\$	409.90	?
1	SUPPORT SUB-ASSY, RADIATOR, LH	\$	R ₁ 245.10	✓
1	SUPPORT SUB-ASSY, RADIATOR, RH	\$	R ₁ 245.10	✓
1	HOOD SUB-ASSY	\$	B ₁ 983.10	✓
1	HINGE ASSY, HOOD, LH	\$	R ₁ 58.90	✓
1	HINGE ASSY, HOOD, RH	\$	R ₁ 58.90	✓
1	BRACE, HOOD LOCK SUPPORT	\$	Pi 1 78.30	✓
1	INSULATOR, HOOD	\$	Re turn 410.90	✓
1	LOCK ASSY, HOOD	\$	R ₁ 135.00	✓
1	SEAL, HOOD TO FRONT END PANEL	\$	R ₁ 85.50	✓
1	WIRE, ENGINE ROOM MAIN	\$	7,323.90	?
1	HORN ASSY, HIGH PITCHED	\$	134.80	?
1	HORN ASSY, LOW PITCHED	\$	134.80	?
1	GUIDE, RADIATOR AIR, NO.1 LH	\$	69.90	?
1	GUIDE, RADIATOR AIR, NO.1 RH	\$	65.30	?
1	GUIDE, RADIATOR AIR, NO.3	\$	112.70	?
1	GUIDE, RADIATOR AIR, NO.2	\$	53.40	?
1	SEAL, RADIATOR TO SUPPORT, NO.3	\$	32.40	?
1	SEAL, RADIATOR TO SUPPORT, NO.2	\$	32.60	?
1	INLET, AIR CLEANER, NO.1	\$	155.60	?
1	INLET, AIR CLEANER, NO.3	\$	42.10	?
1	INLET, AIR CLEANER, NO.2	\$	112.70	?
1	HOSE, AIR CLEANER, NO.1	\$	74.00	?
1	JAR ASSY, WINDSHIELD WASHER	\$	nd 219.10	✓
1	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$	292.40	?
1	INLET SUB-ASSY, WASHER	\$	67.00	?
1	CONDENSER ASSY, COOLER	\$	1,783.20	?
1	HOSE SUB-ASSY, SUCTION	\$	646.80	?
1	HOSE SUB-ASSY, DISCHARGE	\$	402.90	?
1	PIPE SUB-ASSY, SUCTION	\$	465.80	?
1	SENSOR, AIRCONDITIONER PRESSURE	\$	342.80	?
1	TUBE & ACCESSORY ASSY, AIR CONDITIONER	\$	691.00	?
1	COMPRESSOR ASSY, W/MOTOR	\$	Sm 4,771.60	X
1	RADIATOR ASSY	\$	2,218.00	?
1	SHROUD, FAN	\$	264.70	?
1	FAN, RH	\$	281.30	?
1	FAN, LH	\$	219.10	?

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2112-**SHF642X**

1	MOTOR, COOLING FAN, LH	\$	655.10	?
1	MOTOR, COOLING FAN, RH	\$	535.50	?
1	TANK ASSY, INVERTER RESERVE	\$	443.00	?
1	INVERTER WATER PUMP ASSY(W/MOTOR)	\$	518.60	?
1	BATTERY	\$	<i>Ref</i> 1,584.90	✓
1	CLAMP, BATTERY, NO.2	\$	51.80	?
1	CLAMP SUB-ASSY, BATTERY	\$	115.50	?
1	TERMINAL, BATTERY POSITIVE	\$	58.10	?
1	COVER, FUSIBLE LINK	\$	33.90	?
1	SENSOR ASSY, BATTERY STATE	\$	306.10	?
1	BLOCK ASSY, FUSIBLE LINK	\$	119.60	?
1	TANK, RESERVE SEALED W/O CAP	\$	151.40	?
1	CLEANER ASSY, AIR	\$	1,147.00	?
1	BRACKET, HEADLAMP, LH	\$	<i>mi7</i> 34.80	✓
1	BRACKET, HEADLAMP, RH	\$	34.80	?
1	STAY SUB-ASSY, FRONT BUMPER, LH	\$	47.50	?
1	STAY SUB-ASSY, FRONT BUMPER, RH	\$	47.50	?
1	BRACKET, FRONT BUMPER SIDE, LH	\$	59.30	?
1	BRACKET, FRONT BUMPER SIDE, RH	\$	59.30	?
1	BRACKET, RADIATOR GRILLE MOUNTING, LH	\$	36.60	?
1	BRACKET, RADIATOR GRILLE MOUNTING, RH	\$	36.60	?
1	MEMBER SUB-ASSY, FRONT SIDE, RH	\$	<i>R</i> 2,342.30	X
1	MEMBER SUB-ASSY, FRONT SIDE, LH	\$	<i>R</i> 2,342.30	X
1	COVER, RADIATOR SUPPORT OPENING	\$	<i>mi7</i> 211.50	✓
1	ACTUATOR ASSY, SHIFT CONTROL	\$	1,036.40	?
1	COOLER, MOTOR COOLING	\$	297.20	?
1	MIRROR ASSY, OUTER REAR VIEW, RH	\$	<i>Ref/6u</i> 1,436.60	✓
1	COVER SUB-ASSY, FRONT PILLAR, UPR LH	\$	<i>mi7</i> 100.40	✓
1	COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$	<i>mi7</i> 100.40	✓
1	FENDER SUB-ASSY, FRONT RH	\$	<i>Bu</i> 977.80	✓
1	LINER, FRONT FENDER, RH	\$	<i>su</i> 202.50	X
1	EMBLEM, SIDE PANEL, RH	\$	<i>su</i> 54.60	✓
1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	<i>R</i> 1,300.70	X
1	LOCK ASSY, FRONT DOOR W/MOTOR, RH	\$	<i>R</i> 603.20	X
1	MOULDING, FRONT DOOR WINDOW FRAME, FRONT RH	\$	<i>su</i> 38.60	X
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$	<i>su</i> 193.50	X
1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	<i>su</i> 390.60	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2112-

SHF642X

1	MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$	P _h	926.00	
1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$	S _h	321.10	
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	H	110.60	
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	H	97.50	
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	P _h	238.30	
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	W _h	43.50	
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	W _h	13.30	
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	W _h	26.30	
1	FENDER SUB-ASSY, FRONT LH	\$	B _h	977.80	✓
1	LINER, FRONT FENDER, LH	\$	L _h	202.50	✓
1	EMBLEM, SIDE PANEL	\$	M _h	54.60	✓
1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	H	1,300.70	
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	\$	S _h	193.50	
1	HANDLE ASSY, FRONT DOOR OUTSIDE, LH	\$	S _h	390.60	
1	WEATHERSTRIP, FRONT DOOR, LH	\$	P _h	231.30	
1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	H	110.60	
1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	H	97.50	
1	TAPE, BLACK OUT, NO.1 FRT LH	\$	W _h	13.30	
1	TAPE, BLACK OUT, NO.2 FRT LH	\$	W _h	43.50	
1	TAPE, BLACK OUT, NO.3 FRT LH	\$	W _h	26.30	
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$	S _h	926.00	
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$	S _h	238.30	
1	COMPUTER ASSY, AIR BAG	\$	M _h	1,546.00	✓
1	SENSOR, AIR BAG, FRONT LH	\$	M _h	373.90	✓
1	SENSOR, AIR BAG, FRONT RH	\$	M _h	373.90	✓
1	AIR BAG ASSY, INSTRUMENT PANEL PASSENGER W/O DOOR	\$	B _h	3,869.30	✓
1	WHEEL ASSY, STEERING	\$		1,492.50	✓
1	BELT ASSY, FRONT SEAT OUTER, RH	\$	T _h	995.10	✓
1	BELT ASSY, FRONT SEAT OUTER, LH	\$	T _h	995.10	✓
1	BELT ASSY, REAR SEAT 3 POINT TYPE, OUTER LH	\$	T _h	995.10	✓
1	BELT ASSY, REAR SEAT 3 POINT TYPE, OUTER RH	\$	T _h	995.10	✓
1	GLASS, WINDSHIELD	\$	CM	1,576.50	✓

TOTAL	\$	78,933.50
25%	\$	19,733.38
	\$	59,200.13

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF642X

AAD2112-

Special Nett

1SET BUMPER CLIP FRT	\$	95.00	50sm
1 FRONT NUMBER PLATE WITH MOULDING	\$	200.00	25sm
1SET CLIP, FRONT FENDER LINER	\$	85.00	✓
2 FENDER CLIP	\$	130.00	✓
2SET DOOR TRIM CLIP	\$	70.00	X
2SET DOOR WEATHERSTRIP CLIP	\$	130.00	X
1SET FRNT BUMPER RETAINER CLIP	\$	85.00	X
4L Radiator Coolant	\$	120.00	30sm
1 HOOD INSULATOR CLIP	\$	55.00	X
1 Engine Under Cover Clip	\$	60.00	X
2 DOOR STICKER 'TRANSCAB'	\$	200.00	60sm
TOTAL	\$	1,230.00	
TOTAL PARTS	\$	60,430.13	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	120l
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	1000l
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	480.00	80l
To transfer of Fender fittings, attachments and perform water seepage test.	\$	480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	100l

Trans-cab Auto Services Pte Ltd

AAD2112-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF642X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	?
To check steering geometry and computer wheel alignment	\$	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	120/
Towing Fees	\$	150.00	50/
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	1540/
To Check Electrical Lighting Concerned.	\$	170.00	30/
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	220.00	X
To replace, refix and top up coolant for radiator	\$	170.00	50/
To lift-up / out engine with gear box and refit.	\$	440.00	?
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	380.00	?
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	380.00	?
TOTAL	\$	9,560.00	

Over All Total \$ 69,990.13**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

(PART-BY-PART) Repair Days**25 DAYS****11 days**