

ASS. REG. BY:

REF:

TMI/

CC3/TMI21012517/Ktc

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

CO/TP/WS/TP RES/CO RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$71,171k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 71 days Res.: Yes or NoLum Sum: 131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHF 642X Yr Regn: 03, 21

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Pons c.c. 1798Colour: M.P. White 1st AC: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng No: _____

Ch No: JD KB 3FU 003 09 2045

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / RIM or

Tyre Size: F: Sailor 195/65R15R: Dun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 8 mm R/Bal. 2 mmL/Bal. P mm L/Bal. 2 mmD.O.A. 2 A2/21 D.O.I. 9/12/2021

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rt & Cls Ft

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Got BL, Botany Plat

input at report
 Book Value: 71,171.53
 LTA 31,766.00
 Nett Value 39,405.53

Date/Time, File Pass to?

☐: Prell. Report

1)

☐: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 11

Resurvey No. of Trlp: _____

Add Fee: ☐: Site Insp (\$)☐: Interview (\$)☐: Tech Invs (\$)☐: Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$)

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF642X

*Not Notified
Returning Bepain*

AAD2112-

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

09 DEC 2021

SHF642X

JTDKB3FU003092045

TOYOTA

PRIUS GEN 4

02/12/2021

TOKIO

12/03/2021

PART	LIST	
1 COVER, FRONT BUMPER	\$ R 521.00	—
1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$ DIT 110.50	—
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$ R 716.60	—
1 REINFORCEMENT, FRONT BUMPER, NO.2	\$ R 246.10	—
1 ABSORBER, FRONT BUMPER, LOWER	\$ CM 132.70	—
1 ABSORBER, FRONT BUMPER ENERGY	\$ CM 80.20	—
1 SUPPORT, FRONT BUMPER SIDE, RH	\$ DIT 80.10	—
1 SUPPORT, FRONT BUMPER SIDE, LH	\$ DIT 82.30	—
1 COVER, ENGINE UNDER, NO.1	\$ DIT 472.40	—
1 COVER SUB-ASSY, ENGINE UNDER, NO.2	\$ 241.90	?
1 EXTENSION, FRONT BUMPER, RH	\$ 120.10	?
1 EXTENSION, FRONT BUMPER, LH	\$ 120.10	?
1 MOULDING, FRONT BUMPER SIDE, LH	\$ R 95.60	X
1 MOULDING, FRONT BUMPER SIDE, RH	\$ CM 95.60	—
1 COVER, FRONT BUMPER HOLE, LH	\$ M/S 30.20	—
1 COVER, FRONT BUMPER HOLE, RH	\$ M/S 30.20	—
1 LAMP ASSY, FOG, LH	\$ 237.10	?
1 LAMP ASSY, FOG, RH	\$ 237.10	?
1 UNIT ASSY, HEADLAMP, LH	\$ Bn 2,637.60	—
1 COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$ 3,772.50	?
1 UNIT ASSY, HEADLAMP, RH	\$ CM 2,637.60	—
1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$ 3,772.50	?
1 GRILLE SUB-ASSY, RADIATOR	\$ CM 422.50	—
1 GRILLE, RADIATOR, LOWER NO.1	\$ CM 178.60	—
1 EMBLEM ASSY, RADIATOR GRILLE	\$ CM 105.80	—
1 SUPPORT, RADIATOR, UPPER RH	\$ DIT 78.90	—
1 SUPPORT, RADIATOR, UPPER LH	\$ DIT 78.90	—
1 SUPPORT SUB-ASSY, RADIATOR, UPPER	\$ R 377.10	—

Trans-cab Auto Services Pte Ltd**AAD2112-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF642X

1	SUPPORT SUB-ASSY, RADIATOR, LOWER	\$	409.90	?
1	SUPPORT SUB-ASSY, RADIATOR, LH	\$	R ₁ 245.10	✓
1	SUPPORT SUB-ASSY, RADIATOR, RH	\$	R ₁ 245.10	✓
1	HOOD SUB-ASSY	\$	B ₁ 983.10	✓
1	HINGE ASSY, HOOD, LH	\$	R ₁ 58.90	✓
1	HINGE ASSY, HOOD, RH	\$	R ₁ 58.90	✓
1	BRACE, HOOD LOCK SUPPORT	\$	Pi 1 78.30	✓
1	INSULATOR, HOOD	\$	Re turn 410.90	✓
1	LOCK ASSY, HOOD	\$	R ₁ 135.00	✓
1	SEAL, HOOD TO FRONT END PANEL	\$	R ₁ 85.50	✓
1	WIRE, ENGINE ROOM MAIN	\$	7,323.90	?
1	HORN ASSY, HIGH PITCHED	\$	134.80	?
1	HORN ASSY, LOW PITCHED	\$	134.80	?
1	GUIDE, RADIATOR AIR, NO.1 LH	\$	69.90	?
1	GUIDE, RADIATOR AIR, NO.1 RH	\$	65.30	?
1	GUIDE, RADIATOR AIR, NO.3	\$	112.70	?
1	GUIDE, RADIATOR AIR, NO.2	\$	53.40	?
1	SEAL, RADIATOR TO SUPPORT, NO.3	\$	32.40	?
1	SEAL, RADIATOR TO SUPPORT, NO.2	\$	32.60	?
1	INLET, AIR CLEANER, NO.1	\$	155.60	?
1	INLET, AIR CLEANER, NO.3	\$	42.10	?
1	INLET, AIR CLEANER, NO.2	\$	112.70	?
1	HOSE, AIR CLEANER, NO.1	\$	74.00	?
1	JAR ASSY, WINDSHIELD WASHER	\$	Re 219.10	✓
1	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$	292.40	?
1	INLET SUB-ASSY, WASHER	\$	67.00	?
1	CONDENSER ASSY, COOLER	\$	1,783.20	?
1	HOSE SUB-ASSY, SUCTION	\$	646.80	?
1	HOSE SUB-ASSY, DISCHARGE	\$	402.90	?
1	PIPE SUB-ASSY, SUCTION	\$	465.80	?
1	SENSOR, AIRCONDITIONER PRESSURE	\$	342.80	?
1	TUBE & ACCESSORY ASSY, AIR CONDITIONER	\$	691.00	?
1	COMPRESSOR ASSY, W/MOTOR	\$	Re 4,771.60	X
1	RADIATOR ASSY	\$	2,218.00	?
1	SHROUD, FAN	\$	264.70	?
1	FAN, RH	\$	281.30	?
1	FAN, LH	\$	219.10	?

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2112-**SHF642X**

1	MOTOR, COOLING FAN, LH	\$	655.10	?
1	MOTOR, COOLING FAN, RH	\$	535.50	?
1	TANK ASSY, INVERTER RESERVE	\$	443.00	?
1	INVERTER WATER PUMP ASSY(W/MOTOR)	\$	518.60	?
1	BATTERY	\$	<i>Ref</i> 1,584.90	✓
1	CLAMP, BATTERY, NO.2	\$	51.80	?
1	CLAMP SUB-ASSY, BATTERY	\$	115.50	?
1	TERMINAL, BATTERY POSITIVE	\$	58.10	?
1	COVER, FUSIBLE LINK	\$	33.90	?
1	SENSOR ASSY, BATTERY STATE	\$	306.10	?
1	BLOCK ASSY, FUSIBLE LINK	\$	119.60	?
1	TANK, RESERVE SEALED W/O CAP	\$	151.40	?
1	CLEANER ASSY, AIR	\$	1,147.00	?
1	BRACKET, HEADLAMP, LH	\$	<i>mt</i> 34.80	✓
1	BRACKET, HEADLAMP, RH	\$	34.80	?
1	STAY SUB-ASSY, FRONT BUMPER, LH	\$	47.50	?
1	STAY SUB-ASSY, FRONT BUMPER, RH	\$	47.50	?
1	BRACKET, FRONT BUMPER SIDE, LH	\$	59.30	?
1	BRACKET, FRONT BUMPER SIDE, RH	\$	59.30	?
1	BRACKET, RADIATOR GRILLE MOUNTING, LH	\$	36.60	?
1	BRACKET, RADIATOR GRILLE MOUNTING, RH	\$	36.60	?
1	MEMBER SUB-ASSY, FRONT SIDE, RH	\$	<i>R</i> 2,342.30	X
1	MEMBER SUB-ASSY, FRONT SIDE, LH	\$	<i>R</i> 2,342.30	X
1	COVER, RADIATOR SUPPORT OPENING	\$	<i>mt</i> 211.50	✓
1	ACTUATOR ASSY, SHIFT CONTROL	\$	1,036.40	?
1	COOLER, MOTOR COOLING	\$	297.20	?
1	MIRROR ASSY, OUTER REAR VIEW, RH	\$	<i>Ref/mt</i> 1,436.60	✓
1	COVER SUB-ASSY, FRONT PILLAR, UPR LH	\$	<i>mt</i> 100.40	✓
1	COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$	<i>mt</i> 100.40	✓
1	FENDER SUB-ASSY, FRONT RH	\$	<i>Bu</i> 977.80	✓
1	LINER, FRONT FENDER, RH	\$	<i>su</i> 202.50	X
1	EMBLEM, SIDE PANEL, RH	\$	<i>re</i> 54.60	✓
1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	<i>R</i> 1,300.70	X
1	LOCK ASSY, FRONT DOOR W/MOTOR, RH	\$	<i>R</i> 603.20	X
1	MOULDING, FRONT DOOR WINDOW FRAME, FRONT RH	\$	<i>su</i> 38.60	X
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$	<i>su</i> 193.50	X
1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	<i>su</i> 390.60	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2112-

SHF642X

1	MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$	P _h	926.00	
1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$	S _h	321.10	
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	H	110.60	
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	H	97.50	
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	P _h	238.30	
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	W _h	43.50	
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	W _h	13.30	
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	W _h	26.30	
1	FENDER SUB-ASSY, FRONT LH	\$	P _h	977.80	✓
1	LINER, FRONT FENDER, LH	\$	L _h	202.50	✓
1	EMBLEM, SIDE PANEL	\$	M	54.60	✓
1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	H	1,300.70	
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	\$	S _h	193.50	
1	HANDLE ASSY, FRONT DOOR OUTSIDE, LH	\$	S _h	390.60	
1	WEATHERSTRIP, FRONT DOOR, LH	\$	P _h	231.30	
1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	H	110.60	
1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	H	97.50	
1	TAPE, BLACK OUT, NO.1 FRT LH	\$	W _h	13.30	
1	TAPE, BLACK OUT, NO.2 FRT LH	\$	W _h	43.50	
1	TAPE, BLACK OUT, NO.3 FRT LH	\$	W _h	26.30	
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$	S _h	926.00	
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$	S _h	238.30	
1	COMPUTER ASSY, AIR BAG	\$	M	1,546.00	✓
1	SENSOR, AIR BAG, FRONT LH	\$	M	373.90	✓
1	SENSOR, AIR BAG, FRONT RH	\$	M	373.90	✓
1	AIR BAG ASSY, INSTRUMENT PANEL PASSENGER W/O DOOR	\$	Burn	3,869.30	✓
1	WHEEL ASSY, STEERING	\$		1,492.50	✓
1	BELT ASSY, FRONT SEAT OUTER, RH	\$	T _h	995.10	✓
1	BELT ASSY, FRONT SEAT OUTER, LH	\$	T _h	995.10	✓
1	BELT ASSY, REAR SEAT 3 POINT TYPE, OUTER LH	\$	T _h	995.10	✓
1	BELT ASSY, REAR SEAT 3 POINT TYPE, OUTER RH	\$	T _h	995.10	✓
1	GLASS, WINDSHIELD	\$	CM	1,576.50	✓

TOTAL	\$	78,933.50
25%	\$	19,733.38
	\$	59,200.13

Trans-cab Auto Services Pte Ltd

AAD2112-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF642X

Special Nett

1SET BUMPER CLIP FRT	\$	95.00	50sm
1 FRONT NUMBER PLATE WITH MOULDING	\$	200.00	25sm
1SET CLIP, FRONT FENDER LINER	\$	85.00	✓
2 FENDER CLIP	\$	130.00	✓
2SET DOOR TRIM CLIP	\$	70.00	X
2SET DOOR WEATHERSTRIP CLIP	\$	130.00	X
1SET FRNT BUMPER RETAINER CLIP	\$	85.00	X
4L Radiator Coolant	\$	120.00	30sm
1 HOOD INSULATOR CLIP	\$	55.00	X
1 Engine Under Cover Clip	\$	60.00	X
2 DOOR STICKER 'TRANSCAB'	\$	200.00	60sm
TOTAL	\$	1,230.00	
TOTAL PARTS	\$	60,430.13	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	120l
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	1000l
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	480.00	80l
To transfer of Fender fittings, attachments and perform water seepage test.	\$	480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	100l

Trans-cab Auto Services Pte Ltd

AAD2112-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF642X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	?
To check steering geometry and computer wheel alignment	\$	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	1201
Towing Fees	\$	150.00	501
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	15401
To Check Electrical Lighting Concerned.	\$	170.00	301
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	220.00	X
To replace, refix and top up coolant for radiator	\$	170.00	501
To lift-up / out engine with gear box and refit.	\$	440.00	?
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	380.00	?
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	380.00	?
TOTAL	\$	9,560.00	

Over All Total \$ 69,990.13**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

(PART-BY-PART) Repair Days**25 DAYS****11 days**

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	03/12/2021 16:22 (SGT)
Date of Accident	02/12/2021 20:00 (SGT)
Exact Location of Accident	Near Hougang Ave 3, Singapore
Additional Location Information	JUNCTION OF HOUGANG AVE 3 AND BARTLEY ROAD EAST
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF642X
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Company Reg No	2XXXXX878K
Email Address	claims@transcab.com.sg
Mobile Phone No	(Phone) +65-62876666
Alternative Phone No	(Office) +65-62876666

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1767

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	VFX/P2413997
Cover Note Number	

DRIVER

Name of Driver	SIM BENG HONG
NRIC No	SXXXX326I

Date Of Birth	23/07/1960
Occupation	Outdoor
Date Of Driving Pass	18/01/1978
Driving experience	43 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-88661631
Alt. Phone Number	-
Email Address	claims@transcab.com.sg
Address	2 EUNOS CRES
Address complement	#07-2575
Postcode	400002
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Cross Junction
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	YIP WAI PO
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT


REFER TO POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	SD CARD WITH TP
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF6790H
-----------------------------	----------



~~X~~

VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
WONG JUN KEAT

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



1202112032021

2 of 4

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No: T/20211203/2621

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAN AH CHUAN	ID No.	S1628465C
Related Vehicle	GBF6790H (Van)	Contact No.	96270050
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	SIM BENG HONG	ID No.	S14393261
Related Vehicle	SHF642X (Car)	Contact No.	88661631
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B, 2A, 2, 3, 4, 5 Date of Expiry: NIL
Date Treatment	02/12/2021	Date Discharge	02/12/2021
No. of Days granted Medical Leave	05	Degree of Injury	NIL
Passenger			
Name	YIP WAI PO	ID No.	S8685776F
Related Vehicle	SHF642X (Car)	Contact No.	88073234
Hospital/Clinic	CHANGI GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE STATED DATE TIME AND LOCATION,

I WAS AT THE JUNCTION OF HOUGANG AVE 3 TWDS BARTLEY ROAD EAST. I BELIEVE THAT I WAS AT THE SECOND LANE OF A 4 LANE ROAD. I WAS PROCEEDING STRAIGHT AS MY TRAFFIC LIGHT TURN GREEN. I CHECKED MY SURROUNDING AND SO FAR THERE IS NO UPCOMING VEHICLE AHEAD. AFTER I CROSS THE WHITE LINE, SUDDENLY A VEHICLE(GBF6790H) WAS IN FRONT OF ME. I COULD NOT STOPPED IN TIME SO I COULDED WITH THE STATED VEHICLE. AFTER THE ACCIDENT HAPPENED, MY PASSENGER INFO ME THAT HE IS INJURED. I QUICKLY