

SINGA

STANT
se re
Fo

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHF642X

*Not Notified
Returning B4paim*

AAD2112-

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident:
Third Party Insurer:
Date of Registration:

09 DEC 2021

SHF642X

JTDKB3FU003092045

TOYOTA

PRIUS GEN 4

02/12/2021

TOKIO

12/03/2021

PART	LIST
1 COVER, FRONT BUMPER	\$ A ₁ 521.00 ✓
1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$ D ₁ 110.50 ✓
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$ B ₁ 716.60 ✓
1 REINFORCEMENT, FRONT BUMPER, NO.2	\$ B ₂ 246.10 ✓
1 ABSORBER, FRONT BUMPER, LOWER	\$ C _M 132.70 ✓
1 ABSORBER, FRONT BUMPER ENERGY	\$ C _M 80.20 ✓
1 SUPPORT, FRONT BUMPER SIDE, RH	\$ D ₁ 80.10 ✓
1 SUPPORT, FRONT BUMPER SIDE, LH	\$ D ₁ 82.30 ✓
1 COVER, ENGINE UNDER, NO.1	\$ D ₁ 472.40 ✓
1 COVER SUB-ASSY, ENGINE UNDER, NO.2	\$ S ₁ 241.90 ✓
1 EXTENSION, FRONT BUMPER, RH	\$ R ₁ 120.10 ✓
1 EXTENSION, FRONT BUMPER, LH	\$ R ₁ 120.10 ✓
1 MOULDING, FRONT BUMPER SIDE, LH	\$ S ₁ 95.60 X
1 MOULDING, FRONT BUMPER SIDE, RH	\$ C _M 95.60 ✓
1 COVER, FRONT BUMPER HOLE, LH	\$ M ₁ 30.20 ✓
1 COVER, FRONT BUMPER HOLE, RH	\$ M ₁ 30.20 ✓
1 LAMP ASSY, FOG, LH	\$ M ₁ 237.10 ✓
1 LAMP ASSY, FOG, RH	\$ M ₁ 237.10 ✓
1 UNIT ASSY, HEADLAMP, LH	\$ B ₁ 2,637.60 ✓
1 COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$ R ₁ 3,772.50 ✓
1 UNIT ASSY, HEADLAMP, RH	\$ C _M 2,637.60 ✓
1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$ R ₁ 3,772.50 ✓
1 GRILLE SUB-ASSY, RADIATOR	\$ C _M 422.50 ✓
1 GRILLE, RADIATOR, LOWER NO.1	\$ C _M 178.60 ✓
1 EMBLEM ASSY, RADIATOR GRILLE	\$ C _M 105.80 ✓
1 SUPPORT, RADIATOR, UPPER RH	\$ D ₁ 78.90 ✓
1 SUPPORT, RADIATOR, UPPER LH	\$ D ₁ 78.90 ✓
1 SUPPORT SUB-ASSY, RADIATOR, UPPER	\$ B ₁ 377.10 ✓

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2112-

SHF642X

1	SUPPORT SUB-ASSY, RADIATOR, LOWER	\$	R1	409.90	✓
1	SUPPORT SUB-ASSY, RADIATOR, LH	\$	R2	245.10	✓
1	SUPPORT SUB-ASSY, RADIATOR, RH	\$	R1	245.10	✓
1	HOOD SUB-ASSY	\$	R1	983.10	✓
1	HINGE ASSY, HOOD, LH	\$	R1	58.90	✓
1	HINGE ASSY, HOOD, RH	\$	R1	58.90	✓
1	BRACE, HOOD LOCK SUPPORT	\$	R1	78.30	✓
1	INSULATOR, HOOD	\$	Return	410.90	✓
1	LOCK ASSY, HOOD	\$	R1	135.00	✓
1	SEAL, HOOD TO FRONT END PANEL	\$	R1	85.50	✓
1	WIRE, ENGINE ROOM MAIN	\$	CRU/TA	7,323.90	✓
1	HORN ASSY, HIGH PITCHED	\$	SM	134.80	X
1	HORN ASSY, LOW PITCHED	\$	SM	134.80	X
1	GUIDE, RADIATOR AIR, NO.1 LH	\$	CM	69.90	✓
1	GUIDE, RADIATOR AIR, NO.1 RH	\$	CM	65.30	✓
1	GUIDE, RADIATOR AIR, NO.3	\$	SM	112.70	X
1	GUIDE, RADIATOR AIR, NO.2	\$	SM	53.40	X
1	SEAL, RADIATOR TO SUPPORT, NO.3	\$	SM	32.40	X
1	SEAL, RADIATOR TO SUPPORT, NO.2	\$	SM	32.60	X
1	INLET, AIR CLEANER, NO.1	\$	SM	155.60	X
1	INLET, AIR CLEANER, NO.3	\$	SM	42.10	X
1	INLET, AIR CLEANER, NO.2	\$	SM	112.70	X
1	HOSE, AIR CLEANER, NO.1	\$	SM	74.00	X
1	JAR ASSY, WINDSHIELD WASHER	\$	NO	219.10	✓
1	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$	NO	292.40	✓
1	INLET SUB-ASSY, WASHER	\$	SM	67.00	X
1	CONDENSER ASSY, COOLER	\$	R1	1,783.20	✓
1	HOSE SUB-ASSY, SUCTION	\$	SM	646.80	X
1	HOSE SUB-ASSY, DISCHARGE	\$	SM	402.90	X
1	PIPE SUB-ASSY, SUCTION	\$	SM	465.80	X
1	SENSOR, AIRCONDITIONER PRESSURE	\$	SM	342.80	X
1	TUBE & ACCESSORY ASSY, AIR CONDITIONER	\$	SM	691.00	X
1	COMPRESSOR ASSY, W/MOTOR	\$	SM	4,771.60	X
1	RADIATOR ASSY	\$	R1	2,218.00	✓
1	SHROUD, FAN	\$	CM	264.70	✓
1	FAN, RH	\$	CM	281.30	✓
1	FAN, LH	\$	CM	219.10	✓

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2112-

SHF642X

1	MOTOR, COOLING FAN, LH	\$	CMA	655.10	✓
1	MOTOR, COOLING FAN, RH	\$	CM	535.50	✓
1	TANK ASSY, INVERTER RESERVE	\$	Sn	443.00	✓
1	INVERTER WATER PUMP ASSY(W/MOTOR)	\$	Sn	518.60	✓
1	BATTERY	\$	Nd	1,584.90	✓
1	CLAMP, BATTERY, NO.2	\$	Sn	51.80	✓
1	CLAMP SUB-ASSY, BATTERY	\$	Sn	115.50	✓
1	TERMINAL, BATTERY POSITIVE	\$	Sn	58.10	✓
1	COVER, FUSIBLE LINK	\$	Sn	33.90	✓
1	SENSOR ASSY, BATTERY STATE	\$	Sn	306.10	✓
1	BLOCK ASSY, FUSIBLE LINK	\$	Sn	119.60	✓
1	TANK, RESERVE SEALED W/O CAP	\$	Sn	151.40	✓
1	CLEANER ASSY, AIR	\$	Sn	1,147.00	✓
1	BRACKET, HEADLAMP, LH	\$	Mr	34.80	✓
1	BRACKET, HEADLAMP, RH	\$	Sn	34.80	✓
1	STAY SUB-ASSY, FRONT BUMPER, LH	\$	N	47.50	✓
1	STAY SUB-ASSY, FRONT BUMPER, RH	\$	N	47.50	✓
1	BRACKET, FRONT BUMPER SIDE, LH	\$	N	59.30	✓
1	BRACKET, FRONT BUMPER SIDE, RH	\$	N	59.30	✓
1	BRACKET, RADIATOR GRILLE MOUNTING, LH	\$	Sn	36.60	✓
1	BRACKET, RADIATOR GRILLE MOUNTING, RH	\$	Sn	36.60	✓
1	MEMBER SUB-ASSY, FRONT SIDE, RH	\$	N	2,342.30	✓
1	MEMBER SUB-ASSY, FRONT SIDE, LH	\$	N	2,342.30	✓
1	COVER, RADIATOR SUPPORT OPENING	\$	Mr	211.50	✓
1	ACTUATOR ASSY, SHIFT CONTROL	\$	Sn	1,036.40	✓
1	COOLER, MOTOR COOLING	\$	Sn	297.20	✓
1	MIRROR ASSY, OUTER REAR VIEW, RH	\$	Nd/Bu	1,436.60	✓
1	COVER SUB-ASSY, FRONT PILLAR, UPR LH	\$	Mr	100.40	✓
1	COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$	Mr	100.40	✓
1	FENDER SUB-ASSY, FRONT RH	\$	Bu	977.80	✓
1	LINER, FRONT FENDER, RH	\$	Sn	202.50	✓
1	EMBLEM, SIDE PANEL, RH	\$	N	54.60	✓
1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	N	1,300.70	✓
1	LOCK ASSY, FRONT DOOR W/MOTOR, RH	\$	N	603.20	✓
1	MOULDING, FRONT DOOR WINDOW FRAME, FRONT RH	\$	Sn	38.60	✓
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$	Sn	193.50	✓
1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	Sn	390.60	✓

Lump Sum / I.B.I: (\$

☐ Weekend (\$

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2112-

SHF642X

1	MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$	P ₂	926.00	
1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$	S ₂	321.10	
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	H	110.60	
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	H	97.50	
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	P ₂	238.30	
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	U ₂	43.50	
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	U ₂	13.30	
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	U ₂	26.30	
1	FENDER SUB-ASSY, FRONT LH	\$	B ₂	977.80	✓
1	LINER, FRONT FENDER, LH	\$	D ₁	202.50	✓
1	EMBLEM, SIDE PANEL	\$	U ₂	54.60	✓
1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	H	1,300.70	
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	\$	S ₂	193.50	
1	HANDLE ASSY, FRONT DOOR OUTSIDE, LH	\$	S ₂	390.60	
1	WEATHERSTRIP, FRONT DOOR, LH	\$	P ₂	231.30	
1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	H	110.60	
1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	H	97.50	
1	TAPE, BLACK OUT, NO.1 FRT LH	\$	U ₂	13.30	
1	TAPE, BLACK OUT, NO.2 FRT LH	\$	U ₂	43.50	
1	TAPE, BLACK OUT, NO.3 FRT LH	\$	U ₂	26.30	
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$	P ₂	926.00	
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$	S ₂	238.30	
1	COMPUTER ASSY, AIR BAG	\$	U ₂	1,546.00	✓
1	SENSOR, AIR BAG, FRONT LH	\$	U ₂	373.90	✓
1	SENSOR, AIR BAG, FRONT RH	\$	U ₂	373.90	✓
1	AIR BAG ASSY, INSTRUMENT PANEL PASSENGER W/O DOOR	\$	B ₂	3,869.30	✓
1	WHEEL ASSY, STEERING	\$	P ₂	1,492.50	X
1	BELT ASSY, FRONT SEAT OUTER, RH	\$	J ₂	995.10	✓
1	BELT ASSY, FRONT SEAT OUTER, LH	\$	J ₂	995.10	✓
1	BELT ASSY, REAR SEAT 3 POINT TYPE, OUTER LH	\$	J ₂	995.10	✓
1	BELT ASSY, REAR SEAT 3 POINT TYPE, OUTER RH	\$	J ₂	995.10	✓
1	GLASS, WINDSHIELD	\$	CM	1,576.50	✓

TOTAL	\$	78,933.50
25%	\$	19,733.38
	\$	59,200.13

Lump Sum / I.B.I: (\$

☐ Weekend (\$

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2112-

SHF642X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn	380.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$		250.00	120/
Towing Fees	\$		150.00	50/
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	1540/
To Check Electrical Lighting Concerned.	\$		170.00	30/
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn	220.00	X
To replace, refix and top up coolant for radiator	\$		170.00	50/
To lift-up / out engine with gear box and refit.	\$	nn	440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	nn	380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	nn	380.00	X
TOTAL	\$		9,560.00	

Over All Total \$ 69,990.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

(PART-BY-PART) Repair Days

25 DAYS

11 days

Lump Sum / I.B.I: (\$

☐ Weekend (\$

Others

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF642X

AAD2112-

Special Nett

1SET BUMPER CLIP FRT	\$	nn	95.00	501n
1 FRONT NUMBER PLATE WITH MOULDING	\$	B	200.00	455n
1SET CLIP, FRONT FENDER LINER	\$	nn	85.00	✓
2 FENDER CLIP	\$	nn	130.00	✓
2SET DOOR TRIM CLIP	\$	nn	70.00	X
2SET DOOR WEATHERSTRIP CLIP	\$	nn	130.00	X
1SET FRNT BUMPER RETAINER CLIP	\$	nn	85.00	X
4L Radiator Coolant	\$	nec	120.00	301n
1 HOOD INSULATOR CLIP	\$	nn	55.00	X
1 Engine Under Cover Clip	\$	nn	60.00	X
2 DOOR STICKER 'TRANSCAB'	\$	nn	200.00	601n
TOTAL	\$		1,230.00	

TOTAL PARTS \$ 60,430.13**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$		300.00	1201
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,200.00	10001
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$		480.00	801
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn	480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$		380.00	1001

Lump Sum / I.B.I: (\$

☐ Weekend (\$

TOTAL