

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9070Y*Not Authorized* AAD2111-*11 Pay \$ 4300/-*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

09 DEC 2021**SHD9070Y**

JTDKB3FU903076118

TOYOTA

PRIUS

01/12/2021

Tokio

01/11/2018

PART	LIST
1 PANEL SUB-ASSY, FRONT DOOR, RH	\$ <i>R</i> 1,300.70 X
1 FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$ <i>Sn</i> 193.50
1 HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$ <i>Sn</i> 390.60
1 HINGE ASSY, FRONT DOOR, LOWER RH	\$ <i>Rm</i> 110.60
1 HINGE ASSY, FRONT DOOR, UPPER RH	\$ <i>R</i> 97.50
1 TAPE, BLACK OUT, NO.1 FRT RH	\$ <i>Rm</i> 13.30
1 TAPE, BLACK OUT, NO.2 FRT RH	\$ <i>Rm</i> 43.50
1 TAPE, BLACK OUT, NO.3 FRT RH	\$ <i>Rm</i> 26.30
1 MOTOR ASSY, POWER WINDOW REGULATOR, FRT RH	\$ <i>Sn</i> 926.00
1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$ <i>Sn</i> 238.30
1 WEATHERSTRIP, FRONT DOOR, RH	\$ <i>Sn</i> 231.30
1 PANEL SUB-ASSY, REAR DOOR, RH	\$ <i>R</i> 1,294.90 ✓
1 HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$ <i>Sn</i> 97.40 X
1 FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$ <i>Sn</i> 193.50 X
1 HINGE ASSY, REAR DOOR, LOWER RH	\$ <i>R</i> 87.10 X
1 HINGE ASSY, REAR DOOR, UPPER LH	\$ <i>R</i> 98.90 X
1 TAPE, BLACK OUT, NO.1 REAR RH	\$ <i>Rm</i> 21.90 —
1 TAPE, BLACK OUT, NO.2 REAR RH	\$ <i>Rm</i> 34.90 —
1 TAPE, BLACK OUT, NO.3 REAR RH	\$ <i>Rm</i> 15.40 —
1 MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$ <i>Tz</i> 926.00 —
1 REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$ <i>R</i> 206.70 —
1 WEATHERSTRIP, REAR DOOR, RH	\$ <i>Sn</i> 180.10 X
1 PANEL SUB-ASSY, QUARTER, RH	\$ <i>R</i> 871.50 ✓
1 LINER, REAR WHEEL HOUSE, RH	\$ <i>Sn</i> 139.80 X
1 MOULDING ASSY, BODY ROCKER PANEL, RH	\$ <i>Bu</i> 594.80 ✓
1 REINFORCEMENT SUB-ASSY, ROCKER PANEL, RH	\$ <i>R</i> 343.40 X
TOTAL	\$ 6,728.40
25%	\$ 1,682.10

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9070Y**AAD2111-**

\$	5,046.30
----	----------

Special Nett

1	CLIP(FOR FRONT DOOR TRIM BOARD)	\$	nn	65.00	X
1	CLIP(FOR REAR DOOR TRIM BOARD)	\$	nn	65.00	X
1	REAR DOOR STICKER "6555-3333"	\$	nn	100.00	6555-3333
1	FRT DOOR STICKER 'TRANSCAB'	\$	nn	100.00	6555-3333
1	FENDER LINER CLIP	\$	nn	65.00	X
1	ROCKER PANEL CLIP	\$	nn	65.00	—

TOTAL	\$	330.00
--------------	----	---------------

TOTAL PARTS	\$	5,376.30
--------------------	----	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	601
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	8801
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	1001
To Check Electrical Lighting Concerned.	\$	170.00	201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,800.00	9001
To check steering geometry and computer wheel alignment	\$	220.00	601
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	nn	170.00 X
TOTAL	\$	4,790.00	

Over All Total	\$	10,166.30
-----------------------	----	------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

(PART-BY-PART) Repair Days20 Days
8 days

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

AAD2112-006

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9070Y

Vehicle No.:

SHD9070Y

Chassis No.:

JTDKB3FU903076118

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS

Date of Accident :

01/12/2021

Third Party Insurer :

TOKIO

Date of Registration:

01/11/2018

SUPPLEMENTARY

PART

LIST

1 COVER, FLOOR UNDER, NO.2 (RH)

\$ *Dis/lem* 241.90 ✓

TOTAL \$ 241.90

25% \$ 60.48

\$ 181.43