


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SL29K8J
 at Workshop m/s: 7K
 of _____
 Insured: SLU4235K
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: \$68k.
 IDAC Accident Report: Consistent? Yes or No
 GIA / PR Seen: Consistent? Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: Dep 60k.

Veh No: SL29K8J Yr Regn: 23/15/18
 Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: Handg Shuttle Hybrid 1496
 Colour: Red A/C: Insured / Std / NI / NA
 Sp.Reading: 220260 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: GP71208327
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/60 R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Falken

Front _____ Rear _____
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 8/1/14 D.O.I. 10/1/14
 Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No 31 LTA 28579v/s from board n/c1/5 \$5800 informed AH Keung.AH Keung HP: 96273323

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp (\$)) S + RS \$☐ Interview (\$)

) Photos

☐ Tech. Invs (\$)

) Others

☐ Weekend (\$)

)

Report Format:

Lump Sum / I.B.I. (\$) _____)

TOTAL

T K MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56

SINGAPORE 417883

TEL : 96279323 FAX 68442641

CO.REG NO: 53049097-L

* Jaslin

not Arthur
Lm

10/12/21

2/5 @ 5800

6 days

SEAH KAR KHENG JULIAN

DATE : 16/12/2021

BLK 19, JALAN TENTERAM, #21-138

SINGAPORE 321019

ACCIDENT DATE : 08/12/2021

MODEL : HONDA SHUTTLE

CHASSIS NO. : GP71208327

ESTIMATE COST OF REPAIR BILL TO HONDA CAR NO. : SLZ9498J

1 PC REAR BOOTLID	Body	SS\$1,193.60	✓
1 PC REAR BOOTLID LOCK	Brk/Struck	186.90	✓
1 PC REAR BOOTLID RUBBER	Trl	168.50	✓
2 PC REAR BOOTLID EMBLEM	SS.40	120.70	✓
1 PC REAR BOOTLID "H" EMBLEM	120.70	27.40	✓
2 PC REAR BOOTLID ASBORBER	120.70	353.40	X
2 PC REAR BOOTLID REFLECTOR LAMP	120.70	681.60	X
1 PC REAR BOOTLID INNER TRIMBOARD	320.40	388.90	✓
1 PC REAR BOOTLID INNER HANDLE GARNISH	120.70	25.60	X
1 PC REAR BOOTLID CHROME MOULDING & GARNISH	120.70	383.10	X
1 PC REAR WINDSCREEN MOULDING	148.20	153.80	✓
1 PC REAR WINDSCREEN SEALANT	148.20	45.00 S/N	40 S/N
1 PC REAR WINDSCREEN INNER SEAL	148.20	26.00 S/N	✓ S/N

T K MOTOR WORKSHOP

(202)

ESTIMATE COST OF REPAIR BILL TO HONDA CAR NO.: SLZ9498J

2 PC REAR TAILLAMP	CN	\$S1,021.00 ✓
4 PC REAR TAILLAMP CLIPS	11	16.80 X
2 PC REAR FENDER INNER TRIMBOARD	2/san 394.10 MS Torn	911.60 1/2 C
1 PC REAR END PANEL	580.20 Subj	560.50 //
1 PC REAR END PANEL GARNISH	7m	138.60 //
1 PC REAR END PANEL LOCK striker	11	37.60 X
1 PC REAR SPARE WHEEL PANEL	R	956.40 X
1 PC REAR SPARE WHEEL PANEL COMPARTMENT GARNISH	7m	380.60 ✓
1 PC REAR SPARE WHEEL PANEL COMPARTMENT SPONGE	NS	265.20 X
1 PC REAR SPARE WHEEL PANEL TOP COVER GARNISH	waged	327.80 ✓
1 PC REAR BUMPER	936.50 DS	1,150.60 ✓
1 SET REAR REVERSE SENSOR	skid	200.00 S/N ✓ s/n
1 PC REAR REVERSE CAMERA	207 11	380.00 S/N X
8 PC REAR BUMPER CLIPS	11	31.20 —
2 PC REAR BUMPER SIDE RETAINER	501	57.20 —
2 PC REAR BUMPER REFLECTOR	one/ 7m	91.60 //
2 PC REAR BUMPER REFLECTOR COVER GARNISH	7m	93.60 //
2 PC REAR BUMPER REFLECTOR INNER SPONGE	Torn	112.80 —
1 PC REAR NO. PLATE	11	26.00 S/N X
1 PC REAR NO. PLATE COVER	11	20.00 S/N X

T K MOTOR WORKSHOP

Authorized Signature

SINGAPORE 417883

TEL: 96273323 FAX 68442641

CO.REG NO: 53049097-L

ESTIMATE COST OF REPAIR BILL TO HONDA CAR NO. : SLZ9498J

LABOUR CHARGE

TO CHECK WIRING	20	\$550.00
TO SPRAY PAINTING (PEARL RED)	900	1,200.00
TO REMOVE & REFIX REAR WINDSCREEN	120	150.00
TO REMOVE & REFIX REAR INTERIOR UPHOLSTERY	✓	80.00
TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION	60	80.00
TO MEASURE & DRILL REAR BUMPER, POSITION & INSTALL REAR REVERSE SENSOR, REAR CAMERA, CONTROL UNIT, CHECK & TEST FOR FUNCTIONING	50	80.00
TO PANEL BEATING, WELDING, REMOVE ALL DAMAGE PARTS & REPLACING OF THE NEW PARTS ETC.	800	900.00

TOTAL : \$513,073.60

TK MOTOR WORKSHOP



TK Auto Consultants hereby notify the Repairer of the following:

- To remove damaged parts during recovery
- Parts prices are subject to confirmation
- Third-party survey is on a "Without Prejudice" basis
- No legal modification is allowed
- Supplementary benefit is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____