



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 19700288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 39648

INDIA INTERNATIONAL INSURANCE P.L.
64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711
ATTN: MOTOR CLAIMS DEPT

DATE : 07/12/2021
CLAIM NO. : 11829
POLICY NO. : D-21097290MFCE/117

FROM : RAYMOND

VEHICLE NO. : FBR7473D
MAKE/MODEL : HON / NC750X

(Page 1 of 5)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER HANDLE P/N: 40187 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$32.00	32.00
2	BAR HANDLE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$266.00	266.00
3	BOLT (PLASTIC) P/N: 22353 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$4.50	9.00
4	BOX SIDE (GIVI) E22N (BLACK) P/N: 49418 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$388.00	388.00
5	BRACKET HOLDER FIRE EXTINGUISHER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$84.00	84.00
6	BRACKET HOLDER SIDE BOX REAR LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00
7	BRACKET HOLDER SIDE BOX REAR RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00
8	BRACKET LED XT12 PEDESTAL MOUNT WITH KIT P/N: 62717 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$65.00	65.00
9	BRACKET MUDGUARD REAR P/N: 66744 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$143.00	143.00

*39648 *

bizSAFE₃



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
10	BRACKET SIDE BOX (E21NC) P/N: 42174 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$205.00	205.00
11	BRACKET SIDE BOX SUPPORT P/N: 71745 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$128.00	128.00
12	CAP MASTER CYLINDER FRONT P/N: 45603 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
13	CASE CHAIN P/N: 57620 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$124.00	124.00
14	CLAMP EXTENDER BAR HANDLE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00
15	COLLAR COVER WHEEL FRONT - (REPORTED BY MECHANIC)	REPLACE	2.00	\$6.50	13.00
16	COVER MUFFLER P/N: 58549 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$220.00	220.00
17	COVER TAIL LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$298.00	298.00
18	COVER TAIL RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$298.00	298.00
19	CRASH BAR FRONT LH (CISCO) P/N: 70597 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$135.00	135.00
20	CRASH BAR LEG FRONT LH (CISCO) P/N: 70599 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$88.00	88.00
21	CRASH BAR LEG FRONT RH (CISCO) P/N: 70600 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$88.00	88.00
22	CRASH BAR REAR LH (CISCO) P/N: 70601 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$132.00	132.00
23	CRASH BAR REAR RH (CISCO) P/N: 70602 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$132.00	132.00
24	FENDER REAR B P/N: 57702 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$372.00	372.00

*39648 *

bizSAFE₃

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
25	GASKET MUFFLER P/N: 61399 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$26.00	26.00
26	GRIP RAIL RH P/N: 57696 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$352.00	352.00
27	GUARD ENGINE P/N: 66969 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$296.00	296.00
28	HOLDER STEP LH P/N: 57701 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$570.00	570.00
29	HOLDER STEP RH P/N: 57714 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$570.00	570.00
30	LABEL CHAIN ADJUSTER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$26.00	26.00
31	LABEL TIRE & DRIVE CHAIN - (REPORTED BY MECHANIC)	REPLACE	1.00	\$26.00	26.00
32	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	24.00	\$63.00	1,512.00
33	LAMP SIGNAL REAR LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$182.00	182.00
34	LAMP SIGNAL REAR RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$182.00	182.00
35	LEVER CLUTCH P/N: 65115 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$54.00	54.00
36	LIGHT LED (JL) 12 LED RED / BLUE WITH CLEAR LENS P/N: 62716 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$415.00	415.00
37	LIGHT LED (JL) 8 LED RED LENS WITH TELESCOPIC POLE P/N: 67025 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$705.00	705.00
38	MIRROR LH P/N: 57708 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$145.00	145.00
39	MUDGUARD REAR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$117.00	117.00

*39648 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
40	MUFFLER COMP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$808.00	808.00
41	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
42	REPAIR ON BODY ALIGNMENT - (REPORTED BY MECHANIC)	Repair	1.00	\$490.00	490.00
43	RIVET P/N: 29942 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$6.00	12.00
44	RUBBER MOUNT LAMP SIGNAL LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00	22.00
45	RUBBER MOUNT LAMP SIGNAL RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00	22.00
46	STICKER (CERTIS CISCO) WINDSHIELD P/N: 67401 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	55.00
47	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00
48	SWINGARM SUB ASSY P/N: 58570 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2,405.00	2,405.00
49	SWITCH (JL) SIREN REMOTE P/N: 66584 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$110.00	110.00
50	TRANSPORT CHARGES (MOTORCYCLE) OVERSIZED P/N: 45837 - BIKE TOWED BACK TO BHH		1.00	\$90.00	90.00
51	WASHER PLAIN 6MM - (REPORTED BY MECHANIC)	REPLACE	3.00	\$6.50	19.50
52	WHEEL SUB REAR P/N: 57718 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,486.00	1,486.00
53	WINDSHIELD - CLEAR (PUIG) P/N: 67016 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$210.00	210.00

SUB TOTAL

\$14,316.50

GST @ 7 %

\$1,002.16

GRAND TOTAL (SGD)

\$15,318.66

*39648 *



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------

50% deposit required before ordering of parts.					
--	--	--	--	--	--

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*39648 *

bizSAFE₃

Vehicle Details

Vehicle No.	Make / Model
FBR7473D	HONDA / NC750XA
Vehicle Type :	Vehicle Attachment 1 :
P00 - Passenger Motorcycle/Autocycle /Moped	No Attachment
Vehicle Scheme :	Chassis No. :
Normal	JH2RC90A8KK302596
Propellant :	Engine No. :
Petrol	RC88E5203230
Motor No. :	Engine Capacity :
-	745 cc
Power Rating :	Maximum Power Output :
-	-
Maximum Laden Weight :	Unladen Weight :
429 kg	220 kg
Year Of Manufacture :	Original Registration Date :
2019	12 Oct 2020
Lifespan Expiry Date :	COE Category :
-	D - Motorcycle
Quota Premium :	COE Expiry Date :
\$7,702.00	11 Oct 2030
Road Tax Expiry Date :	PARF Eligibility Expiry Date :
11 Apr 2022	-
Inspection Due Date :	Intended Transfer Date :
11 Oct 2023	13 Dec 2021
CO2 Emission :	CEV/VES Rebate Utilised Amount :
-	-
CO Emission :	HC Emission :

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 10 Dec 2021 / 12:13:35

Receipt Date/Time : 10 Dec 2021 / 12:13:35

Tax Invoice/Receipt

Receipt No. : ITNET-00000-211210-001538

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Result of Insurance Enquiry - XE2706Z				
As at 05 Dec 2021/21:15:00				
Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - XE2706Z Enquiry Fee 20211210121055580281	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
421808XXXXXX7159		eNETS Credit Card		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

[> Back to OneMotoring](#)

Enquire Vehicle's Insurance Particulars

Thank You!

The insurance details of the vehicle you enquired can be found below. If you have entered a valid email address, a copy would have been sent to you.

Vehicle No.	Incident Date/Time	Insurance Company Name
XE2706Z	05 Dec 2021 / 21:15:00	INDIA INT'L INS PTE LTD

[Save as PDF](#)[OK →](#)[Print](#)