

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT SOMPO INSURANCE SINGAPORE PL CS3/SMO21012535/Atf3e2 Ref: 50 RAFFLES PLACE #03-03 SINGAPORE LAND 18/01/2022 Date: **TOWER SINGAPORE 048623** Code: SMO 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **GBC 8180X** GBD 7972D Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. CMTD2103579/LOR Excess (\$) 0.00 **Assign Date** GRACE TEO 10/12/2021 Assign From **Vehicle Particulars & Condition** 2. NISSAN NV200 1461 Make & Model C.C HIDDEN 2015 Engine No. Year of Reg. VSKYBAM20Z0094579 WHITE Chassis No. Colour 160422 KM Odometer Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 175/70 R14C **GOODYEAR** 6 mm 175/70 R14C L/H Front Tyre **GOODYEAR** 6 mm 175/70 R14C GOODYEAR R/H Rear Tyre 6 mm 175/70 R14C GOODYEAR L/H Rear Tyre 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. 5. **General Information** 03/12/2021 Inspect Date / Time 23/12/2021 (11:24 AM) Accident Date HUP HUP WORKSHOP PTE LTD Survey held at 27-A JURONG PORT ROAD #01-29 SINGAPORE 619101 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500-\$5,500

Report Ref No. CS3/SMO21012535/Atf3e2

Estimate Days of Repair

Inspected By

5b.

ADRIAN LING WAI PING

K.K.LAU CPT(RET)

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

ESTIMATED NORMAL PERIOD FOR REPAIR:

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

7 Working Days

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.