

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLR 89285at Workshop m/s Koh motor

of _____

Insured: GAC 2818E

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 490

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: Rep 1316

Date / Time Action / Instruction

LTAS 50449Veh No: SLR 89285Yr Regn: 30/8/17Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Honda00yssey

c.c

2358Colour: silver

A/C:

Insured / Std / NI / NA

Sp. Reading: 56161

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMRC1880HC203488Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: _____

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 10/1/21D.O.I. 13/1/21

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rear w/screen shorted &The U/C Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS. SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

) TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$) _____

TOTAL

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	851B
Vehicle Details	
Vehicle No.:	SLR89255
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Dec 2021
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EX-S CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	K24W72041132
Chassis No.:	JHMRC1880HC203488
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$27,932.00
Original Registration Date:	30 Aug 2017
First Registration Date:	30 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$31,105.00 <i>1555-2</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2027
PARF Rebate Amount:	\$23,328.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,501.00
COE Rebate Amount:	\$27,121.00
Total Rebate Amount:	\$50,449.00

The information contained herein is correct as at 13 Dec 2021

OK

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum


OPEL YEAR END SALE


INSIGNIA
\$139,500*


CROSSLAND GS
\$99,500*



ENJOY GUARANTEED DISCOUNT OF UP TO \$13,000!

Post an Advertisement

Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2021 Toyota Hiace 2.0A Petrol \$60800



Easy Loan Approval. View Now.
 Up to 100% Loan. High Trade-In
 Offered To Your Veh
 Think One Automobile StarAd



Browse by Category ▾

Sort by Date Posted ▾ 20

13 vehicles



Honda Odyssey

Advanced Search



Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Search Selection

Honda Odyssey

Any

Any

2017

Any

Any

Any



Honda Odyssey 2.4A EX-S 8-Seater

\$95,800**\$14,050 /yr****29-Aug-2017****2,356 cc****18,000 km****MPV**

One Owner, Super Low Mileage, Full Service Records By Kah Motors, 5 Years Warranty, Accident Free, Excellent Condition. 8 Seater 2-3-3 Seat Configuration, Ideal For Extended Family, Luxurious Interior Paneling, View To Appreciate.

Posted: 12-Dec-2021

Tags: 2017 Honda Odyssey, Honda Odyssey, Honda, Odyssey



Honda Odyssey 2.4A EXV-S Sunroof

\$101,800**\$14,090 /yr****18-Dec-2017****2,356 cc****52,000 km****MPV**

Pristine Condition! Full Service By Agent! 1 Owner Only! 100% Loan Available With Lowest Interest Rate From 1.88% Per Annum! 1 To 1 Exchange Without Cash Top Up! Hurry And Call Our Friendly Sales Adviser For More Information Before It's Sold! Best Price Guaranteed!

✓ This car comes with 6-mth sgCarMart Warranty - the best protection for your car. Learn More

Platinum Motoring

Posted: 12-Dec-2021

Tags: 2017 Honda Odyssey, Honda Odyssey, Honda, Odyssey



Honda Odyssey 2.4A EXV-S Sunroof

\$85,800**\$12,960 /yr****31-Jan-2017****2,356 cc****130,000 km****MPV**

1 Careful Owner, Low Depreciation, Agent Maintained, Fuel Efficiency, Easy Financing, Flexible Loan Available, Accident-Free, 6 Months Free Servicing By Reputable Workshop With 40 Years Experience In The Market For A Peace Of Mind, Call For Viewing/Test Drive Now.

Posted: 11-Dec-2021

Tags: 2017 Honda Odyssey, Honda Odyssey, Honda, Odyssey



Honda Odyssey 2.4A EX-S

\$97,800**\$14,080 /yr****16-Oct-2017****2,356 cc****61,339 km****MPV**Graded B by **STRA**

Agent Warranty Till Oct 2022! Offer 1.85% Interest Rate! Purchase From An Award Winning Dealership! STA Certified Accident Free Quality Pre-Owned With Low Mileage For Peace Of Mind! 100% Loan Approval With Our Flexible In House Loan Financing Options! View...

Cosmo Automobiles

Posted: 11-Dec-2021

Tags: 2017 Honda Odyssey, Honda Odyssey, Honda, Odyssey



Excellent Grip Performance Michelin 18" Tyre

ON SALE Michelin PS4 (225/40/18). Visit us @ 32 Old Toh Tuck Rd, #01-09, I-biz Centre S(597657). Call 66862255 now!

Find out more!



Honda Odyssey 2.4A EXV-S Sunroof

\$97,988**\$15,360 /yr****03-Feb-2017****2,356 cc****53,600 km****MPV**

ent Unit. Viewing By Appointment Only. 1.85% Financing Rate! 5 Years/Unlimited Mileage Warranty By Agent Kah Motor! Black Paintwork With Black Leather Interior! Trade-In Available. Attractive Financing Rates And In-House Financing Available. C...

Cars Ventures Pte Ltd



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT21003812	Page	1
Registration No	: SLR8925S	Date	: 10. Dec 2021		
Chassis No	: JHMRC1880HC203488	Customer No.	: WZL009		
Model	: ODYSSEY 2.4 EX-S 17YM (EURO 6)	Svc Advisor	: RUEBEN THOMAS		
Owner's Name	: TAN TAI MENG	Engine No	: K24W72041132		
Ins Policy No.	:	Date Time	: 10. Dec 2021 11:47:11 AM		
Date of Accident	: 10/12/2021	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: TAN TAI MENG						
	OWNER INSURER: LIBERTY INSURANCE						
	ACC DATE: 10/12/2021						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: LONPAC INSURANCE						
	TP VEH: GBC2818E						
73211-T6A-Q02	GLASS SET,RR.WINDSHIELD <i>shattered</i>	1	1078.20	25	808.65	56.61	865.26
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE <i>neu</i>	2	19.20	25	28.80	2.02	30.82
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER <i>neu</i>	1	18.00	25	13.50	0.95	14.45
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER <i>neu</i>	1	18.00	25	13.50	0.95	14.45
73221-SR4-000	SPACERRR.W/SHIELD <i>neu</i>	4	4.20	25	12.60	0.88	13.48
73225-TM8-000	RUBBER A/WINDSHIELD DAM <i>neu</i>	1	3.90	25	2.92	0.20	3.12
73226-SZW-000	DAMPERSTD 5X5 <i>neu</i>	2	9.10	25	13.65	0.96	14.61
76711-T6A-003	CAPPIVOT <i>neu</i>	1	5.20	25	3.90	0.27	4.17
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>neu</i>	1	60.00		60.00	4.20	64.20
68100-T6A-Q10ZZ	TAILGATE COMP <i>306570</i>	1	1141.90	25	856.42	59.95	916.37
34155-T6A-003	LIGHT ASSYL.LID <i>320</i>	1	411.80	25	308.85	21.62	330.47
34150-T6A-003	LIGHT ASSY,R.LID <i>320</i>	1	411.80	25	308.85	21.62	330.47
33500-T6A-003	TAILLIGHT ASSYR. <i>320</i>	1	893.80	25	670.35	46.92	717.27
74440-T6A-003	WEATHERSTRIPTAILGATE <i>2m</i>	1	125.20	25	93.90	6.57	100.47
74800-TF0-J02	LOCKTAILGATE <i>20/3m</i>	1	197.70	25	148.27	10.38	158.65
74890-T6A-J01	GARNISH ASSYRR.LICENSE <i>neu</i>	1	245.70	25	184.27	12.90	197.17
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN <i>neu</i>	1	187.20	25	140.40	9.83	150.23
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER <i>D-5</i>	1	220.00	25	165.00	11.55	176.55
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL <i>D-5</i>	1	11.50	25	8.62	0.60	9.22

Printed on 10/12/2021 1:49:41 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SLR8925S
Chassis No : JHMRC1880HC203488
Model : ODYSSEY 2.4 EX-S 17YM (EURO 6)
Owner's Name : TAN TAI MENG
Ins Policy No. :
Date of Accident : 10/12/2021
Document No. : SQT21003812
Date : 10. Dec 2021
Customer No. : WZL009
Svc Advisor : RUEBEN THOMAS
Engine No : K24W72041132
Date | Time : 10. Dec 2021 11:47:11 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
75701-T6A-000	EMBLEMH <i>net</i>	1	28.10	25	21.07	1.47	22.54
04715-T6A-000ZZ	FACERR.BUMPER <i>D.S</i>	1	573.20	25	429.90	30.09	459.99
91505-TM8-003	CLIP.BUMPER <i>net</i>	9	2.30	25	15.52	1.09	16.61
33505-SLJ-013	REFLECTOR ASSYR.RR. <i>one</i>	1	48.40	25	36.30	2.54	38.84
71598-T6A-003	SPACERL.RR.BUMPER SIDE <i>best</i>	1	20.40	25	15.30	1.07	16.37
71593-T6A-003	SPACERR.RR.BUMPER SIDE <i>best</i>	1	20.40	25	15.30	1.07	16.37
71502-T6A-003ZG	FACER.RR.BUMPER GARNISH <i>D.S</i>	1	81.90	25	61.42	4.30	65.72
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>should</i>	1	320.00	25	320.00	22.40	342.40
84640-T6A-003ZA	LINING ASSYRR.PANEL <i>D.S</i>	1	110.50	25	82.87	5.80	88.67
84665-T6A-J12ZA	LINING COMPL.RR.SIDE	1	670.30	25	502.72	35.19	537.91
84615-T6A-N22ZD	LINING COMP.R.RR.SIDE <i>D.S</i>	1	782.70	25	587.02	41.09	628.11
74940-TR0-003	BUZZER ASSYSMART <i>1</i>	1	64.10	25	48.07	3.36	51.43
38387-SLE-003	ANTENNA ASSY.L.RR. <i>one</i>	1	64.60	25	48.45	3.39	51.84
76700-T6A-J01	WIPER MOTOR ASSY	1	256.40	25	192.30	13.46	205.76
76720-T4N-H01	ARM,RR.WIPER	1	45.40	25	34.05	2.38	36.43
76730-S3N-003	BLADEWINDSHIELD WIPER	1	45.70	25	34.27	2.40	36.67
66100-T6A-Q01ZZ	PANEL COMP,REAR <i>body</i>	1	491.40	25	368.55	25.80	394.35
04656-T6A-310ZZ	PAN SET,3RD SEAT <i>roughed/suc</i>	1	360.30	25	270.22	18.92	289.14
72841-SH3-315	OILSHEET <i>net</i>	1	43.40	25	32.55	2.28	34.83
Sum Item					6958.33	487.08	7,445.41

BO-VK-ASTRO-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN <i>net</i>	1	300.00	25	300.00	21.00	321.00
Sum Ext. Service					300.00	21.00	321.00

BOSUN	SUNDRIES <i>net</i>	1	50.00	25	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	25	180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	200.00	25	200.00	14.00	214.00
BOJSE	BODY JOINT SEALANT. <i>net</i>	1	200.00	25	200.00	14.00	214.00

Printed on 10/12/2021 1:49:41 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SLR8925S
Chassis No : JHMRC1880HC203488
Model : ODYSSEY 2.4 EX-S 17YM (EURO 6)
Owner's Name : TAN TAI MENG
Ins Policy No. :
Date of Accident : 10/12/2021

Document No. : SQT21003812 **Page** 3
Date : 10. Dec 2021
Customer No. : WZL009
Svc Advisor : RUEBEN THOMAS
Engine No : K24W72041132
Date | Time : 10. Dec 2021 11:47:11 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	✓	100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N)	1	250.00	✓	250.00	17.50	267.50
BG01S	TO VACUUM & CLEAR SHATTERED GLASS	1	350.00	200	350.00	24.50	374.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00	350	450.00	31.50	481.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00	350	450.00	31.50	481.50
BM103D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00	350	450.00	31.50	481.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00	✓	650.00	45.50	695.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00	550	650.00	45.50	695.50
BMF00D	REMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	650.00	450 phd?	650.00	45.50	695.50
BMU30R	REMOVE & INSTALL EXHAUST SYSTEM.(N)	11	450.00	X	450.00	31.50	481.50
BKR0P2B	CUT & RENEW RR FLOOR PANEL.STRAIGHTEN FENDERS ALIG	1	6200.00	6125	6200.00	434.00	6634.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3300.00	3100	3300.00	231.00	3531.00
Sum Labor					14580.00	1,020.60	15,600.60

Survey By : marcus lkk
Date & Time : 13/10/21 @ 9am.

Excess :
Status : not Authorised

Signature : Take photo before repair.
12 days?

Total Amount 21,838.33 1,528.68 23,367.01
Total (Inclusive of GST) 23,367.01

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 10/12/2021 1:49:41 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.