

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

13/12/2021 12:22

JOB-NO: 50113814

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHC0430G

TRANS: AUTO

CHASSIS: KMHC851CVKU141322

MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 DI

ENGINE: G4LEJU191238

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	1.00	1,200.00	0.00	1,200.00	300 400	Y	
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	170.00	0.00	170.00	30	Y	
3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	1.00	280.00	0.00	280.00	X	Y	
4 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	260.00	0.00	260.00	30	Y	
5 TO REFIT REAR REVERSE SENSOR	1.00	140.00	0.00	140.00	30	Y	
6 TO RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	200	Y	
7 TO RESPRAY REAR BUMPER CENTER MOULDING	1.00	250.00	0.00	250.00	150	Y	
8 TO RESPRAY REAR BUMPER LOWER MOULDING	1.00	250.00	0.00	250.00	80	Y	
9 TO RESPRAY REAR REVERSE SENSOR	1.00	250.00	0.00	250.00	30	Y	
10 TO RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00	200	Y	
11 TO RESPRAY REAR TAILGATE PANEL	1.00	250.00	0.00	250.00	X	Y	
12 TO RESPRAY REAR QUARTER PANEL	1.00	250.00	0.00	250.00	X	Y	
TOTAL:		3,800.00	0.00	3,800.00			

MATERIALS

1 REAR BUMPER COVER / DD	1.00	459.40	91.88	367.52	L	Y	
2 REAR BUMPER CENTER MOULDING / BR	1.00	270.10	54.02	216.08	L	Y	
3 REAR LH BUMPER RETAINER / BR	1.00	33.10	6.62	26.48	L	Y	
4 REAR BUMPER LOWER MOULDING / CUT	1.00	47.50	9.50	38.00	L	Y	
5 REAR BUMPER REINFORCEMENT X?	1.00	294.80	58.96	235.84	L	Y	
6 REAR LH BUMPER REINFORCEMENT X?	1.00	138.10	27.62	110.48	L	Y	
BRACKET							
7 REAR BUMPER TOWING COVER / MIS	1.00	9.10	1.82	7.28	L	Y	
8 REAR FOG LAMP ASSY X?	1.00	201.50	40.30	161.20	L	Y	
9 REAR LH BUMPER UNDER COVER X?	1.00	35.90	7.18	28.72	L	Y	
10 REAR LH BUMPER REFLECTOR X?	1.00	31.90	6.38	25.52	L	Y	✓
11 SMART KEY ANTENNA X?	1.00	41.90	8.38	33.52	L	Y	
12 REAR TAILGATE HYUNDAI EMBLEM X	1.00	68.20	13.64	54.56	L	Y	
13 REAR TAILGATE IONIQ EMBLEM X	1.00	48.20	9.64	38.56	L	Y	
14 REAR TAILGATE HYBRID EMBLEM X	1.00	51.20	10.24	40.96	L	Y	
15 REAR BOOT WEATHERSTRIP X	1.00	127.40	25.48	101.92	L	Y	
16 TAILLAMP LH X	1.00	905.20	181.04	724.16	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
17 REAR LH FENDER LINER X	1.00	148.40	29.68	118.72	L	Y	
18 REAR LH QUARTER PANEL AIR VENT X	1.00	57.60	11.52	46.08	L	Y	
19 REAR LH BLIND SPOT DETECTION UNIT X	1.00	1,784.40	356.88	1,427.52	L	Y	
20 REAR BUMPER CLIP SET - nec	1.00	75.00	0.00 30	75.00	S	Y	
21 REAR BUMPER PROTECTOR - nec	1.00	160.00	0.00 60	160.00	S	Y	
22 REAR REVERSE SENSOR SET - BR	2.00	400.00	0.00	400.00 200	S	Y	
23 REAR FENDER LINER CLIP SET - nec	1.00	65.00	0.00	65.00 30	S	Y	
24 REAR TAILGATE "6552-1111" STICKER X	1.00	140.00	0.00	140.00	S	Y	
25 REAR TAILGATE "COMFORT DELGRO" STICKER X	1.00	140.00	0.00	140.00	S	Y	
26 REAR TAILGATE "BOOK NOW" STICKER X	1.00	140.00	0.00	140.00	S	Y	
27 REAR BUMPER MOULDING CLIP SET - nec	1.00	55.00	0.00	55.00 10	S	Y	
28 REAR BUMPER UNDER COVER CLIP SET X	1.00	60.00	0.00	60.00	S	Y	
29 TAILLAMP GUIDE CLIP SET X	1.00	55.00	0.00	55.00	S	Y	
30 REAR LICENCE PLATE NUMBER WITH FRAME X	1.00	100.00	0.00	100.00	S	Y	
TOTAL:		6,143.90	950.78	5,193.12			
TOTAL PARTS & LABOUR :		9,943.90	950.78	8,993.12			

EXCESS/LOADING:\$ 0.00

No. Of Day: _____

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: S\$ _____

DATE OF SURVEY: ____ / ____ / ____

SURVEYED BY: _____

CONTACT NO: _____ FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL: _____ FAX: _____

ML RL
LTP PIP
M ALH
48 djs

Part by Part

Labour = \$ 1150.00
S/N = \$ 330.00
Parts = \$ 680.88

LtstP = \$ 2160.88
Final Amt = \$ 2160.88