

Our Job Ref No : 305497435
Date : 15/12/21

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHC8759C

09/12/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: CHINA SFD9781C

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less:
Final Lumpsum Repair cost


\$2,100.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.


We confirm the estimates and
finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name : Thevan

Date : 17/12/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORTDELGRO PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC8759C ✓

09/12/21

MAKE REG. 17.03.2016

MODEL I-40

CHIANG /CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER BRACKET LH			\$24.60
1	FRONT BUMPER TOP BRACKET LH			\$22.40
1	FRONT BUMPER			\$1,052.20
1	FRONT BUMPER GRILLE LH/ RH		\$93.45	\$186.90
1	RADIATOR EMBLEM			\$28.00
1	RADIATOR GRILLE ASSY			\$1,409.10
1	HEAD LAMP ASSY LH /RH		\$1,388.00	\$2,776.00
10	BUMPER CLIPS		\$2.20	\$22.00
	SUB TOTAL			\$5,521.20
	LESS 20%			\$1,104.24
				\$4,416.96
1	FRONT NUMBER PLATE			\$30.00
				\$30.00
	Labour Charge			
	Panel Beating			\$560.00
	Spray Painting Charge			\$600.00
	Tuff Kote			\$60.00
	Check Lighting			\$60.00
	TOTAL LABOUR			\$1,280.00
	ESTIMATE TOTAL			\$5,726.96

Thang @ LKK Auto. Low

82235769

9/10/21 1700

L/S after repair photo
2 days up ✓LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: