



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21012546/R1vf3e2	
			Date: 24/12/2021	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMB 166R	Veh. Inspected	SBS 3388M	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/12/21/7007	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	13/12/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	VOLVO B9TL 9.4L AUTO	c.c	9364	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	YV3S4P927EA166433	Colour	GREEN	
Odometer	552287 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	FIRENZA	8 mm	
L/H Front Tyre	275/70 R22.5	FIRENZA	8 mm	
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm	
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	8/8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	08/12/2021	Inspection Date	13/12/2021	
Survey held at	TOWER TRANSIT SINGAPORE PTE. LTD. 21 BULIM DRIVE SINGAPORE 648170			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>1 Working Days</b>	