



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Lim Seng Choon	Cust No/Name /Mr Lim Seng Choon
6 Springside Drive	Reg No/Reg Date SMJ144L / 20/02/201
Singapore 786975	Date In/Mileage / 0
Contact No Mobile: 90308598	Chassis No MMBSTA13AKH000687
	Engine No 3A92UHM3342
	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	10/12/2021/ 11:54		442 / CocoLu	18563
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW FRT BUMPER, FRT SUPPORT PANEL, REPAIR FRT FENDER RH&LH	450 x 1			1800.00
BONNET					
E PNT88000	REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR				100.00
E PNT98000	SPRAY PAINT FOR FRT BUMPER, BONNET, FRT SUPPORT PANEL	350 x 1			1750.00
FRT FENDER RH & LH					
M SUNDRY	FRT NUMBER PLATE WITH FRAME cut				50.00
A 54900099	CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRY	Sundry				20.00
A 54900099	TOP UP AIRCON GAS				80.00
M FACE,FR BUMPER		1.00	706.00	00.00	706.00
M MARK,THREE-DIA		1.00	70.00	00.00	70.00
M COVER,HEADLAMP SUPT PANEL		1.00	62.00	00.00	62.00
M BRACKET,FR BUMPER,RH		1.00	13.00	00.00	13.00
M BRACKET,FR BUMPER,LH		1.00	13.00	00.00	13.00
M GRILLE,FR UNDER		1.00	165.00	00.00	165.00
M AIR DAM,SIDE,FR RH		1.00	18.00	00.00	18.00
M AIR DAM,SIDE,FR LH		1.00	18.00	00.00	18.00
M GARNISH,FR BUMPER,LH		1.00	127.00	00.00	127.00
M GRILLE,RADIATOR		1.00	557.00	00.00	557.00
M PANEL ASSY,FR END		1.00	1055.00	00.00	1055.00
M PANEL,HEADLAMP SUPPORT,UPR		1.00	66.00	00.00	66.00
M HEADLAMP ASSY,RH		1.00	663.00	00.00	663.00
M HEADLAMP ASSY,LH		1.00	663.00	00.00	663.00
M PANEL,AIR GUIDE		1.00	112.00	00.00	112.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Lim Seng Choon 6 Springside Drive Singapore 786975 Contact No Mobile: 90308598	Cust No/Name	/Mr Lim Seng Choon
	Reg No/Reg Date	SMJ144L / 20/02/201
	Date In/Mileage	/ 0
	Chassis No	MMB5TA13AKH000687
	Engine No	3A92UHM3342
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
		Colour/Trim
		W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	10/12/2021/ 11:54		442 / CocoLu	18563
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M RADIATOR ASSY	1 x nn	1.00	972.00	00.00	972.00
M TANK ASSY, RADIATOR COND	1 x nn	1.00	42.00	00.00	42.00
M FAN, COOLING, LH	1 x nn	1.00	77.00	00.00	77.00
M SHROUD, COOLING FAN	1 x nn	1.00	131.00	00.00	131.00
M CONDENSER ASSY, A/C REFRIGE	1 x nn / DD	1.00	762.00	00.00	762.00
M PIPE, A/C CONDENSER OUTLET	1 x nn	1.00	305.00	00.00	305.00
M HOSE, A/C COMPR DISCHARGE	1 x nn	1.00	210.00	00.00	210.00

Estimate

Stev (LKK)

13/12/21, 11:00

00- M / L

EXTRA - !

P/P

L/ BL / J

68 L/S

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm & accepted by
Signature:
Date:

Nett 10,757.00
7% GST on 10757.00 752.99
Total Payable 11,509.99

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.