



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 09.12.2021
Emailed : 22.12.2021, 4.50pm
Date survey : 13.12.2021

VEHICLE NO : SMJ 144 L
MODEL : MIT ATTRAGE 1.2
WIP : 18563

Material	:	\$	2,717.33
Labour	:	\$	2,880.00
Sub-Total	:	\$	5,597.33
	:		-
Less Excess	:	\$	300.00
Total	:	\$	5,297.33
GST 7%	:	\$	370.81
Grand Total	:	\$	5,668.14
Finalise By/Date	:	LOI / 22/12/2021	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim

☐ Claim GIA / LTA fee

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Mr Lim Seng Choon Reg No/Reg Date SMJ144L / 20/02/2019 Date In/Mileage 13/12/2021/ 57745 Chassis/Package MMBSTA13AKH000687 /DC17PT Engine No 3A92UHM3342 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim W05 WHITE PEARL / BK BLACK
13/12/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	22/12/2021/ 15:52	BLC	260 / AiTing	18563			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 450.00
E PNT88000 REMOVE & INSTALL A/COND CONDENSOR & RADIATOR TO FACILITATE REPAIR								? 100.00
E PNT98000 RESPRAY ON FRONT BUMPER AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 350.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY SUNDRIES								✓ 20.00
A 54900099 VACUUM & TOP UP A/COND GAS								? 80.00
S SPECIALISTJOB SUPPLY & REPLACE FRONT LICENSE PLATE WITH FRAME								✓ 50.00
E PNT88000 REPLACE FRONT AIR DAM								80.00
E PNT98000 RESPRAY FRONT AIR DAM								350.00
E PNT88000 REPLACE FRONT H/LAMP SUPPORT PANEL								900.00
E PNT98000 RESPRAY FRONT H/LAMP SUPPORT PANEL								350.00
X EXC EXCESS								-300.00
X FACE,FR BUMPER					1.00	706.00	23.00	543.62
X MARK,THREE-DIA					1.00	70.00	23.00	53.90
X GRILLE,FR UNDER					1.00	165.00	23.00	127.05
X GRILLE,RADIATOR					1.00	557.00	23.00	428.89
X PANEL ASSY,FR END					1.00	1055.00	23.00	812.35
X CONDENSER ASSY,A/C REFRIGE					1.00	762.00	23.00	586.74

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 13/12/2021	<table> <tr> <td>Cust No/Name</td><td>/Mr Lim Seng Choon</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMJ144L / 20/02/2019</td></tr> <tr> <td>Date In/Mileage</td><td>13/12/2021/ 57745</td></tr> <tr> <td>Chassis/Package</td><td>MMBSTA13AKH000687 /DC17PT</td></tr> <tr> <td>Engine No</td><td>3A92UHM3342</td></tr> <tr> <td>Make/Model</td><td>MIT/19MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>W05 WHITE PEARL / BK BLACK</td></tr> </table>	Cust No/Name	/Mr Lim Seng Choon	Reg No/Reg Date	SMJ144L / 20/02/2019	Date In/Mileage	13/12/2021/ 57745	Chassis/Package	MMBSTA13AKH000687 /DC17PT	Engine No	3A92UHM3342	Make/Model	MIT/19MY ATTRAGE 1.2 CVT	Colour/Trim	W05 WHITE PEARL / BK BLACK
Cust No/Name	/Mr Lim Seng Choon														
Reg No/Reg Date	SMJ144L / 20/02/2019														
Date In/Mileage	13/12/2021/ 57745														
Chassis/Package	MMBSTA13AKH000687 /DC17PT														
Engine No	3A92UHM3342														
Make/Model	MIT/19MY ATTRAGE 1.2 CVT														
Colour/Trim	W05 WHITE PEARL / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	22/12/2021/ 15:52	BLC	260 / AiTing	18563

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X RIVET,FR BUMPER	10.00	5.00	23.00	38.50
X CLIP,RR BUMPER	10.00	3.00	23.00	23.10
X PANEL,AIR GUIDE,RH } Supp.	1.00	11.00	23.00	8.47
X PANEL,AIR GUIDE	1.00	? 112.00	23.00	86.24
X PANEL,AIR GUIDE,LH → Supp.	1.00	11.00	23.00	8.47
Z TEXT AIG OD CLAIM DOA : 09.12.21 SURVEYOR STEVE LKK 13.12.21 POLICY NO : 1900011407-01 REPAIR 03 DAYS				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	2,717.33	Nett	5,297.33
Labour	2,810.00	7% GST on	370.81
Standard Menu	0.00		
Specialist Job	50.00		
Diagnostics Job	0.00		
Sundry/Others	-280.00		
Total(w/o GST)	5,297.33	Total Payable	5,668.14

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : AIG


Supplementary Parts For Registration No.: SMJ 144 L

<u>Materials</u>		<u>Cost (\$)</u>
1	Rivet, fr bumper (x10)	50.00 — nec
2	Clips (x10)	30.00 — nec
3	Panel, Air guide, RH	11.00 — BR
4	Panel, Air guide, LH	11.00 — BR
Total		102.00
Less 23%		23.46
Total Materials		78.54

<u>Labour</u>		<u>Cost (\$)</u>
1	Replace front air dam	80.00 —
2	Respray front air dam	350.00 —
3	Replace front H/lamp support panel	900.00 —
4	Respray front H/lamp support panel	350.00 —
Total Labour		1,680.00
Taxable Amount		1,758.54
7% GST		123.10
Grand total		<u><u>1,881.64</u></u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD


LOI AI TING
SENIOR OFFICER - ADMIN
TEL: 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SmJ 44LWIP: 18563

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	R/I Front Body Kit \$80	? / SUPP			
2	Respray Front Body Kit \$350	? / SUPP			
3	Replace Front Support \$900	? / SUPP			
4	Repair Respray Front Support \$380	? / SUPP			
5	R/I Radiator & Condensor \$100	? / SUPP			
6	Air Con Condensor 1	? / SUPP		- BT	Stop
7	Panel Air Guide	? / SUPP		- BR	15/12/21
8	Panel Air Guide LH	? / SUPP		- BR	
9	Panel Air Guide RH	? / SUPP		- BR	
10	Clip Front Bumper	? / SUPP		- R	
11	Coil and 4L	? / SUPP		- R	
12	Rivet Front Bumper	? / SUPP		- R	
13	Panel Front Support	? / SUPP		- R	
14	Additional 3 Repair Days	? / SUPP		- R	
15	= 16 days	? / SUPP			
16		? / SUPP			
17	Top up gas \$80	? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

DATE	TAKEN BY

PHOTO BEFORE PAINT

PHOTO AFTER PAINT

PHOTO OF MOUNT TO CELLETTE BENCH

REMOVE AND INSTALL ENGINE

REMOVE AND INSTALL DASHBAORD

REMOVE & INSTALL FUEL TANK

PHOTO UNDERCARRIAGE PARTS

MODEL: atvageSURVEYOR: Steve

All DTCs

2021.12.21

Setting	
Item	Information
M.U.T.-3 Version	SEW21091-00
V.C.I. Version	B179
Vehicle Information	A13A 2019MY

very nice job

After very PWT-3 not unit to Ease all Be board

2021.12.21

Is do Done

is by G.C Test drive

All DTCs

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	KOSOSS_99880010		No DTCs	
AT/CVT/A-MTTC-SST	KOSOSS_99880010		No DTCs	
4WS/Electric Power Steering	KOSOSS_99880010		No DTCs	
ABS/ASC/ASTC/WSS	KOSOSS_99880010		No DTCs	
SRS-AIR BAG	KOSOSS_99880010		No DTCs	
Air Conditioner	KOSOSS_99880010		No DTCs	
ETACS	KOSOSS_99880010		No DTCs	
Meter	KOSOSS_99880010		No DTCs	
Steering Angle Sensor	KOSOSS_99880010		Non-target System	
KOS/OSS/IMMO/Keyless (with KOS)	KOSOSS_99880010		No DTCs	