



CYCLE & CARRIAGE

AIG-OD CLAIM
SURVEY: 13/12/21
LKK-STEVE

VEHICLE NO : SMV384Y

MODEL : MIT/OUTLANDER 2.0 STYLE

WIP : 18565

Material	:	\$	<u>4,086.39</u>
Labour	:	\$	<u>1,595.00</u>
Sub-Total	:	\$	<u>5,681.39</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>5,381.39</u>
GST 7%	:	\$	<u>376.70</u>
Grand Total	:	\$	<u>5,758.09</u>

Re-Finalise By/Date : Umay on 18/01/22

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 05 WORKING DAYS + 2 days (wk.end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 13/12/2021	Cust No/Name	KCV16006/LONG SIOW MENG
	Reg No/Reg Date	SMV384Y / 14/09/2020
	Date In/Mileage	13/12/2021/ 26741
	Chassis/Package	GF7W0700855 /#
	Engine No	4J11CQ9517
	Make/Model	MIT/20MY OUTLANDER 2.0 STYLE (999)
	Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	18/01/2022/ 08:58	BLK	884 / Lauro Songcuan	18565

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRONT BUMPER PANEL & AFFECTED AREAS				450.00 ✓
E PNT98000 PAINT WORK ON FRONT BUMPER				350.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
S SPECIALISTJOB SUPPLY FRONT NUMBER PLATE WITH FRAME				50.00 ✓
E PNT88000 REPAIR LH FRONT FENDER → <i>Supp</i>				225.00 ✗
E PNT98000 SPRAY PAINT LH FRONT FENDER → <i>Supp</i>				350.00 ✗
X EXC INSURANCE EXCESS				-300.00
X HEADLAMP ASSY,LH	1.00	1948.00	23.00	1499.96 ✓
X FACE,FR BUMPER	1.00	851.00	23.00	655.27 ✓
X GARNISH,FR LICENSE PLATE	1.00	23.00	23.00	17.71 ✓
X GARNISH,FR BUMPER SIDE	1.00	220.00	23.00	169.40 ✓
X GARNISH,FR BUMPER SIDE	1.00	112.00	23.00	86.24 ✓
X REINFORCEMENT,FR BUMPER	1.00	510.00	23.00	392.70 ?
X REINF,FR BUMPER SIDE,LH	1.00	60.00	23.00	46.20 ?
X REINFORCEMENT,FR BUMPER	1.00	135.00	23.00	103.95 ?
X EXTENSION,FR BUMPER	1.00	517.00	23.00	398.09 ✓
X COVER,FR BUMPER	1.00	361.00	23.00	277.97 ✓
X GRILLE ASSY,RADIATOR	1.00	550.00	23.00	423.50 ✓
X CLIP,ENG ROOM COVER → <i>Supp</i>	10.00	2.00	23.00	15.40 ✗
Z TEXT AIG - OD CLAIM DOA: 09/12/2021				

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 13/12/2021	Cust No/Name	KCV16006/LONG SIOW MENG
	Reg No/Reg Date	SMV384Y / 14/09/2020
	Date In/Mileage	13/12/2021/ 26741
	Chassis/Package	GF7W0700855 /#
	Engine No	4J11CQ9517
	Make/Model	MIT/20MY OUTLANDER 2.0 STYLE (999)
	Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	18/01/2022/ 08:58	BLK	884 / Lauro Songcuan	18565

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
SURVEY: STEVE (LKK) 13/12/2021 05 DAYS				
Pro Forma				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	4,086.39	Nett	5,381.39
Labour	1,525.00	7% GST on	376.70
Standard Menu	0.00		
Specialist Job	50.00		
Diagnostics Job	0.00	Total Payable	5,758.09
Sundry/Others	-280.00		
Total(w/o GST)	5,381.39		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : **AIG**


Supplementary For Registration No.: **SMV 384 Y**

<u>Materials</u>			<u>Cost (\$)</u>
1	Clip, Eng Room Cover (10 pcs)	nec	20.00
		23% Discount	4.60
			<u>15.40</u>
<u>Labour</u>			
1	Repair LH Front Fender		225.00
2	Spray Paint LH Front Fender		350.00
			<u>575.00</u>
Labou & Materials			590.40
7% Gst			41.33
Total			<u>631.73</u>

Thank You.

Yours faithfully

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD


LARRY SONGCUAN
CUSTOMER SERVICE
TEL: 6568 4658
FAX : 6567 5258

CAR NO: SNV 384YWIP: 18565 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	REINFORCEMENT FR BUMPER	? / SUPP	(Sig)	— BT	
2	REINFORCEMENT FR BUMPER	? / SUPP	(metal)	— BT	
3	BAR FR BUMPER LHF	? / SUPP	(metal)	— BT	
4	Bumper clip X10	? / SUPP		— ME	
5		? / SUPP			
6		? / SUPP			
7	Repair LHF Fender H 450 225	? / SUPP		—	Steve 14/12/21
8	Spary paint LHF Fender H 350	? / SUPP		—	
9	Repair working Day = 02 day	? / SUPP		—	
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: DartlanderSURVEYOR: Steve - lkh