



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<tr> <td>Cust No/Name</td><td>KCV16006/LONG SIOW MENG</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMV384Y / 14/09/202</td></tr> <tr> <td>Date In/Mileage</td><td>13/12/2021/ 0</td></tr> <tr> <td>Chassis No</td><td>GF7W0700855</td></tr> <tr> <td>Engine No</td><td>4J11CQ9517</td></tr> <tr> <td>Make/Model</td><td>MIT/20MY OUTLANDER 2.0 STYLE (999)</td></tr> <tr> <td>Colour/Trim</td><td>X04 BLACK / BK BLACK</td></tr>	Cust No/Name	KCV16006/LONG SIOW MENG	Reg No/Reg Date	SMV384Y / 14/09/202	Date In/Mileage	13/12/2021/ 0	Chassis No	GF7W0700855	Engine No	4J11CQ9517	Make/Model	MIT/20MY OUTLANDER 2.0 STYLE (999)	Colour/Trim	X04 BLACK / BK BLACK
Cust No/Name	KCV16006/LONG SIOW MENG														
Reg No/Reg Date	SMV384Y / 14/09/202														
Date In/Mileage	13/12/2021/ 0														
Chassis No	GF7W0700855														
Engine No	4J11CQ9517														
Make/Model	MIT/20MY OUTLANDER 2.0 STYLE (999)														
Colour/Trim	X04 BLACK / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	10/12/2021/ 12:27	BLK	282 / Kevin Leong	18565
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	REPLACE FRT BUMPER PANEL, FRT LH FENDER & AFFECTED AREA 450x1				1350.00
E PNT98000	PAINT WORK ON FRT BUMPER & FRT LH FENDER 350 x1				700.00
M SUNDRY	PERFORM RUST PREVENTION				40.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRY	TO SUPPLY FRONT NUMBER PLATE WITH FRAME				50.00
M SUNDRY	SUNDRIES				30.00
M HEADLAMP ASSY, LH	- CUT	1.00	1948.00	23.00	1499.96
M FACE, FR BUMPER	- BR	1.00	851.00	23.00	655.27
M BRACKET, FR BUMPER SIDE, LH	? x nn	1.00	18.00	23.00	13.86
M GARNISH, FR BUMPER, LH	? x nn	1.00	48.00	23.00	36.96
M GARNISH, FR LICENSE PLATE	- CUT	1.00	23.00	23.00	17.71
M GARNISH, FR BUMPER SIDE	- BR (chrome)	1.00	220.00	23.00	169.40
M GARNISH, FR BUMPER SIDE	- BR (chrome)	1.00	112.00	23.00	86.24
M GARNISH, FR BUMPER SIDE	? x nn	1.00	48.00	23.00	36.96
M REINFORCEMENT, FR BUMPER	? x nn	1.00	510.00	23.00	392.70
M REINF, F/BMPR SIDE, LWRLH	? x nn	1.00	25.00	23.00	19.25
M REINF, FR BUMPER SIDE, LH	? x nn	1.00	60.00	23.00	46.20
M REINFORCEMENT, FR BMPR SIDE	? x nn	1.00	22.00	23.00	16.94
M REINFORCEMENT, FR BUMPER	? x nn	1.00	135.00	23.00	103.95
M EXTENSION, FR BUMPER (Silver)	- CUT	1.00	517.00	23.00	398.09
M COVER, FR BUMPER (Black)	- CUT	1.00	361.00	23.00	277.97
M GRILLE ASSY, RADIATOR	- CUT	1.00	550.00	23.00	423.50
M COVER, FR BUMPER	? x nn	1.00	25.00	23.00	19.25
M COVER, HEADLAMP SUPT PANEL	? x nn	1.00	50.00	23.00	38.50
M FENDER, FR LH	? x nn	1.00	622.00	23.00	478.94

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV16006/LONG SIOW MENG
	Reg No/Reg Date	SMV384Y / 14/09/202
	Date In/Mileage	13/12/2021/ 0
	Chassis No	GF7W0700855
	Engine No	4J11CQ9517
	Make/Model	MIT/20MY OUTLANDER 2.0 STYLE (999)
	Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	10/12/2021/ 12:27	BLK	282 / Kevin Leong	18565			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M MOULDING,FR BUMPER,LH 2 x 77					1.00	97.00	23.00	74.69

Estimate

ster (LKK)
 13/12/21, 10.30a

00-M AL
 EXAM ?
 P/P
 My Bul by
 3 dps

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm & accepted by:

	Nett	7,126.34
7% GST on	7126.34	498.84
Total Payable		7,625.18

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.