

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969

Our Ref : 805497567

Via Fax : EWMA

Date : 13.12.21

Your Insured : SLR 1760X

Time of Fax :                     

Date of Acc : 10.12.21

Attn: Motor Claims Department ALG

Dear Sirs

**SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH 7982C**

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
◆ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
◆ <u>Chiang Liat Choon</u>	<u>Tel: 6214 8314 or HP: 9296 6006</u>

} **chianglc@cdge.com.sg**  
**Fax no. 6546 8156**

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

  
For Vice President  
Taxi Accident Repair

## COMFORTDELGRO PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO SH7982C

10/12/21

MAKE REG. 29.12.2016

MODEL I-40

CHIANG /AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER BRACKET RH			\$24.60
1	FRONT BUMPER TOP BRACKET RH			\$22.40
1	FRONT BUMPER			\$1,052.20
1	FRONT BUMPER GRILLE / RH			\$93.45
1	RADIATOR EMBLEM			\$28.00
1	RADIATOR GRILLE ASSY			\$1,409.10
1	HEAD LAMP SUPPORT PANEL			\$907.40
1	HEAD LAMP ASSY /RH			\$1,388.00
10	BUMPER CLIPS		\$2.20	\$22.00
	<b>SUB TOTAL</b>			<b>\$4,947.15</b>
	<b>LESS 20%</b>			<b>\$989.43</b>
				<b>\$3,957.72</b>
1	FRONT NUMBER PLATE			\$30.00
				<b>\$50.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$560.00
	Spray Painting Charge			\$600.00
	Tuff Kote			\$60.00
	Check Lighting			\$60.00
	<b>TOTAL LABOUR</b>			<b>\$1,280.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$5,287.72</b>

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO305497567

OMER

IS COMFORT TRANSPORTATION PTE LTD

OMER NO. 7010045

LESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

DUNT CARD NO.

REGN NO.:

SH 7982C

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

10.12.2021 23:45

DATE/TIME IN

YR OF MANU.

29.12.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMHU097349

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 10.12.2021

ATURE: 3P 10.12.2021

NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Io.: SH 7982C

LIMITS

Vehicle No.:

SH 7982C

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard