



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV11499/LEK CHIN KWONG (LU ZENG GUANG)
	Reg No/Reg Date	SMR7700T*ECB1/ 14/11/201
	Date In/Mileage	/ 19135
	Chassis No	KNAPH813ML5612855
	Engine No	G4KJH768945
	Make/Model	KIA/SORENTO 2.4 A SX GDI SR
	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	11/12/2021/ 12:51	BLE	261 / Edwin Caina	43862			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								
ULTRASONIC SENSOR-S.P.A.S SIDE								
KS96891C1000ABP								
E PNT88000								
RENEW FR BUMPER , BONNET & FR SUPPORT					1.5 X 470			600 2000.00
REPAIR RHF FENDER								1050.00
E PNT98000								
RESPRAY FR BUMPER , BONNET & RHF FENDER					3 X 350			100.00
E PNT88000								
REMOVE & REFIT AC COND & RADIATOR								80.00
M SUNDRY								
TOP UP AC GAS								30.00
A 54900099								
CHECK WIRING ELECTRICAL SYSTEM								120.00
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								80.00
E PNT88000								
REMOVE & REFIT FR PARKING ASSIST SENSOR								20.00
M SUNDRY								
Sundries								
M PANEL ASSY-HOOD					1.00	1654.00	20.00	1323.20
M HINGE ASSY-HOOD,LH					1.00	87.00	20.00	69.60
M HINGE ASSY-HOOD,RH					1.00	87.00	20.00	69.60
M CLIP-HOOD INSULATING PAD MTG					13.00	1.00	20.00	10.40
M LATCH ASSY-HOOD					1.00	104.00	20.00	83.20
M STRIP ASSY FR-HOOD					1.00	27.00	20.00	21.60
M LAMP ASSY-HEAD,RH					1.00	2743.00	20.00	2194.40
M CARRIER ASSY-FRONT END MODULE					1.00	760.00	20.00	608.00
M BEAM COMPLETE-FR BUMPER					1.00	551.00	20.00	440.80
M COVER-FR BUMPER UPR					1.00	561.00	20.00	448.80
M MOULDING-FRONT BUMPER LWR,RH					1.00	89.00	20.00	71.20
M LIP-FRONT BUMPER					1.00	56.00	20.00	44.80
M SKID PLATE-FR BUMPER					1.00	111.00	20.00	88.80

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table border="1"> <tr> <td>Cust No/Name</td><td>LCV11499/LEK CHIN KWONG (LU ZENG GUANG)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMR7700T*ECB1/ 14/11/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 19135</td></tr> <tr> <td>Chassis No</td><td>KNAPH813ML5612855</td></tr> <tr> <td>Engine No</td><td>G4KJH768945</td></tr> <tr> <td>Make/Model</td><td>KIA/SORENTO 2.4 A SX GDI SR</td></tr> <tr> <td>Colour/Trim</td><td>ABP AURORA BLACK / WK SATURN BLACK</td></tr> </table>	Cust No/Name	LCV11499/LEK CHIN KWONG (LU ZENG GUANG)	Reg No/Reg Date	SMR7700T*ECB1/ 14/11/201	Date In/Mileage	/ 19135	Chassis No	KNAPH813ML5612855	Engine No	G4KJH768945	Make/Model	KIA/SORENTO 2.4 A SX GDI SR	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK
Cust No/Name	LCV11499/LEK CHIN KWONG (LU ZENG GUANG)														
Reg No/Reg Date	SMR7700T*ECB1/ 14/11/201														
Date In/Mileage	/ 19135														
Chassis No	KNAPH813ML5612855														
Engine No	G4KJH768945														
Make/Model	KIA/SORENTO 2.4 A SX GDI SR														
Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	11/12/2021/ 12:51	BLE	261 / Edwin Caina	43862			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	GRILLE-FRONT BUMPER	x nn			1.00	191.00	20.00	152.80
M	GRILLE-FRONT BUMPER FOG LAMP,R	BR			1.00	81.00	20.00	64.80
M	AIR DUCT-FR BUMPER,RH	x nn			1.00	28.00	20.00	22.40
M	LAMP ASSY-FRONT FOG,RH	BR			1.00	593.00	20.00	474.40
M	ABSORBER-FRONT BUMPER ENERGY	x nn			1.00	117.00	20.00	93.60
M	STIFFENER ASSY-FR BUMPER LWR	x nn			1.00	117.00	20.00	93.60
M	BRACKET-FR BUMPER SIDE,RH	x nn			1.00	17.00	20.00	13.60
M	GARNISH ASSY-FNDR SIDE,RH	x nn			1.00	88.00	20.00	70.40
M	ULTRASONIC SENSOR ASSY-BWS	x nn			4.00	187.00	20.00	598.40

# Estimate

Stere (LKK) 13/12/21, 11:39am

SURVEYOR NAME: \_\_\_\_\_

SURVEYOR SIGNATURE: OO-ML AL

DATE: EXP-?

REMARKS: PIP

My BL Ly

7 5 dgr

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by \_\_\_\_\_

Authorized signatory and company stamp \_\_\_\_\_

7% GST on	Nett	10,538.40
	10538.40	737.69
<b>Total Payable</b>		<b>11,276.09</b>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.