



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /LAM SZE JIA (LAN SIJIA) Reg No/Reg Date SMN5700C / 19/08/201 Date In/Mileage 14/12/2021/ 0 Chassis No GF7W0601876 Engine No 4J11BH4181 Make/Model MIT/19MY OUTLANDER 2.0 STYLE(994) Colour/Trim D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	13/12/2021/ 11:23	BLK	282 / Kevin Leong	18622
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER PANEL, REINFORCEMENT & AFFECTED AREA	450				900.00
E PNT98000 PAINT WORK ON FRT BUMPER PANEL	350				350.00
E PNT88000 REMOVE & INSTALL FRT PARKING ASSISST FOR FACILITATE REPAIR	80				120.00
M SUNDRY PERFORM RUST PREVENTION	8				40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM					30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM					120.00
M SUNDRY TO SUPPLY FRONT NUMBER PLATE WITH FRAME					50.00
M SUNDRY SUNDRIES	20				50.00
M LAMP ASSY, FOG, FR RH	1.00	348.00	23.00		267.96
M GARNISH, FR BUMPER, RH	1.00	48.00	23.00		36.96
M BRACKET, FR BUMPER SIDE, RH	1.00	18.00	23.00		13.86
M GARNISH, FR BUMPER SIDE	1.00	220.00	23.00		169.40
M GARNISH, FR BUMPER SIDE	1.00	112.00	23.00		86.24
M MOULDING, FR BUMPER, RH	1.00	116.00	23.00		89.32
M FACE, FR BUMPER	1.00	851.00	23.00		655.27
M COVER, FR BUMPER	1.00	361.00	23.00		277.97
M GARNISH, FR BUMPER SIDE	1.00	48.00	23.00		36.96
M RIVET, FR BUMPER	10.00	5.00	23.00		38.50
M TANK, WINDSHIELD WASHER	1.00	87.00	23.00		66.99
M SENSOR, W/SHLD WASHER TANK	1.00	114.00	23.00		87.78
M EXTENSION, FR BUMPER	1.00	517.00	23.00		398.09
M BODY KIT, OUTLANDER	1.00	1554.00	20.00		1243.20
M REINFORCEMENT, FR BUMPER	1.00	493.00	23.00		379.61
M BAR, FR BUMPER GUARD	1.00	130.00	23.00		100.10
M REINFORCEMENT, FR BMPR SIDE	1.00	22.00	23.00		16.94

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

## ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<table> <tr> <td>Cust No/Name</td><td>/LAM SZE JIA (LAN SIJIA)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMN5700C / 19/08/201</td></tr> <tr> <td>Date In/Mileage</td><td>14/12/2021/ 0</td></tr> <tr> <td>Chassis No</td><td>GF7W0601876</td></tr> <tr> <td>Engine No</td><td>4J11BH4181</td></tr> <tr> <td>Make/Model</td><td>MIT/19MY OUTLANDER 2.0 STYLE(994)</td></tr> <tr> <td>Colour/Trim</td><td>D01 COSMIC BLUE MET/ BK BLACK</td></tr> </table>	Cust No/Name	/LAM SZE JIA (LAN SIJIA)	Reg No/Reg Date	SMN5700C / 19/08/201	Date In/Mileage	14/12/2021/ 0	Chassis No	GF7W0601876	Engine No	4J11BH4181	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)	Colour/Trim	D01 COSMIC BLUE MET/ BK BLACK
Cust No/Name	/LAM SZE JIA (LAN SIJIA)														
Reg No/Reg Date	SMN5700C / 19/08/201														
Date In/Mileage	14/12/2021/ 0														
Chassis No	GF7W0601876														
Engine No	4J11BH4181														
Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)														
Colour/Trim	D01 COSMIC BLUE MET/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	13/12/2021/ 11:23	BLK	282 / Kevin Leong	18622			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	REINF,FR BUMPER SIDE,LH				1.00	60.00	23.00	46.20
M	REINF,FR BUMPER SIDE,RH				1.00	69.00	23.00	53.13
P	GRILLE ASSY,RADIATOR				1.00	550.00	23.00	423.50

# Estimate

Steve (LKK)  
14/12/21, 11:30p

00-MAL  
EXCISE?  
PFF  
My Bel sy  
48 d/s

LKK Auto Consultants hereby notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Confirm &amp; accepted by

Acknowledged by Reparer

Signature:

Date:

	Nett	6,147.98
7% GST on		430.36
<b>Total Payable</b>		<b>6,578.34</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.