



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/LAM SZE JIA (LAN SIJIA)
	Reg No/Reg Date	SMN5700C / 19/08/201
	Date In/Mileage	14/12/2021/ 0
	Chassis No	GF7W0601876
	Engine No	4J11BH4181
	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim	D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	13/12/2021/ 11:23	BLK	282 / Kevin Leong	18622			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								900.00
REPLACE FRT BUMPER PANEL, REINFORCEMENT & AFFECTED AREA								
E PNT98000								350.00
PAINT WORK ON FRT BUMPER PANEL								
E PNT88000								120.00
REMOVE & INSTALL FRT PARKING ASSISST FOR FACILITATE REPAIR								
M SUNDRY								40.00
PERFORM RUST PREVENTION								
A 54900099								30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								50.00
TO SUPPLY FRONT NUMBER PLATE WITH FRAME								
M SUNDRY								50.00
SUNDRIES								
M	LAMP ASSY,FOG,FR RH				1.00	348.00	23.00	267.96
M	GARNISH,FR BUMPER,RH				1.00	48.00	23.00	36.96
M	BRACKET,FR BUMPER SIDE,RH				1.00	18.00	23.00	13.86
M	GARNISH,FR BUMPER SIDE				1.00	220.00	23.00	169.40
M	GARNISH,FR BUMPER SIDE				1.00	112.00	23.00	86.24
M	MOULDING,FR BUMPER,RH				1.00	116.00	23.00	89.32
M	FACE,FR BUMPER				1.00	851.00	23.00	655.27
M	COVER,FR BUMPER				1.00	361.00	23.00	277.97
M	GARNISH,FR BUMPER SIDE				1.00	48.00	23.00	36.96
M	RIVET,FR BUMPER				10.00	5.00	23.00	38.50
M	TANK,WINDSHIELD WASHER				1.00	87.00	23.00	66.99
M	SENSOR,W/SHLD WASHER TANK				1.00	114.00	23.00	87.78
M	EXTENSION,FR BUMPER				1.00	517.00	23.00	398.09
M	BODY KIT, OUTLANDER				1.00	1554.00	20.00	1243.20
M	REINFORCEMENT,FR BUMPER				1.00	493.00	23.00	379.61
M	BAR,FR BUMPER GUARD				1.00	130.00	23.00	100.10
M	REINFORCEMENT,FR BMPR SIDE				1.00	22.00	23.00	16.94

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/LAM SZE JIA (LAN SIJIA)
	Reg No/Reg Date	SMN5700C / 19/08/201
	Date In/Mileage	14/12/2021/ 0
	Chassis No	GF7W0601876
	Engine No	4J11BH4181
	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim	D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	13/12/2021/ 11:23	BLK	282 / Kevin Leong	18622

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M REINF,FR BUMPER SIDE,LH	1.00	60.00	23.00	46.20
M REINF,FR BUMPER SIDE,RH	1.00	69.00	23.00	53.13
P GRILLE ASSY,RADIATOR	1.00	550.00	23.00	423.50

Estimate

Confirm & accepted by

Nett	6,147.98
7% GST on	6147.98
Total Payable	6,578.34

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.