

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21012553/EQF3E2

Date: 05/01/2022

REFERENCE

Insured/Claimant: GOH KIAN AIK Policy No: 7210002864
Date of Loss: 10/12/2021 Nature of Claim: OD Claim No: 0093347718SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJG5115P**
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGLH711842
Reg. Date: 21/01/2021 (Man. Year: 2020) Chassis No: KNAF5416MM5100877
Colour: White Odometer: 26217 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$94,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18 Rear Tyre Size: 225/40Z R18
Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm
Front Right Side: Pirelli 4 mm Rear Right Side: Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,224.40	1,930.80	2,293.60	54.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	980.00	1,150.00	53.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,354.40	2,910.80	3,443.60	54.19
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	6,054.40	2,610.80	3,443.60	56.88
+ GST 7.00/7.00% (S\$)	423.81	182.76	241.05	56.88
Nett Amount (S\$)	6,478.21	2,793.56	3,684.65	56.88

INSPECTION

Date of Assignment: 13/12/2021
Date Inspected: 15/12/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FR NUMBER PLATE WITH CASING	Cut	50.00 FS	*50.00 FS
2	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
3	1		*COVER-FR BUMPER	Dented	633.00 FL	*633.00 FL
4	1		*GRILLE-FRONT BUMPER	Crushed	485.00 FL	*485.00 FL
5	1		*GRILLE ASSY-RADIATOR	Cut	328.00 FL	*328.00 FL
6	1		*GARNISH-RADIATOR GRILLE	Not Necessary	38.00 FL	*- FL
7	1		*MOULDING-FRONT BUMPER, LH	Broken	216.00 FL	*216.00 FL
8	1		*LAMP ASSY-SIDE REPEATER, LH	Not Necessary	143.00 FL	*- FL
9	1		*AIR DUCT-FR BUMPER, LH	Not Necessary	14.00 FL	*- FL
10	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
11	1		*ULTRASONIC SENSOR ASSY-P.A.S (4PCS)	Broken(2Pcs Only)	652.00 FL	*326.00 FL
12	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
13	1		*LAMP ASSY-HEAD, LH	Not Necessary	2,210.00 FL	*- FL
14	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
15	1		*COVER-FR BUMPER FOG LAMP, LH (Supplementary)	Broken	15.00 FL	*15.00 FL
16	1		*WIRING ASSY-BUMPER EXTENSION (Supplementary)	Broken	207.00 FL	*207.00 FL
17	1		*ABSORBER-FRONT BUMPER ENERGY (Supplementary)	Broken	84.00 FL	*84.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,263.00	2,396.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,038.60	465.20
Total Parts (\$)	4,224.40	1,930.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FR BUMPER. REPAIR LHF FENDER	New	1,200.00	400.00
2	RESPRAY FR BUMPER & LHF FENDER	New	700.00	350.00
3	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
5	REMOVE & REFIT FR PARKING ASSIST SENSOR	New	80.00	80.00
			Gross Labour Cost (\$\$)	2,130.00
				980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >