



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for KIA CERATO 1.6 A GT LINE H370.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Includes account details for LAX00000 and operator Edwin Caina.

Main items table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various car parts and services like bumper repairs, wiring check, and diagnostic services.

Estimate

SURVEYOR NAME: Steve (LKK) 15/12/2021 9:39am
SURVEYOR SIGNATURE: [Signature]
DATE: [Blank]

REMARKS: PIP, My BML by
3 days 7% GST on

Summary table with columns: Net, Total Payable. Values: Net 6,109.60, Total Payable 6,537.27.

Confirm & accepted by the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- To be used for insurance claim only if permitted by the insurer
- Supplemental items to be resurveyed and priced
- Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.