

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 VEH# SLQ600L
 Signature:
 Accident Date 11/12/2021
 Date:



2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Model: HONDA VEZEL
 6-Jun-17

Veron
 TP EQ

Location PIE TOWARDS TUAS BEFORE STEVEN ROAD EXIT

3P: GBK5738R (EQ)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
✓ 1	1 pc	Front bumper <i>Distorted</i>	942.20	745	
✓ 2	1 pc	Front bumper enforcement <i>Distorted</i>	320.50	✓	
✓ 3	10 pcs	Front bumper clips <i>New</i>		40.00	30
✓ 4	2 pcs	Front bumper o/s & n/s retainer <i>New</i>	176.80	75	
✓ 5	2 pcs	Front bumper o/s & n/s fog lamp <i>cracked</i>	803.10	655	
✓ 6	2 pcs	Front bumper o/s & n/s fog lamp garnish cover <i>torn</i>	180.00	160.	
✓ 7	1 pc	Front bumper lower grille <i>cracked</i>	320.00	162	
✓ 8	1 pc	Front bumper lower diffuser <i>New</i>	665.30	X.	
✓ 9	1 pc	Front bumper enforcement bracket (upper) <i>cracked</i>	106.80	✓	
✓ 10	1 pc	Front grille <i>Smashed</i>	650.00	352	
✓ 11	1 pc	Front grille outer <i>Smashed</i>	580.60	225	
✓ 12	1 pc	Front grille emblem <i>New</i>	80.00	45	
✓ 13	4 pcs	Front grille clips <i>New</i>		16.00	✓
✓ 14	1 pc	Front bonnet <i>Distorted</i>	1,059.90	882	
✓ 15	2 pcs	Front bonnet o/s & n/s hinges <i>Best</i>	226.10	97	
✓ 16	1 pc	Front bonnet lock (lower) <i>Damaged</i>	220.00	95	
✓ 17	1 pc	Front bonnet lock garnish <i>New</i>	54.60	X	
✓ 18	1 pc	Front bonnet heat shield <i>Crumbled</i>	258.90	✓	
✓ 19	6 pcs	Front bonnet insulator clips <i>New</i>		24.00	✓
✓ 20	1 pc	Front bonnet seal <i>New</i>	108.75	X	
✓ 21	2 pcs	Front bonnet o/s & n/s seal <i>New</i>	220.00	X.	
✓ 22	16 pcs	Front bonnet seal clips <i>New</i>		64.00	X
✓ 23	2 pcs	Front bonnet o/s & n/s stopper (upper) <i>New</i>	120.40	X	
✓ 24	2 pcs	Front bonnet o/s & n/s stopper (lower) <i>New</i>	82.40	X.	
✓ 25	2 pcs	Front o/s & n/s head lamp <i>cracked</i>	4,405.60	3600.	
✓ 26	4 pcs	Front o/s & n/s head lamp clips <i>New</i>		16.00	✓
✓ 27	2 pcs	Front o/s & n/s head lamp support panel <i>New</i>	125.60	X	
✓ 28	1 pc	Front wiring harness <i>New</i>	1,845.60	X.	
✓ 29	1 pc	Front temperature sensor <i>Damaged</i>	86.80	✓	
✓ 30	1 pc	Front intake manifold <i>ut</i>	645.60	489	
✓ 31	1 pc	Front support panel <i>Distorted</i>	980.40	676.	
✓ 32	1 pc	Front support panel top garnish cover <i>Del-d</i>	290.40	190.	
✓ 33	4 pcs	Front support panel garnish cover clips <i>New</i>		24.00	✓
✓ 34	2 pcs	Front o/s & n/s fender <i>Bulged</i>	1,406.40	✓	
✓ 35	2 pcs	Front o/s & n/s fender "Hybrid" emblem <i>New</i>	165.60	✓	
✓ 36	2 pcs	Front o/s & n/s fender wheel guard <i>LH cracked</i>	456.00	228	
✓ 37	16 pc	Front o/s & n/s fender wheel guard clips <i>New</i>		64.00	20
✓ 38	2 pcs	Front o/s & n/s fender wheel arch garnish <i>LH torn</i>	240.00	120	
✓ 39	1 pc	Front cross member (lower) <i>New</i>	1,130.20	X	

✓	40	1 pc	Front wiper panel garnish	?	506.00	X		
✓	41	1 pc	Front wiper panel garnish seal	?	160.00	X		
✓	42	4 pcs	Front wiper panel garnish clips				16.00	X
✓	43	1 pc	Front seat	NE m	1,806.00	X		
✓	44	1 pc	Front air duct	Detoned	78.60	/		
✓	45	1 pc	Air cond condenser	Dented	967.00	✓	858	
✓	46	4 pcs	Air cond condenser mounting	NE m	120.00	✓	50	
✓	47	2 pcs	Air cond condenser pipe		490.00	X		
✓	48	1 pc	Air cond condenser fan motor	?	490.00	X		
✓	49	1 pc	Air cond condenser fan blade		206.00	X		
✓	50	1 pc	Air cond condenser fan guard	Dented	202.00	✓	126	
✓	51	1 pc	Radiator	Dented	1,470.00	✓	1250	
✓	52	1 pc	Coolant	NE m			90.00	50
✓	53	4 pcs	Radiator mounting	NE m	120.00	✓	50	
✓	54	1 pc	Radiator fan blade	NE m	240.00	X		
✓	55	1 pc	Radiator fan guard	cracked	230.00	✓	126	
✓	56	1 pc	Radiator fan motor	NE m	420.00	X		
✓	57	1 pc	Radiator expansion tank	?	80.00	X		
✓	58	1 pc	vacuum hose	?	85.00	/		
✓	59	1 pc	Engine air filter hose		160.00	/		
✓	60	1 pc	Engine air filter duct		127.55	X		
✓	61	1 pc	Engine air filter resonator tank	cracked	490.00	✓	298	
✓	62	1 pc	Engine under cover	NE m	490.00	X		
✓	63	1 pc	Horn (n/s)	NE m	120.00	X		
✓	64	1pc	Front windscreen	NE m	2,100.30	X		
✓	65	1pc	Front windscreen solar film	?			150.00	X
✓	66	4pcs	Front windscreen moulding	?			245.00	X
✓	67	1 pc	Front windscreen sealant				60.00	X
✓	68	1 pc	Front regn no plate	Polishing			80.00	50
✓	69	1 pc	Front regn no plate bracket	Dented			30.00	/
✓	70	1pc	Rear bumper	Distorted	840.00	✓	765	
✓	71	2pcs	Rear bumper o/s & n/s top garnish	Rit Dented	586.40	✓	293.20	195
✓	72	10pcs	Rear bumper clips	NE m			40.00	/
✓	73	2pcs	Rear bumper screw clips	NE m			20.00	X
✓	74	2pcs	Rear bumper o/s & n/s reflector	cracked	208.00	/		
✓	75	2pcs	Rear bumper o/s & n/s retainer	NE m	125.00	✓	79	
✓	76	2pcs	Rear reverse sensor	Damaged			280.00	202
✓	77	1pc	Rear end panel	Distorted	611.90	/		
✓	78	1 pc	Rear end panel inner trim	Dented	150.00	/		
✓	79	1 pc	Rear o/s tail lamp panel	Dented	213.00	✓		
✓	80	2pcs	Rear o/s & n/s tail lamp	cracked	940.00	✓		
✓	81	2pcs	Rear o/s & n/s tail lamp clips	NE m			20.00	/
✓	82	1pc	Rear tail gate	Distorted	1,178.00	✓	1100	
✓	83	pcs	Rear o/s & n/s tail gate stopper	NE m	80.00	X		
✓	84	1pc	Rear tail gate weatherstrip	NE m	265.00	/		
✓	85	1pc	Rear tail gate 'HONDA' emblem	?	55.00	/		
✓	86	1pc	Rear tail gate 'VEZEL' emblem	?	55.00	/		
✓	87	1pc	Rear tail gate 'Hybrid' emblem		54.50	/		
✓	88	1pc	Rear tail gate moulding	cracked	360.50	/		
✓	89	6pcs	Rear tail gate moulding clips	NE m			48.00	20
✓	90	1pc	Rear tail gate inner trim	cracked	310.00	✓		
✓	91	12pcs	Rear tail gate inner trim clips	NE m			34.00	/
✓	92	2pcs	Rear o/s & n/s tail gate inner trim	NE m	87.00	X		
✓	93	12pcs	Rear o/s & n/s tail gate inner trim clips	NE m			34.00	X
✓	94	1pc	Rear tail gate handle	NE m	80.00	X		
✓	95	1pc	Rear tail gate lock (Upper)	Dented	260.60	✓		
✓	97	1pc	Rear power window motor	Dented	460.30	✓	226	

✓	98	1pc	Rear tail gate lock (Lower) <i>new</i>	130.00	X		
✓	99	2 pcs	Rear tail gate o/s & n/s reflector <i>included</i>	845.60	/		
✓	100	1pc	Rear windscreen <i>shattered</i>	2,100.00	1267		
✓	101	1pc	Rear windscreen solar film <i>new</i>		150.00	✓	
✓	102	4pcs	Rear windscreen moulding <i>new</i>		145.00	✓	
✓	103	1 pc	Rear windscreen sealant <i>new</i>		60.00	✓	
✓	104	1pc	Rear boot floor o/s corner panel <i>Repair</i>	165.80	X		
✓	105	1 pc	Rear spare wheel tank <i>Distorted</i>	998.70	/		
✓	106	1 pc	Rear spare wheel board cover <i>Deland</i>	261.10	/		
✓	107	1 pc	Rear spare wheel board cover o/s & n/s chrome garnish <i>new</i>	165.40	X		
✓	108	1 pc	Rear spare wheel tank insulator <i>new</i>		200.00	X	
✓	109	1 pc	Rear spare wheel tank tool box <i>included</i>	245.60	/		
✓	110	1 pc	Rear o/s fender <i>Buckled</i>	1,005.60	885		
✓	111	2pcs	Rear o/s & n/s fender inner trim <i>Deland</i>	615.60	/		
✓	112	12pcs	Rear o/s & n/s fender inner trim clips <i>new</i>		34.00	✓	
✓	113	1 pc	Rear o/s wheel guard <i>torn</i>	210.30	148		
✓	114	2pcs	Rear o/s & n/s wheel arch <i>torn</i>	242.00	/		
✓	115	1 pc	Rear o/s air vent <i>new</i>	76.60	X		
✓	116	1 pc	Rear spare wheel tank under cover <i>Deland</i>	310.60	/		
✓	117	1 pc	Rear exhaust muffler <i>seized</i>	991.60	598		
✓	118	2 pc	Rear exhaust muffler mounting <i>new</i>	223.00	X		
✓	119	1 pc	Rear exhaust centre pipe <i>new</i>	845.60	X		
✓	120	1 pc	Rear buzzer <i>included</i>	210.00	78		
✓	121	1 pc	Rear battery air vent <i>Dehorned</i>	565.40	242		
X	122	1 pc	Rear regn no plate <i>F.M</i>		80.00	+	
X	123	1 pc	Rear regn no plate bracket <i>F.M</i>		30.00	+	
			26713.3	Sub Total:	47,241.70	2,094.00	0.00
			21370.64		20%	0%	0%
				After Less %:	37,793.36	2094.00	0.00

Labour	
1	To dismantle damaged parts, straighten & welding. 2,800.00 2600
2	To spray painting. 2,400.00 2200
3	To re align front & rear chassis frame. 180.00 X
4	To check wiring (Front) 200.00 30
5	To remove & replace air cond system, vacuum & refill gas. 120.00 60
6	To remove & replace radiator. 120.00 60
7	To re set electrical system. 380.00 X
8	To remove rear battery to facilitate repair 500.00 350
9	To remove & replace rear exhaust. 100.00 80
10	To remove and refit front windscreen 150.00 X
11	To refit rear windscreen 150.00 120
12	To remove & replace rear reverse sensor. 50.00 40
13	To check wiring. (Rear) 120.00 X.30
14	To re seal anti rust. 200.00 100
15	To remove upholstery and rear seats Sub Total: 7,470.00
16	To transfer tailgate fitting 150 300 250 Total: 47,357.36
	After Less 20%: 37,885.89

total: 28,333.64 Adm Lg 47,807.36
 2/s: 22.8K 2/c 18Days

Chan

Chan San Choon
 Director
 DipEng, AAE MIMI, MSAE(Aust)

