

ASS. REC. BY:

REF:

PMR/210125591Kny3

Kennerth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SEN 9173 J Yr Regn: 05, 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel c.c. 1496

Colour:

M. Grey A/C: Insured / Std / NI / NA

Sp. Reading:

342222 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

AU3 1217142

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD / Rlm or

Tyre Size:

F:

R:

215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Roadstone

Front

Rear

R/Bal.

4 mm

R/Bal.

3 mm

L/Bal.

4 mm

L/Bal.

3 mm

D.O.A.

10/12/21

D.O.I.

14/12/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/12/21 8:36am Carpal (Red, \$ 5076.80, 59%)

17/05/23 Re-confirmed with Chew Keong lump sum \$3200 and 5 days (red, \$5476.8, 63%)

Date/Time, File Pass to?

☐

: Prell. Report

1) 16/5/23

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) 1

# SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

VFM PTE LTD

46 Lentor Plain

Singapore 786548.

Not Attached  
11 By @ 3600 L/S \$3200  
Recovery After Repair on 17/05/23  
5 days

Date: 11-12-21

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: HONDA VEZEL HYBRID/SLN9173J	
IPC	Tailgate 951	1263.90
IPC	Tailgate weatherstrip	306.70
IPC	Tailgate Lock	237.50
IPC	Tailgate Lock Buzzer	96.20
IPC	Tailgate Inner Trim board	385.10
IPC	Tailgate Lock catch	67.80
IPC	Tailgate HYBRID Emblem	86.50
IPC	Tailgate VEZEL Emblem	79.60
		2523.3
IPC	Rear Windscreen Mldg.	118.60
IPC	Rear Windscreen Inner seal	93.80
IPC	Rear Gutter Panel	186.90
IPC	Rear End Panel	568.30
IPC	Cargo Box	437.50
IPC	Rear End Panel Top Garnish	195.70
	206	
IPC	Rear BUMPER Tow Cover	60.30
IPC	Rear BUMPER 726.70	896.20
IPC	Rear BUMPER Reflector O/S	109.50
IPC	Rear BUMPER Side Retainer O/S	93.60

# SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

Date: 11-12-21

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: SLN9173J	
1PC	Exhaust silencer	673.10
1set	Reverse sensor	220.00
1PC	Rear windscreen sealant	60.00
	To removed and replace the parts mentioned above	
	Panel beat and realign the necessary affected	
	areas.	950.00
	To check wiring system.	30.00
	To apply waterproof sealant on affected areas.	120.00
	To apply putty & spray painting on affected	850.00
	areas	
	To repair rear windscreen glass.	150.00
	To install reverse sensors.	60.00
	To carry out exhaust work	80.00
	To remove carpet & trimming & seat to enable	120.00
	repair.	
	To transfer tailgate accessories	80.00
	To wing charges	50.00
	LKK Auto Consultants hence notify	
	the Repairer of the following:	
	• To resurvey before/after spray painting	
	• To display damaged part(s) during resurvey	
	• Parts prices are subject to confirmation	
	• Third party survey is on a "Without Prejudice" basis	
	• No illegal modification(s) is allowed	
	• Supplementary item(s) must be resurveyed and	
	is subject to final approval from Insurance Company	

Acknowledged by Repairer  
Signature: of 1  
Date:

8676.8