



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0995/2021/JT
DATE : 9-Dec-21
WIP : 57584

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 17/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : M/S PREMIUM LEASING PTE LTD
ADDRESS : 9 LENG KEE ROAD
SINGAPORE 159090
TELEPHONE : HP +65 97997776
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : **SMV 4438 A**
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR : 30/9/2020
ENGINE NO : CZD C05091
CHASSIS NO : WAUZZZF37M1009469
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Dec-21
PLACE OF ACCIDENT : UPPER THOMSON ROAD BEFORE TRAFFIC
JUNCTION OF SIN MING AVE TOWARDS SIN
MING ROAD




55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 4438 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓ ✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	500 ✓
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 2,200.00	✓ ✓
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOORS.	S/N \$ 560.00	✓ ✓
5	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AD ALIGN TO POSTION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,400.00	1800 3000
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND BOTH FRONT DOORS.	\$ 6,000.00	2500 3300 ✓
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 16,824.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 4438 A

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER / le	1	\$ 2,016.00	1612.80	
2	FRONT BUMPER CONNECTING PIECE - cut	1	\$ 145.00	115.60	
3	FRONT BUMPER CLOSING ELEMENT - LH / RH ? x NN	2	\$ 118.00		
4	FRONT BUMPER GRILLE - CENTER - cut	1	\$ 217.00	173.20	
5	FRONT BUMPER GRILLE COVER - cut	1	\$ 51.00	40.80	
6	FRONT BUMPER GRILLE - LH / RH ? x NN	2	\$ 220.00	176	
7	FRONT BUMPER CLOSING ELEMENT ? x NN	1	\$ 190.00		
8	FRONT BUMPER SPOILER ? x NN	1	\$ 383.00	306.40	
9	FRONT BUMPER BRACKET ? x NN	1	\$ 21.00		
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH ? x NN	2	\$ 306.00	244.12 122	
11	RADIATOR GRILLE - CAA	1	\$ 1,433.00	1146.40	
12	FRONT STRIKER PLATE - CRA.	1	\$ 244.00	194.80	
13	RADIATOR GRILLE CAP - mis	1	\$ 45.00	35.60	
14	RADIATOR BRACKET ? x NN	1	\$ 41.00	32.48 x	
15	FRONT CAMERA ? x	1	\$ 1,141.00	912.80 x	
16	FRONT BUMPER WIRING SET ? - cut	1	\$ 676.00	540.80	
17	FRONT BUMPER REINFORCEMENT BEAM - BT. (photo)	1	\$ 916.00	732.40	
18	FRONT BUMPER GUIDE SECTION - LH / RH ? x CAA	2	\$ 78.00	60.96	
19	FRONT BUMPER TOP COVER ? x CAA	1	\$ 123.00	98	
20	FRONT BUMPER FOAM FILLER PIECE - le (photo)	1	\$ 102.00	81.60	
SUB TOTAL SPARE PARTS			\$ 8,466.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 4438 A

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	CAUTION STICKER <i>OK</i>	1	\$ 14.00	10.88
22	AIR CON STICKER <i>OK</i>	1	\$ 8.00	5.68
23	HORN - LH / RH <i>OK</i>	2	\$ 267.00	
24	HORN SUPPORT - LH / RH <i>OK</i>	2	\$ 44.00	
25	FRONT PARKING AID SENSOR <i>OK</i>	4	\$ TBC	
26	FRONT PARKING AID SENSOR SEAL RING <i>OK</i>	4	\$ 9.00	
27	FRONT FENDER - LH / RH <i>OK</i>	2	\$ 2,572.00	
28	FRONT FENDER ATTACHEMENT PARTS <i>OK</i>	1	\$ 63.00	
29	FRONT FENDER BRACE - LH / RH <i>OK</i>	2	\$ 176.00	
30	FRONT FENDER BRACKET - LH / RH <i>OK</i>	2	\$ 64.00	
31	FRONT WHEEL HOUSING LINER - LH <i>OK</i>	1	\$ 240.00	
32	FRONT WHEEL HOUSING LINER - RH <i>OK</i>	1	\$ TBC	
33	FRONT WHEEL HOUSING LINER ATTACHEMENT PARTS <i>OK</i>	1	\$ 101.00	
34	FRONT WHEEL HOUSING COVER - LH / RH <i>OK</i>	2	\$ 32.00	
35	BONNET <i>OK</i>	1	\$ 3,508.00	2806.40
36	BONNET HINGE - LH / RH <i>OK</i>	2	\$ 146.00	115.52
37	BONNET ATTACHEMENT PARTS <i>OK</i>	1	\$ 296.00	
38	BONNET STRIKER - LH / RH <i>OK</i>	2	\$ 220.00	175.20
39	BONNET SOUND ABSORBER <i>OK</i>	1	\$ 219.00	
40	BONNET IMPACT PROTECTION - CENTER <i>OK</i>	1	\$ 28.00	21.84
SUB TOTAL SPARE PARTS		:	\$ 8,007.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6841 1183
EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 4438 A

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	PLENUM CHAMBER <i>2/ ✓ Cut</i>	1	\$	129.00	103.20
42	BONNET LOCK MICROSWITCH - LH & RH <i>2/ ✓ BT</i>	2	\$	427.00	341.60
43	BONNET BOWDEN CABLE - CENTER <i>2/ x</i>	1	\$	58.00	
44	BONNET BOWDEN CABLE CAP <i>2/ x</i>	1	\$	10.00	
45	BONNET RELEASE ELEMENT <i>2/ x</i>	1	\$	58.00	
46	BONNET RELEASE LEVER <i>2/ ✓ Cut</i>	1	\$	14.00	11.20
47	HEADLIGHT MOUNTING - LH / RH <i>2/ ✓ CPA</i>	2	\$	236.00	188.80
48	HEADLIGHT - LH / RH <i>2/ CPA</i>	2	\$	11,178.00	8942.40
49	HEADLIGHT POWER MODULE <i>2/ x</i>	2	\$	1,516.00	
50	HEADLIGHT HEAT SINK <i>2/ x</i>	2	\$	1,562.00	
51	HEADLIGHT HOSE - LH / RH <i>2/ x</i>	2	\$	48.00	
52	HEADLIGHT SPACER <i>2/ x</i>	2	\$	80.00	
53	LIFT CYCLINDER - LH / RH <i>2/ x</i>	2	\$	420.00	
54	LIFT CYCLINDER HOSE <i>2/ ✓ Cut</i>	1	\$	80.00	63.44
55	RADIATOR COOLANT LOCK CARRIER <i>2/ ✓ CPA</i>	1	\$	1,272.00	1017.60
56	AIRCOND CONDENSER FLUID RESERVOIR <i>2/ ✓ Cut (1/4)</i>	1	\$	551.00	440.80
57	AIRCOND CONDENSER PRESSURE HOSE <i>2/ x</i>	1	\$	330.00	
58	AIRCOND CONDENSER DISCHARGE HOSE <i>2/ x</i>	1	\$	337.00	
59	OUTSIDE TEMPERATURE SENSOR BRACKET <i>2/ ✓ CPA</i>	1	\$	7.00	5.52
60	TEMPERATURE SENSOR EXTERNAL <i>2/ x MN</i>	1	\$	59.00	
SUB TOTAL SPARE PARTS		:	\$	18,372.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 4438 A

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT		REMARKS
61	RADIATOR COOLANT COOLER ? x SMV	1	\$	1,035.00	
62	RADIATOR COOLANT COOLER INNER ? x	1	\$	920.00	
63	RADIATOR AIR GUIDE - LOWER ? ✓	1	\$	42.00	33.04
64	RADIATOR AIR GUIDE - LH / RH ? ✓	2	\$	76.00	59.52
65	RADIATOR AIR GUIDE - UPPER ? ✓	1	\$	42.00	33.04
66	RADIATOR COOLANT ? ✓ MBL	6	\$	266.00	212.64
67	FRONT WHEEL COVER - LH / RH ✓ MBL	2	\$	536.00	428.80
68	FRONT WINDOW SLOT SEAL TRIM STRIP OUTER - LH / RH X NN	2	\$	448.00	
69	FRONT WINDOW GUIDE TRIM STRIP - LH / RH X NN	2	\$	514.00	
70	FRONT NO PLATE ✓ BT	S/N	\$	60.00	60
71	SUNDRIES ? ✓ MBL		\$	400.00	145.28
TOTAL SPARE PARTS			:	\$	39,184.00
TOTAL LABOUR CHARGES			:	\$	16,824.00
GRAND TOTAL			:	\$	56,008.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Eno Qiao
19/12/21
TBA
Not Authorized.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

7 Days .
before part photos

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date:

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0995/2021/JT
20-Dec-21
CHANG
1 of 1
SMV 4438 A
AUDI Q3 1.4 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FRONT CAMERA SECURING PLATE <i>ANN</i>	\$ 33.00	X
2	WASH WATER RESERVOIR <i>de</i>	\$ 220.00	176
3	WATER RESERVOIR SEAL <i>nee</i>	\$ 59.00	146.64
4	AIR FILTER <i>com</i>	\$ 239.00	19120
5	INTAKE AIR GUIDE <i>com</i>	\$ 20.00	15.36
6	INTAKE AIR GUIDE <i>com</i>	\$ 29.00	26.16
GRAND TOTAL		\$ 600.00	

For Premium Automobiles Pte Ltd

Authorised Signature