

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 4438 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	/
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	500
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 2,200.00	/
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOORS.	S/N \$ 560.00	/
5	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AD ALIGN TO POSTION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,400.00	1500 + 1500 /
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND BOTH FRONT DOORS.	\$ 6,000.00	1500 3300
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	/
TOTAL LABOUR CHARGES		: \$ 16,824.00	

Additional
3 days




Car-in

16/12/21.

wip: 57584

Kiam/keang



AIR - Gus Qiang

- 7 days

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHA1@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 4438 A

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER / le	1	\$ 2,016.00	
2	FRONT BUMPER CONNECTING PIECE - cut	1	\$ 145.00	
3	FRONT BUMPER CLOSING ELEMENT - LH / RH ?	2	\$ 118.00	
4	FRONT BUMPER GRILLE - CENTER - cut	1	\$ 217.00	
5	FRONT BUMPER GRILLE COVER - cut	1	\$ 51.00	
6	FRONT BUMPER GRILLE LH / RH < LH? RH?	2	\$ 220.00	
7	FRONT BUMPER CLOSING ELEMENT ?	1	\$ 190.00	
8	FRONT BUMPER SPOILER ? cut	1	\$ 383.00	
9	FRONT BUMPER BRACKET ?	1	\$ 21.00	
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH < LH? RH?	2	\$ 306.00	
11	RADIATOR GRILLE - CAA	1	\$ 1,433.00	
12	FRONT STRIKER PLATE - CAA	1	\$ 244.00	
13	RADIATOR GRILLE CAP - MIS	1	\$ 45.00	
14	RADIATOR BRACKET ?	1	\$ 41.00	
15	FRONT CAMERA ??	1	\$ 1,141.00	
16	FRONT BUMPER WIRING SET ? cut	1	\$ 676.00	
17	FRONT BUMPER REINFORCEMENT BEAM - BT. (photo)	1	\$ 916.00	
18	FRONT BUMPER GUIDE SECTION LH / RH ? cut	2	\$ 78.00	
19	FRONT BUMPER TOP COVER ? cut	1	\$ 123.00	
20	FRONT BUMPER FOAM FILLER PIECE - le (photo)	1	\$ 102.00	
SUB TOTAL SPARE PARTS			\$ 8,466.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 4438 A

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	CAUTION STICKER ? <i>new</i>	1	\$ 14.00	
22	AIR CON STICKER ? <i>new</i>	1	\$ 8.00	
23	HORN - LH / RH ?	2	\$ 267.00	
24	HORN SUPPORT - LH / RH ?	2	\$ 44.00	
25	FRONT PARKING AID SENSOR ?	4	TBC	
26	FRONT PARKING AID SENSOR SEAL RING <i>new</i>	4	\$ 9.00	
27	FRONT FENDER - LH / RH X <i>repair</i>	2	\$ 2,572.00	
28	FRONT FENDER ATTACHEMENT PARTS ?	1	\$ 63.00	
29	FRONT FENDER BRACE - LH / RH ?	2	\$ 176.00	
30	FRONT FENDER BRACKET - LH / RH ?	2	\$ 64.00	
31	FRONT WHEEL HOUSING LINER - LH ?	1	\$ 240.00	
32	FRONT WHEEL HOUSING LINER - RH ?	1	TBC	
33	FRONT WHEEL HOUSING LINER ATTACHEMENT PARTS ?	1	\$ 101.00	
34	FRONT WHEEL HOUSING COVER - LH / RH X <i>new</i>	2	\$ 32.00	
35	BONNET <i>new</i>	1	\$ 3,508.00	
36	BONNET HINGE LH RH ?	2	\$ 146.00	
37	BONNET ATTACHEMENT PARTS ?	1	\$ 296.00	
38	BONNET STRIKER LH RH ? <i>bf</i>	2	\$ 220.00	
39	BONNET SOUND ABSORBER ?	1	\$ 219.00	
40	BONNET IMPACT PROTECTION - CENTER ? <i>new</i>	1	\$ 28.00	
SUB TOTAL SPARE PARTS		:	\$ 8,007.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 4438 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	PLENUM CHAMBER ? cut ✓	1	\$ 129.00	
42	BONNET LOCK MICROSWITCH LH & RH ? bt ✓	2	\$ 427.00	
43	BONNET BOWDEN CABLE - CENTER ? bt ✓	1	\$ 58.00	
44	BONNET BOWDEN CABLE CAP ?	1	\$ 10.00	
45	BONNET RELEASE ELEMENT ?	1	\$ 58.00	
46	BONNET RELEASE LEVER ? cut ✓	1	\$ 14.00	
47	HEADLIGHT MOUNTING - LH / RH ? cra ✓	2	\$ 236.00	
48	HEADLIGHT - LH / RH ✓ cra	2	\$ 11,178.00	
49	HEADLIGHT POWER MODULE ?	2	\$ 1,516.00	
50	HEADLIGHT HEAT SINK ?	2	\$ 1,562.00	
51	HEADLIGHT HOSE - LH / RH ?	2	\$ 48.00	
52	HEADLIGHT SPACER ?	2	\$ 80.00	
53	LIFT CYLINDER - LH / RH ?	2	\$ 420.00	
54	LIFT CYLINDER HOSE ? cut ✓	1	\$ 80.00	
55	RADIATOR COOLANT LOCK CARRIER ? cra ✓	1	\$ 1,272.00	
56	AIRCOND CONDENSER FLUID RESERVOIR ? ✓ cut (photo)	1	\$ 551.00	
57	AIRCOND CONDENSER PRESSURE HOSE ?	1	\$ 330.00	
58	AIRCOND CONDENSER DISCHARGE HOSE ?	1	\$ 337.00	
59	OUTSIDE TEMPERATURE SENSOR BRACKET ? cra ✓	1	\$ 7.00	
60	TEMPERATURE SENSOR EXTERNAL ?	1	\$ 59.00	
SUB TOTAL SPARE PARTS		:	\$ 18,372.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 4438 A

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	RADIATOR COOLANT COOLER ?	1	\$	1,035.00
62	RADIATOR COOLANT COOLER INNER ?	1	\$	920.00
63	RADIATOR AIR GUIDE - LOWER ? <i>coa</i>	1	\$	42.00
64	RADIATOR AIR GUIDE LH / RH ? <i>coa</i>	2	\$	76.00
65	RADIATOR AIR GUIDE - UPPER ? <i>coa</i>	1	\$	42.00
66	RADIATOR COOLANT ? <i>nee</i>	6	\$	266.00
67	FRONT WHEEL COVER - LH / RH <i>etc.</i>	2	\$	536.00
68	FRONT WINDOW SLOT SEAL TRIM STRIP OUTER - LH / RH <i>X</i>	2	\$	448.00
69	FRONT WINDOW GUIDE TRIM STRIP - LH / RH <i>X</i>	2	\$	514.00
70	FRONT NO PLATE <i>BT</i>	S/N	\$	60.00
71	SUNDRIES ?		\$	400.00
TOTAL SPARE PARTS		:	\$	39,184.00
TOTAL LABOUR CHARGES		:	\$	16,824.00
GRAND TOTAL		:	\$	56,008.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.