

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21012563/GVCE2**Date:** 27/09/2022**REFERENCE**

Insured/Claimant:	HONG SUNG-MO	Policy No:	2100419323	
Date of Loss:	01/12/2021	Nature of Claim:	OD	Claim No: 6747134074SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH2460G		
Make & Model:	AUDI A7 SPORTBACK, 2.0 TFSI (A)	Engine No:	CYP003416
Reg. Date:	30/06/2015 (Man. Year: 2015)	Chassis No:	WAUZZZ4G8FN093920
Colour:	Grey	Odometer:	48771 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$87,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/40ZR19	Rear Tyre Size:	255/40ZR19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,626.00	4,600.48	20,025.52	81.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	22,932.00	9,257.00	13,675.00	59.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	47,558.00	13,857.48	33,700.52	70.86
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	45,958.00	12,257.48	33,700.52	73.33
+ GST 7.00/7.00% (S\$)	3,217.06	858.02	2,359.04	73.33
Nett Amount (S\$)	49,175.06	13,115.50	36,059.56	73.33

INSPECTION

Date of Assignment:	13/12/2021	
Date Inspected:	10/12/2021	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days	

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR-LH	Repair	4,831.00 FS	-
2	1		*FRONT WING DOOR STONE GUARD FILM-LH	Necessary	114.00 FS	*91.20 FS
3	1		*BONDING AGENT	Not Necessary	49.00 FS	-
4	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	-
5	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
6	1		*REAR BUFFER BUMP STOP-LH	Not Necessary	15.00 FS	*- FS
7	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	187.00 FS	*- FS
8	1		*FRONT DOOR CATCH-LH	Not Necessary	128.00 FS	*- FS
9	1		*FRONT WING MIRROR MOUNTING-LH	Not Necessary	1,590.00 FS	*- FS
10	1		*FRONT MIRROR CONNECTOR PLUG	Not Necessary	16.00 FS	*- FS
11	1		*FRONT MIRROR HOUSING PRIMED-LH	Repair	304.00 FS	*- FS
12	1		*FRONT SIGNAL INDICATOR	Cut	141.00 FS	*112.40 FS
13	1		*FRONT MIRROR GLASS CARRIER PLATE-LH	Not Necessary	1,229.00 FS	*- FS
14	1		*REAR DOOR-LH	Buckled	4,831.00 FS	*3,864.80 FS
15	1		*REAR DOOR OUTER SEAL	Necessary	172.00 FS	*135.60 FS
16	1		*BONDING AGENT	Not Necessary	49.00 FS	-
17	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	-
18	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
19	1		*REAR DOOR SEAL BRACKET-LH	Not Necessary	4.00 FS	*- FS
20	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	87.00 FS	*- FS
21	1		*FRONT DOOR CATCH-LH	Not Necessary	128.00 FS	*- FS
22	1		*FRONT DOOR HINGE LOWER-LH	Not Necessary	170.00 FS	*- FS
23	1		*REAR DOOR SIDE PANEL-LH	Repair	4,621.00 FS	-
24	1		*REAR SIDE WINDOW-LH	Not Necessary	682.00 FS	-
25	1		*REAR SILL TRIM STRIP-LH	Not Necessary	158.00 FS	-
26	1		*REAR WHEEL HOUSING LINER-LH	Not Necessary	275.00 FS	*- FS
27	1		*REAR SIDE MEMBER TRIM-LH	Not Necessary	929.00 FS	*- FS
28	1		*REAR SILL PANEL ATTACHMENT PARTS	Necessary	130.00 FS	*104.00 FS
29	1		*REAR SILL PANEL ADHESIVE TAPE ATTACHMENT PARTS	Necessary	16.00 FS	*12.48 FS
30	1		*REAR SILL PANEL SUPPORT-LH	Not Necessary	6.00 FS	*- FS
31	1		*REAR STONE GUARD FILM-LH	Not Necessary	118.00 FS	*- FS
32	1		*ALUMINUM RIM	Repair	2,114.00 FS	*- FS
33	1		*ARYLIC SEALANT	Not Necessary	180.00 FS	-
34	1		*CAVITY WAX	Not Necessary	140.00 FS	-
35	1		*STONE CHIP	Not Necessary	180.00 FS	-
36	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
37	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	-
38	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 24,626.00 4,600.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	900.00	900.00
3	TO RENEW 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER	New	300.00	-
4	TO INSTALL SOLAR FILM FOR 1/4 GLASS	New	400.00	0.00
5	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS	New	200.00	-
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT.INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	480.00
7	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS,DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	480.00
8	TO DISMANTLE AND REINSTALL REAR BUMPER.TO CUT OUT AND WELD LHS REAR FENDER.TO RENEW LHS SILL PANEL TRIM,LHS FRONT DOOR AND LHS REAR DOOR.RE-ORGANOZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	9,000.00	3,200.00
9	TO RESPRAY LHS FRONT DOOR,LHS WING MIRROR COVER,DOOR HANDLES,LHS REAR DOOR,HINGES,LHS SILL PANEL TRIM,LHS REAR FENDER,LHS SILL PANEL TRIM,DRAIN CHANNEL,DOOR ENTRANCE,ROOF CHANNEL AND REAR END PANELLING	New	8,500.00	3,725.00
10	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT TEST	New	280.00	280.00
11	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			22,932.00	9,257.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >