## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Date: 13 Dec 2021 Attn: Nadaraja, Deeban

# **Preliminary Advice**

Vehicle No : SJH2460G Accident Date : 01/12/2021 Make : AUDI A7 SPORTBACK Policy No. : 2100419323 : 13/12/2021 Excess Assignment Date : S\$0.00 Est. Duration of Repair Date of Inspection : 10/12/2021 : 14

Inspection At : PREMIUM AUTOMOBILES PTE LTD

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 47,558.00 |
|-----------------------------|------|-----------|
| Revised Amount              | :S\$ | 31,271.00 |
| Check Items (Estimated)     | :S\$ | 2,555.00  |
| Total                       | :S\$ | 33,826.00 |

:S\$ Lump Sum Repair

#### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 87,000.00 COE / PARF Rebate :S\$ 68,383.00

Salvage Value :S\$

Margin for Repair :S\$ 18,617.00

#### Remarks

| ( | ) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kin | ıdly |
|---|---|--|------|
|   |   | let us have your authorisation.  |      |

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments: Pending repair cost from repairer.

> Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.