

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0982/2021/JT
DATE : 3-Dec-21
WIP : 56824

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 10/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Guo Qiang

7 days - ok - Johnny Boo

7-Sep-22

OWNER'S NAME : MR HONG SUNG-MO
ADDRESS : 7 ARDMORE RESIDENCE
#23-01
SINGAPORE 259954
TELEPHONE : HP +65 91171894
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100419323-06
VEHICLE NO : **SJH 2460 G**
MODEL CODE : AUDI A7 SB 2.0 TFSI
MODEL YEAR : 30/6/2015
ENGINE NO : CYP 003416
CHASSIS NO : WAUZZZ4G8FN93920
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Dec-21
PLACE OF ACCIDENT : LAVENDER ROAD BEFORE
INTERSECTION OF BENDEMEER

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJH 2460 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	
2	TO REMOVE AND TRASNFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	900.00	\$ 900.00
3	TO RENEW 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER.	S/N \$	300.00	
4	TO INSTALLL SOLAR FILM FOR 1/4 GLASS.	S/N \$	400.00	
5	TO CARRY OUT WATER SEEPAGE TEST FOR 1/4 GLASS.	S/N \$	200.00	
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	\$ 480.00
SUB TOTAL LABOUR CHARGES		:	\$ 3,560.00	\$ 1,380.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJH 2460 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		c/f	\$	2,750.00
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	\$ 480.00
8	TO DISMANTLE AND REINSTALL REAR BUMPER. TO CUT OUT AND WELD LHS REAR FENDER. TO RENEW LHS SILL PANEL TRIM, LHS FRONT DOOR AND LHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	9,000.00	\$ 3,200.00
9	TO RESPRAY LHS FRONT DOOR, LHS WING MIRROR COVER, DOOR HANDLES, LHS REAR DOOR, HINGE, LHS SILL PANEL TRIM, LHS REAR FENDER, LHS SILL PANEL TRIM, DRAIN CHANNEL, DOOR ENTRANCE, ROOF CHANNEL AND REAR END PANELLING.	\$	8,500.00	\$ 3,725.00
10	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT TEST.	S/N \$	280.00	\$ 280.00
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
	TOTAL LABOUR CHARGES	:	\$ 22,932.00	\$ 9,257.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJH 2460 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT DOOR - LH	1	\$ 4,831.00		
2	FRONT WING DOOR STONE GUARD FILM - LH	1	\$ 114.00	\$	91.20
3	BONDING AGENT	1	\$ 49.00		
4	CLEANING SOLUTION	1	\$ 68.00		
5	APPLICATOR	1	\$ 8.00		
6	REAR BUFFER BUMP STOP- LH	1	\$ 15.00		
7	FRONT DOOR ATTACHEMENT PARTS	1	\$ 187.00		
8	FRONT DOOR CATCH - LH	1	\$ 128.00		
9	FRONT WING MIRROR MOUNTING - LH	1	\$ 1,590.00		
10	FRONT MIRROR CONNECTOR PLUG	1	\$ 16.00		
11	FRONT MIRROR HOUSING PRIMED - LH	1	\$ 304.00		
12	FRONT SIGNAL INDICATOR	1	\$ 141.00	\$	112.40
13	FRONT MIRROR GLASS CARRIER PLATE - LH	1	\$ 1,229.00		
14	REAR DOOR - LH	1	\$ 4,831.00	\$	3,864.80
15	REAR DOOR OUTER SEAL	1	\$ 172.00	\$	135.60
16	BONDING AGENT	1	\$ 49.00		
17	CLEANING SOLUTION	1	\$ 68.00		
18	APPLICATOR	1	\$ 8.00		
19	REAR DOOR SEAL BRACKET - LH	1	\$ 4.00		
20	REAR DOOR ATTACHEMENT PARTS	1	\$ 87.00		
SUB TOTAL SPARE PARTS		:	\$ 13,899.00	\$	4,204.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJH 2460 G

S/N	PARTS DESCRIPTION	QTY	DAMAGED PAI	
			S/NETT	
		<i>c/f</i>		
21	FRONT DOOR CATCH - LH	1	\$	128.00
22	FRONT DOOR HINGE LOWER - LH	1	\$	170.00
23	REAR DOOR SIDE PANEL - LH	1	\$	4,621.00
24	REAR SIDE WINDOW - LH	1	\$	682.00
25	REAR SILL TRIM STRIP - LH	1	\$	158.00
26	REAR WHEEL HOUSING LINER - LH	1	\$	275.00
27	REAR SIDE MEMBER TRIM - LH	1	\$	929.00
28	REAR SILL PANEL ATTACHEMENT PARTS	1	\$	130.00
29	REAR SILL PANEL ADHESIVE TAPE ATTACHEMENT PARTS	1	\$	16.00
30	REAR SILL PANEL SUPPORT - LH	1	\$	6.00
31	REAR STONE GUARD FILM - LH	1	\$	118.00
32	ALUMINIUM RIM	1	\$	2,114.00
33	ARYLIC SEALANT	S/N	\$	180.00
34	CAVITY WAX	S/N	\$	140.00
35	STONE CHIP	S/N	\$	180.00
36	METAL FILLER POWDER	S/N	\$	280.00
37	1/4 GLASS SEALANT	S/N	\$	100.00
38	SUNDRIES		\$	500.00
TOTAL SPARE PARTS		:	\$	24,626.00
TOTAL LABOUR CHARGES		:	\$	22,932.00
GRAND TOTAL		:	\$	47,558.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-31/08/22



RTS & PRICES

<i>REMARKS</i>	
\$	<i>4,204.00</i>

\$ *104.00*

\$ *12.48*

\$ *280.00*

\$	<i>4,600.48</i>
----	-----------------

\$	<i>9,257.00</i>
----	-----------------

\$	<i>13,857.48</i>
----	------------------



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT