

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21012569/BPA3Q2**Date:** 17/03/2022REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2070167989   |
| <b>Claimant Vehicle No :</b> | SMC9425D                             | <b>Insured Vehicle No :</b> | SKB1218S     |
| Date of Loss:                | 11/12/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 1375591016SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SMC9425D</b>                   | Engine No:  | G4FGFH796994      |
| Make & Model:               | KIA FORTE K3, 1.6 SX S/R HID (A)  | Chassis No: | KNAFZ411MF5523668 |
| Reg. Date:                  | 14/10/2015 (Man. Year: 2015)      | Odometer:   | 135846 km         |
| Colour:                     | Grey                              |             |                   |
| Engine Capacity:            | 1591 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 225/45 R17    | Rear Tyre Size:  | 225/45 R17    |
| Front Left Side:  | Michelin 5 mm | Rear Left Side:  | Michelin 5 mm |
| Front Right Side: | Michelin 5 mm | Rear Right Side: | Michelin 5 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                                       | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                                       | 7,800.50          | 1,572.78          | 6,227.72          | 79.84         |
| Miscellaneous Items                                         | 0.00              | 0.00              | 0.00              |               |
| Labour                                                      | 2,750.00          | 1,000.00          | 1,750.00          | 63.64         |
| Paintwork Labour                                            | 0.00              | 0.00              | 0.00              |               |
| Towing                                                      | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>                         | <b>10,550.50</b>  | <b>2,572.78</b>   | <b>7,977.72</b>   | <b>75.61</b>  |
| <b>Approved Total (Overridden) (S\$)</b>                    |                   | <b>2,050.00</b>   |                   |               |
| <b>(S\$)</b>                                                | 10,550.50         | 2,050.00          | 8,500.50          | 80.57         |
| <b>+ GST 7.00/7.00% (S\$)</b>                               | 738.54            | 143.50            | 595.04            | 80.57         |
| <b>Nett Amount (S\$)</b>                                    | <b>11,289.04</b>  | <b>2,193.50</b>   | <b>9,095.54</b>   | <b>80.57</b>  |
| <b>+ Car Rental (8.0 x S\$100.00/day + 7.00% GST) (S\$)</b> |                   | 856.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                               |                   | 7.45              |                   |               |
| <b>Nett Liability (S\$)</b>                                 |                   | <b>3,056.95</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>                          |                   | <b>3,050.00</b>   |                   |               |

INSPECTION

|                             |                          |                                              |
|-----------------------------|--------------------------|----------------------------------------------|
| Date of Assignment:         | 13/12/2021               | Team Autopro Pte Ltd (sin Ming) (HQ)         |
| Date Inspected:             | 13/12/2021 Inspected At: | 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY |
| Estimated Period of Repair: | 6.0 days                 | Singapore 575722                             |

**Adjuster:** Lim Teow Guan**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars                        | Condition              | Repairer's  | Amount     |
|-----|-----|----------|------------------------------------|------------------------|-------------|------------|
| 1   | 1   |          | *BOOTLID                           | Not Damaged            | 826.00 FL   | *- FL      |
| 2   | 1   |          | *BOOTLID LOGO                      | Not Damaged            | 62.00 FL    | *- FL      |
| 3   | 2   |          | *BOOTLID LAMP                      | Not Damaged            | 852.00 FL   | *- FL      |
| 4   | 1   |          | *BOOTLID LOCK                      | Not Damaged            | 560.00 FL   | *- FL      |
| 5   | 1   |          | *REAR BUMPER                       | Broken                 | 716.00 FL   | *576.40 FL |
| 6   | 2   |          | *REAR BUMPER SIDE RETAINER         | Necessary              | 128.00 FL   | *56.00 FL  |
| 7   | 1   |          | *REAR BUMPER REINFORCEMENT         | Broken                 | 380.00 FL   | *380.00 FL |
| 8   | 1   |          | *REAR BUMPER REINFORCEMENT BRACKET | O/S Bent               | 448.00 FL   | *80.30 FL  |
| 9   | 1   |          | *REAR BUMPER SPONGE                | No such part           | 187.00 FL   | *- FL      |
| 10  | 4   |          | *REAR BUMPER REVERSE SENSORS       | Scratched (2 PCS ONLY) | 800.00 FL   | *200.00 FL |
| 11  | 1   |          | *REAR BUMPER DIFFUSER              | Broken                 | 258.00 FL   | *258.00 FL |
| 12  | 1   |          | *REAR BUMPER REFLECTOR             | O/S Broken             | 156.00 FL   | *65.00 FL  |
| 13  | 5   |          | *REAR BUMPER STAY                  | No such part           | 290.00 FL   | *- FL      |
| 14  | 1   |          | *REAR END PANEL                    | Repair                 | 583.00 FL   | *- FL      |
| 15  | 1   |          | *REAR END PANEL TOP GARNISH        | Broken                 | 183.00 FL   | *98.50 FL  |
| 16  | 2   |          | *TAIL LAMP                         | Not Damaged            | 1,052.00 FL | *- FL      |
| 17  | 2   |          | *TAIL LAMP INNER SPONGE            | Not Damaged            | 120.00 FL   | *- FL      |
| 18  | 2   |          | *TAIL LAMP PANEL                   | Not Damaged            | 660.00 FL   | *- FL      |
| 19  | 2   |          | *TAIL LAMP LOWER BRACKET           | Not Damaged            | 184.00 FL   | *- FL      |
| 20  | 2   |          | *TAIL LAMP INNER SPONGE CLIPS      | No such part           | 100.00 FS   | *- FS      |
| 21  | 10  |          | *REAR BUMPER CLIPS                 | Necessary              | 50.00 FS    | *30.00 FS  |
| 22  | 1   |          | *SUNDRIES                          | Not Necessary          | 50.00 FS    | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                    |          |          |
|----------------------------------------------------|----------|----------|
| Sub Total (S\$)                                    | 8,645.00 | 1,744.20 |
| - List Item Discount on L Items 10.00/10.00% (S\$) | 844.50   | 171.42   |
| Total Parts (S\$)                                  | 7,800.50 | 1,572.78 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars                   | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                               |          |                 |                 |
| 1                               | PANEL BEATING                 | New      | 1,200.00        | 800.00          |
| 2                               | RUST PROOFING                 | New      | 150.00          | 0.00            |
| 3                               | SPRAY PAINTING                | New      | 1,200.00        | 200.00          |
| 4                               | CHECK WIRING                  | New      | 100.00          | 0.00            |
| 5                               | RESET & RE-PROGRAM FAULT CODE | New      | 100.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                               |          | <b>2,750.00</b> | <b>1,000.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >