



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:LYNN			Ref: CC4/ASM21012570/Uga3q2 Date: 26/05/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
<b>Insured Veh.</b>	XD 797D	<b>Veh. Inspected</b>	SLQ 5904C	
<b>Policy No.</b>	GA568854	<b>Coverage (\$)</b>	0.00	
<b>Claim No.</b>	S1M03NYF	<b>Excess (\$)</b>	0.00	
<b>Assign From</b>		<b>Assign Date</b>	13/12/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
<b>Make &amp; Model</b>	TOYOTA PICNIC (A)	<b>c.c</b>	1998	
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009	
<b>Chassis No.</b>	JTEGH23B000026996	<b>Colour</b>	GREY	
<b>Odometer</b>	205689 KM	<b>Steering</b>	IN ORDER	
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM	
<b>General</b>	GOOD			
<b>3. Conditions of Tyres</b>				
	<b>Size</b>	<b>Make</b>	<b>Balance</b>	
<b>R/H Front Tyre</b>	225/45Z R18	RADIAL	6 mm	
<b>L/H Front Tyre</b>	225/45Z R18	RADIAL	6 mm	
<b>R/H Rear Tyre</b>	225/45Z R18	RADIAL	6 mm	
<b>L/H Rear Tyre</b>	225/45Z R18	RADIAL	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
<b>Accident Date</b>	08/12/2021	<b>Inspection Date</b>	13/12/2021	
<b>Survey held at</b>	ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>			<b>6 Working Days</b>	